


SITE INFORMATION

*SURVEY DATE: _June 12, 2012	*ADDRESS: 45339 300th Street					
*SURVEYOR: Jim Stone	*COUNTY: Clay					
	*CITY: Wakonda					
LOCATION DESCRIPTION: From the intersection of South Dakota Highway 50 bi-pass and South						
Dakota Highway 19, 15 miles North to 302 nd Street, turn left (West, 9 miles to 453 rd Ave, turn right (North)						
2 miles to 300 th Street, turn right and about ½ mile, turn right (South) into farm.						
LEGAL DESCRIPTION: Lot A, E ½ NW ¼, 20 – 95 – 53 Star Twp.						
*QUARTER 1: NW 1/4	OWNED NAME: Downin Conceptour					
	OWNER NAME: <u>Dennis Ganschow</u> OWNER ADDRESS: 45339 300 th Street					
*QUARTER 2: (*TOWNSHIP: Star						
*RANGE: 53	OWNER CITY: Wakonda OWNER STATE: South Dakota					
	OWNER ZIP: 57073 QUAD NAME:					
ACRES: 7.3 OWNER CODE 1: P	QUAD NAME:					
OWNER CODE 3: F S L P						
HISTORIC SIGNIFICANCE						
						
*DOE:	REGISTER NAME:					
*DOE DATE:	MULTIPLE PROPERTY NAME:					
REASON INELIGIBLE:						
	CATEGORY:					
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L					
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L					
REFERENCE NUMBER:	<u> </u>					
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D					
PERIOD:						
	CRITERIA 3: A B C D					
	CRITERIA 4: A B C D					
SIGNIFICANCE NOTES:						



STRUCTURE DETAILS					
SHPO ID:					
*PROPERTY NAME:					
OTHER NAME:					
O MER NAME.					
CURRENT FUNCTION:	Storage	FOUNDA	TION:	Poured concrete	
				Asphalt shingles	
CURRENT SUBFUNCTION:		ROOF MATE	DIAI -	over cedar shingles	
HISTORIC FUNCTION:	Livestock barn	ROOF SI			
HISTORIC SUBFUNCTION:	Hay and grain sto				
				Gothic roof barn	
OCCUPIED:	Yes		TYPE:	Livestock barn	
ACCESSIBLE:	Yes with permission	w	Δ11 Q -	2x6, sheathing, ½"x6" cedar siding	
ACCESSIBLE.	permission		ALLO.	72 AU Cedai Sidilig	
			Albe	ert Christian Nelson	
STORIES:	2	SIGNIFICANT PERSON:			
*DATE OF CONSTRUCTION:	1940's	CULTURAL AFFILIATION:		Danish	
ALTERED/MOVED NOTES: Original site. Roof has been covered with asphalt shingles					
-		•			
Horse stalls and any milk cow stanchions have been removed. Windows have been replaced with 9"x12" vinyl four light windows.					
Tilly roa. light willaone.					
INTERIOR NOTES: Four rows of posts and beams running East to West. West 18' beams are (3) 2X8'S					
with steel posts replacing 4x6's. East 42' has one row of 4x6 beam and 4x6 posts on the North. The					
posts and beams are missing on the South side. A 2x6 wall supports the next 16' from the South.					
OTHER NOTES: Laminated round gothic rafters, with sheathing cedar shingles and asphalt shingles.					
A 2x4 solid wall separates the West 18' from the East. A 42' 2x6 solid separates the South 16' from					
the North 24'. Two metal cup					
windows in the hayloft. 16'x8					
floor		, ,			
*PHYSICAL NOTES: Barn is	s in excellent condi	tion.			









PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 12, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 12, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 12, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 12, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, SE 16' x 42', 42' hay feed rack on

CAMERA DIRECTION: North wall



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, West side, looking North, granary

CAMERA DIRECTION: and stair case





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, NE 24'x42', looking East, 42' grain CAMERA DIRECTION: and silage feed bunk

PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: granary in hayloft

Hayloft, looking NW,






PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking East, laminated round gothic

CAMERA DIRECTION: rafters



PHOTOGRAPHER:

Jim Stone


DATE OF PHOTO: June 12, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: chute up to cupola

Hayloft, looking NE, air





CLAY CO.. SD



HISTORY

This farm located in the E ½ of the NW ¼, in Section 20, in Star Township, Clay County was homesteaded by James H. Dwyer.

The 1894 Clay County Atlas lists S. N. Carr as the owner.

The 1901 Clay County Atlas lists M. DeBois as the owner.

The 1912 Clay County Atlas lists R. J. Ward as the owner.

The 1924 Clay County Atlas lists Andrew Nielson as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists A. C. Nelson as the owner.

The Following Is Furnished by

Dennis Ganschow, the present owner.

Albert Christian Nelson bought this farm in the early 1930's. He built this barn in the 1940's.