


SITE INFORMATION				
*SURVEY DATE: September	3, 2013 *ADDRESS: 46629 311 th Street			
*SURVEYOR:Jim Stone	*COUNTY: Clay			
	*CITY: Vermillion			
LOCATION DESCRIPTION: From Verm	illion, intersection of South Dakota Highway 50 bi-pass and			
University Road, North about 7 miles to 311th Street, turn right (East) about 1-1/4 miles, on the right				
(South) side.				
LEGAL DESCRIPTION: E ½, NW ¼, 16 – 93 – 51 Prairie Center Twp.				
*QUARTER 1: <u>NW 1/4</u>	OWNER NAME: Paul T. Nelson Family Trust			
*QUARTER 2:	OWNER ADDRESS: 31079 467th Ave.			
*TOWNSHIP: Prairie Center	OWNER CITY: Vermillion			
*RANGE:	OWNER STATE: So. Dak.			
*SECTION:16	OWNER ZIP: <u>57069</u>			
ACRES: 81.38	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2:				
OWNER CODE 3:				
LUCTORIC CICNUTICANCE				
HISTORIC SIGNIFICANCE				
*DOE: REGISTER NAME:				
*DOE DATE: MULTIPLE PROPERTY NAME:				
REASON INELIGIBLE:				
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or N	C CRITERIA 1: A B C D			
PERIOD:	CRITERIA 2: A B C D			
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
SIGNIFICANCE NOTES:				


STRUCTURE DETAILS




SHPO ID:				
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION: Storage		FOUNDATION:		
			Steel roofing over	
CURRENT SUBFUNCTION:	Straw storage	ROOF MATERIAL:		
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof	
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYSTEM:	Balloon framing	
		STYLE:	Gable roof barn	
OCCUPIED:	Yes	TYPE:	Livestock barn	
	Yes with		2x6 studs, 1x8 #106	
ACCESSIBLE:	permission	WALLS:	drop siding, ½"x6" cedar lap siding	
7.00200.522.	pormicolon		oodar lap olanig	
STORIES:	2 5	SIGNIFICANT PERSON:	A. M. Lockwood	
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	?	
2/112 01 001101110011011.			•	
ALTERED/MOVED NOTES: Original site. Roof covered with steel roofing over cedar shingles. All				
evidence of horse stalls has been removed. 18' x 24' lean-to removed from the East side. A 24' x 32'				
pole barn addition added on the East side. ½"x6" cedar lap siding applied over the original 1x8 #106 drop				
siding. 16' x 10' granary and 6'x8' milk room may have been added on the South wall later.				
INTERIOR NOTES: Two and one half rows of 4x6 posts with 4x6's for beams support 2x8 joists for				
hayloft. Framing for milk cow stanchions is still in place along North wall. Actual metal collars for each milk cow have been removed. 2x6 rafters with three 2x6 bracing on each side from top of wall down to				
floor.	. 2x0 railers with timee 2	exo bracing on each side from	top of wall down to	
OTHER NOTES: 2x6 stud walls with 1x8 shiplap and ½"x6" cedar lap siding on three walls of original				
barn. Pole barn construction on 24' x 32' addition on East side. Addition has vertical steel siding and				
steel roof. Original galvanized metal cupola still in place. Windows are 8"x x 10" four light.				
*PHYSICAL				
NOTES: Barn is i	in good condition.	*RESTRICTED: Y	or N	
*UTM EASTING:				
*UTM NORTHING:				
		 _		













PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, original barn, looking NE, milk cow stanchions along North wall. 4x6 posts, 4x6 CAMERA DIRECTION: beam, 2x8 floor joists,



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: September 3, 2013

ROLL NUMBER: **PHOTO NUMBER:**

First floor, Original barn, looking SW, 16' x 10'

CAMERA DIRECTION: granary in SW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, 2x6 stud wall in Hayloft, 2x6 rafters and 2x6 wall

CAMERA DIRECTION: bracing.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SW, 2x6 rafters and 2x6 bracing CAMERA DIRECTION: for rafters at the peak.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking East into pole barn addition, CAMERA DIRECTION: manufactured trusses.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hog barn just South of original barn, looking NE, very old galvanized

CAMERA DIRECTION: metal cupola.





© Farm & Home Publishers, Ltd.

33

CLAY CO., SD



History

This farm located in the NW ¼ of Section 16, Prairie Center Township, Clay County was a School Section and could not be homesteaded. When the county was surveyed Section 16 and Section 36 were designated as School Sections if possible. Rents or sale of the land went into a fund to provide for county education.

The 1894 Clay County Atlas lists A. M. Lockwood as the owner. He would have purchased this land.

The 1901, 1912, and 1924 Clay County Atlas lists A. M. Lockwood as the owner.

The 1937 Clay County Atlas lists R. Peterson as the owner. A. Gale was the operator (renter).

The 1948 and 1956 Clay County Atlas lists M. W. O'Connor as the owner.