

""SITE INFORMA	ATION					
*SURVEY DA	TE: June 26,	2013 *ADDRESS:	45623 302nd Street			
*SURVEYO	OR: Jim Stor	re *COUNTY:	Clay			
		*CITY:	Wakonda			
		·	uth Dakota Highway 50 bi-pass and			
South Dakota Highway 19, North 15 miles to 302 <sup>nd</sup> Street, turn left (West) about 4-3/4 miles, left (South)						
side.						
LEGAL DESCRIPTION	N: <u>NW ¼, 35 – </u>	95 – 53 Star Twp.				
			Edward Lamont, Teresa K.,			
*QUARTER 1: _	NW 1/4	OWNER NAME:	Douglas J. & Ruth A. Hessman			
*QUARTER 2: _		OWNER ADDRESS:	P. O. Box 520			
*TOWNSHIP: _	Star	OWNER CITY:	Wakonda			
*RANGE: _	53	OWNER STATE:	South Dakota			
*SECTION: _	35	OWNER ZIP:	57073			
ACRES: _	155.69	QUAD NAME:				
OWNER CODE 1:	Р					
OWNER CODE 2:						
OWNER CODE 3:						
HISTORIC SIGNII	FICANCE					
*DO	DE:	REGISTER NA	REGISTER NAME:			
*DOE DAT			OPERTY NAME:			
REASON INELIGIBLE:						
			CATEGORY:			
NOMINATION STATUS:		SIGNI	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:		SIGNI	FICANCE LEVEL 2: N S L			
REFERENCE	NUMBER:					
HISTORIC DISTRICT RATING: C or NC		NC CRITI	ERIA1: A B C D			
PERIOD:		CRITI	ERIA 2: A B C D			
		CRITI	ERIA 3: A B C D			
		CRITI	ERIA 4: A B C D			
SIGNIFICANCE NOTES:						


#### STRUCTURE DETAILS



SHPO ID:		_				
*PROPERTY NAME:						
OTHER NAME:						
CURRENT FUNCTION:	Goat barn	FOUNDATIO	N: Poured concrete Asphalt shingles over			
CURRENT SUBFUNCTION:	Storage	ROOF MATERIA				
HISTORIC FUNCTION:	Livestock barn	ROOF SHAF	E: Gambrel roof			
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTE	M: Balloon framing			
			.E: Gambrel roof barn			
OCCUPIED:	Yes	TYF	PE: Livestock barn			
	Yes with		2x6 studs, 1x6 #106			
ACCESSIBLE:	permission	WALLS:	drop siding			
0700150		NONIFICANT DEDOOM	AP Harrie			
STORIES:		SIGNIFICANT PERSON:	Alice Hewitt			
*DATE OF CONSTRUCTION:	<u>1920's</u> CU	LTURAL AFFILIATION:	<u>'</u>			
ALTERED/MOVED NOTES. Original site. Some evidence of horse stelle and or milk some steric has						
ALTERED/MOVED NOTES: Original site. Some evidence of horse stalls and or milk cow stanchions has been removed. Asphalt shingles has been installed over cedar shingles on the roof.						
been removed. Aspiral simigles has been installed over cedal simigles on the root.						
INTERIOR NOTES: Two rows of 6x6 posts, and 6x6 beam support the 2x8 joists for the hayloft floor.						
Two double horse stalls and two double and one single milk cow stalls were on the South wall.						
8' x 10' granary are still in the NW corner. Three granaries still in place in the NW corner of the hayloft.						
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Rafters are 2x6's with a 2x6 brace at the hip						
4' O. C. and a 2x6 brace supporting hip 4' O. C., between braced hip rafters. Asphalt shingles over cedar						
shingles. Windows are 8" x 10" four light. Metal cupola is still in place. Cupola is small compared others.						
*PHYSICAL NOTES: Barn i	s in fair condition.					
*UTM ZONE:		*RESTRICTED: Y	or N			
*UTM EASTING:						
*UTM NORTHING:						



#### SKETCH MAP RAFTERS 8'x10' GRANAR ZX6 HIP BRACE T'ac. Z×6 BRACE 121246 BEAM ò DOUBLE 12) DOUBLE U) SINGLE HORSE STALLS MILK COW STAKES 3 32 FIRST FLOOR 2-6 STUDS 1-6 #106 BROP SIDING POURED CONCRETE FOUNDATION WEST ELEVATION







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, 6x6 post, 6x6 beam, 2x8 joists, note granary in

CAMERA DIRECTION: NW corner.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking SW, horse stalls along South

CAMERA DIRECTION: wall.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, <u>2013</u>

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking SW, 2x6 braces supporting hip, 4'

CAMERA DIRECTION: O. C.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NW, 2x6 braces at hip, 4' O. C., note offset from 2x6

**CAMERA DIRECTION:** braces supporting hip.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone June 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NW, three granaries in the

CAMERA DIRECTION: NW corner





CLAY CO., SD



### **HISTORY**

This farm located in the NW ¼ of Section 35, Star Township, Clay County was homesteaded by Richard I. Hewitt.

The 1894 Clay county atlas lists R. J. Hewitt as the owner.

The 1901 and 1912 Clay County Atlas lists Alice Hewitt as the owner.

The 1924 Clay County Atlas lists Alice Hewitt and E. N. Sorenson as the owners.

The 1937 Clay County Atlas lists E. N. and C. Sorenson as the owners.

The 1948 Clay County Atlas lists E. N. Sorenson as the owner.

The 1956 Clay County atlas lists F. E. Axlund as the owner.