

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
 *PROPERTY NAME: _____
 OTHER NAME: _____

CURRENT FUNCTION:	<u>Shop</u>	FOUNDATION:	<u>Poured concrete foundation</u>
CURRENT SUBFUNCTION:	<u>Storage</u>	ROOF MATERIAL:	<u>cedar shingles</u>
HISTORIC FUNCTION:	<u>Livestock barn</u>	ROOF SHAPE:	<u>Gambrel</u>
HISTORIC SUBFUNCTION:	<u>Hay storage</u>	STRUCTURAL SYSTEM:	<u>Balloon framing</u>
		STYLE:	<u>Gambrel roof barn</u>
OCCUPIED:	<u>Yes</u>	TYPE:	<u>Livestock barn</u>
	<u>Yes with</u>		<u>2x6 studs, 1x6 #106</u>
ACCESSIBLE:	<u>permission</u>	WALLS:	<u>drop siding</u>
STORIES:	<u>2</u>	SIGNIFICANT PERSON:	<u>Andrew Salberg</u>
	<u>Re-built</u>		
*DATE OF CONSTRUCTION:	<u>1930's</u>	CULTURAL AFFILIATION:	<u>Swedish</u>

ALTERED/MOVED NOTES: Original site. Barn burned down in 1930's. Was re-built on original foundation. Window have replaced with 9"x12" vinyl four light windows.

INTERIOR NOTES: Has two rows of 6x6 posts, with a 6x6 for a beam. Has a 2x6 solid wall in 17' in from the West wall. 2x8 floor joists for hayloft floor. Double 1x6 rough sawn bracing on each side of rafters. From the center of the lower rafter down to the floor and from the center of lower rafter up to the center of the top rafter. Short bracing from bottom of lower rafter out to 1x6 bracing and also from hip out.

OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Rafters are 2x6. Windows are 9"x12"four light vinyl windows. Metal cupola still in place. Horse stalls and granary are still in place in the West side. Milk cow stalls , milk room, granary, calf pen and multipurpose area are still in place in the East side.

*PHYSICAL NOTES: Barn is in very good condition. Needs re-roofing soon.

*UTM ZONE: _____ *RESTRICTED: Y or N
 *UTM EASTING: _____
 *UTM NORTHING: _____

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, West side,
looking NW, horse stalls
on West wall.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 6

CAMERA DIRECTION: First floor, West side,
looking North, granary in
NW corner, solid wall on
the right.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 7

First floor, East side,
looking SE, milk cow
stalls and milk room in

CAMERA DIRECTION: SE corner.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 8

First floor, East side,
looking NE, milk cow
stalls on North side of

CAMERA DIRECTION: alley.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 9

CAMERA DIRECTION: First floor, East side, looking NW, calf pen and double granary in the NW corner of East side.




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 10

CAMERA DIRECTION: First floor, East side, looking North, milk cow stall and double granary in the NW corner of East side.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 11

**Hayloft, looking NE,
double 1x6 braces from
center of lower rafter
down to floor.**

CAMERA DIRECTION: _____



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 12

**Hayloft, looking NE,
double 1x6 bracing up to
center of top rafter and
down to floor.**

CAMERA DIRECTION: _____

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 18, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 13

CAMERA DIRECTION: Hayloft, looking NE,
double 1x6 bracing from
center of top rafter down,
note bracing from hip
out to 1x6 bracing.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



HISTORY

This farm located in the NW $\frac{1}{4}$ of Section 22, Prairie Center Township, Clay County was homesteaded by Andres Salberg.

The 1894 and 1901 Clay County Atlas lists Andrew Salberg as the owner and lists this farm as the "Salberg Farm".

The 1912 Clay County Atlas lists S. A. Salberg as the owner.

The 1924 Clay County Atlas lists S. A. Salberg as the owner.

The 1937 Clay County Atlas lists S. B. Salberg as the owner and J.B. Salberg as the operator..

The 1948 and 1956 Clay County Atlas lists J. B. Salberg as the owner.