

#### SITE INFORMATION

\*SURVEY DATE: <u>July 20, 2012</u>

\*ADDRESS: <u>30641 466<sup>th</sup> Ave.</u>

\*SURVEYOR: Jim Stone

\*COUNTY: <u>Clay</u> \*CITY: Vermillion

LOCATION DESCRIPTION: <u>South Dakota Highway 50 East of Vermillion 2 miles to Greenfield Road,</u> turn left (North) 12-1/2 miles to 306<sup>th</sup> Street, turn left (West) about 2-1/3 miles, on the right (North).

LEGAL DESCRIPTION:  $S \frac{1}{2}$ , SE  $\frac{1}{4}$  17 – 94 – 51 Garfield Twp.

*QUARTER 1:	SE	1/4			C	OWNER I	NAME:	Raym	ond	J. Ko	eni	gs Tr	ust		
*QUARTER 2:					OWN	NER ADD	RESS:	1317 E	Boon	e					
<b>*TOWNSHIP:</b>	Ga	rfield				OWNER	CITY:	Pella							
*RANGE:		51			C	WNER S	STATE:	lowa							
*SECTION:		17				OWNE	R ZIP:	50219							
ACRES:	7	ô.17				QUAD I	NAME:								
OWNER CODE 1:	Ρ														
OWNER CODE 2:	F	3 L	Ρ												
OWNER CODE 3:	F S	3 L	Р												
		NOF													
HISTORIC SIGN		NCE	-												
*D(	OE: _					REGIS		AME:							
					MULTIPLE PROPERTY NAME:										
REASON INELIGIB															
								c	CATE	GOF	RY:				
NOMINATIO	N STA	TUS:					SIGNI	FICANC	E LE	EVEL	1:	Ν	S	L	
DA	<b>FE LIS</b>	TED:					SIGNI	FICANC	ELE	EVEL	2:	Ν	S	L	
REFERENCE															
HISTORIC DISTRIC	T RAT	ING:	С	or NC			CRITE	ERIA 1:	Α	в	С	D			
	PEF	lOD:					CRITE	ERIA 2:	Α	в	С	D			
							CRITE	ERIA 3:	Α	в	С	D			
							CRITE	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NO	TES:														
		-													

#### STRUCTURE DETAILS



SHPO ID:		_	
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:	Cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel and gable
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gambrel roof barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6, diagonal sheathing, ½"x6" cedar lap siding
	-		
	_		n, C. A. , Alfreda
STORIES:	5	SIGNIFICANT PERSON: <u>Anke</u>	
*DATE OF CONSTRUCTION:	<u>?</u> CU	LTURAL AFFILIATION:	?

ALTERED/MOVED NOTES:Original site.West barn is 28'x40' gable roof barn and is the first barn.the East 32' x 42' gambrel roof barn was added later.Any stanchions or stalls in the East barn havebeen removed.Some of the 6x6 posts are gone in the East barn.Three steel posts are supporting the6x8 South beam.

INTERIOR NOTES: West barn has two rows 6x6 posts and 6x6 beam to support hayloft floor. Floor joists are 2x8's. Has a stairs to the hayloft, horse stalls and granary still in place. East barn which is attached has two rows of 6x6 posts and 6x8 beams. Floor joists are 2x8's. Also has a stairs to hayloft. Has a door from East barn to West barn and an opening in the hayloft for the same purpose. OTHER NOTES: Windows were 9"x12" four light. Walls are 2x6x 15' on the West barn and 2x6x 13' on


the East barn with diagonal sheathing and ½"x6" cedar lap siding. 2x6 studs above on gable ends to

the roof line. Rafters are 2x6 with no bracing in the West barn. Rafters are 2x6 in the East barn with 2x8 hip to wall and top of wall to floor bracing 8' O.C. 2x4 bracing on each hip. 2x8 x bracing in center of hayloft with a  $\frac{1}{2}$ " bolt to tie 2x8's just above the wall (see drawing).

\*PHYSICAL NOTES: <u>Barn is in poor condition. The roof is leaking. Windows and doors need repaired.</u> Roof needs steel on it to preserve the barn.

<b>*UTM ZONE:</b>	*RESTRICTED:	Υ	or	Ν
*UTM EASTING:				
*UTM NORTHING:				






\* = REQUIRED FIELD

3



#### SKETCH MAP




#### **PHOTOGRAPHS**

PHOTOGRAPHER: DATE OF PHOTO:		ROLL NUMBER:	
		PHOTO NUMBER: CAMERA DIRECTION:	
		Orthing of Britis	

\* = REQUIRED FIELD

3





DATE OF PHOTO:

**PHOTO NUMBER:** 2 CAMERA DIRECTION: Looking NW, SE corner






**PHOTOGRAPHER:** DATE OF PHOTO:

Jim Stone July 20, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

3 CAMERA DIRECTION: Looking SW, NE corner



July 20, 2012 **PHOTO NUMBER:** 4 CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:Jim StoneROLL NUMDATE OF PHOTO:July 20, 2012PHOTO NUM

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, West barn, looking South, horse CAMERA DIRECTION: stalls

5



PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 20, 2012 ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 6 First floor, West barn, looking South, horse Stalls

7





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: July 20, 2012 ROLL NUMBER: PHOTO NUMBER:

Hayloft, East barn, looking West, lower CAMERA DIRECTION: rafter bracing

7



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	July 20, 2012	PHOTO NUMBER:	8
=			

CAMERA DIRECTION: rafter bracing

Hayloft, East barn, looking West, upper rafter bracing





 PHOTOGRAPHER:
 Jim Stone


 DATE OF PHOTO:
 July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

9 Hayloft, East barn, looking West, 2x8 cross bracing in center of havloft

CAMERA DIRECTION: hayloft





PRAIRIE CENTER TWP.

© Farm & Home Publishers. Ltd.

21

CLAY CO., SD



# HISTORY

This farm located in the S <sup>1</sup>/<sub>2</sub> of the SE <sup>1</sup>/<sub>4</sub> of Section 17, Garfield Township, Clay County was homesteaded by Fred Heimerkin.

The 1894, 1901 and 1912 Clay County Atlas lists Karen Anker as the owner.

The 1924 Clay County Atlas lists C. A. Anker as the owner.

The 1937,1948 and 1956 Clay County Atlas lists Alfreda Anker as the owner. The 1937 Atlas lists A. Soderman as the operator (renter).

