


""SITE INFORMATION	1									
*SURVEY DATE:	June 21, 2013	*ADDRESS:	45534 299	45534 299 th Street						
*SURVEYOR:	Jim Stone	*COUNTY:	Clay							
		*CITY:	Wakonda							
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and										
South Dakota Highway 19, North 20 miles to South Dakota Highway 46, turn left (West) about 5 miles to										
457th Ave., turn left (South) about 1/4 mile, left (East) side.										
LEGAL DESCRIPTION: W 1/2, NW 1/4, 1 – 95 – 53 Star Twp.										
LEGAL DESCRIPTION: W 1/2, NW 1/4, 1 - 95 - 53 Star Twp.										
*QUARTER 1: NW	1/4	OWNER NAME:	James K. I	James K. Holm						
*QUARTER 2:		OWNER ADDRESS:	29722 457 ^t	29722 457 th Ave.						
*TOWNSHIP: St	ar	OWNER CITY:	Wakonda	Wakonda						
*RANGE: 53	3	OWNER STATE:	South Dak	ota						
*SECTION:1	*SECTION:1									
ACRES:76.	.44	QUAD NAME:								
OWNER CODE 1: P										
OWNER CODE 2:										
OWNER CODE 3:										
HISTORIC SIGNIFICANCE										
*DOE:	REGISTER NA	REGISTER NAME:								
		MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:										
			CATEGORY:							
NOMINATION STAT	SIGNI	SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:			FICANCE LE	EVEL 2:	N	S	L			
REFERENCE NUMB	ER:									
HISTORIC DISTRICT RATI			ERIA 1: A							
PERIOD:			ERIA 2: A							
			ERIA 3: A							
		CRITE	ERIA 4: A	в с	D					
SIGNIFICANCE NOTES:										
SIGNIFICANCE NOTES:										


STRUCTURE DETAILS



SHPO ID:		<u></u>					
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Storage	FOUNDATIO	N: Poured concrete				
CURRENT SUBFUNCTION:	Storage	ROOF MATERIA	Steel roofing over L: cedar shingles				
HISTORIC FUNCTION:	Livestock barn		OF SHAPE: Gambrel roof				
HISTORIC SUBFUNCTION:	Hay and grain storage		-				
	<u>, , , , , , , , , , , , , , , , , , , </u>	 STYL					
OCCUPIED:	Yes	TYP					
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs, 1x6 #106 drop siding, steel				
STORIES:	2	SIGNIFICANT PERSON:	Anton Erickson				
*DATE OF CONSTRUCTION:	-	CULTURAL AFFILIATION:	?				
ALTERED/MOVED NOTES	Original site. Mast see	dance of house stelle and an					
-		vidence of horse stalls and or					
been removed. Steel roofing has been installed over cedar shingles on the roof. Two lean-to's have							
been added much later. Lean-to's are pole barn construction with steel sides and roof. 9' x 7' overhead							
Door added in the SW corner	of the original parn.						
INTERIOR NOTES: _Two row	rs of 6x6 posts, and 6x	6 beams to support the 2x8 joi	sts for the hayloft floor.				
Milk room and tack room with stairs to hayloft are still in the NW corner of original barn. North lean-to							
Appears to have been built first and has 8" posts 8' O. C. The south lean-to has 6x6 treated posts 8' O. C.							
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding on all four walls of the original barn. Rafters							
are 2x6's, with 4x6 posts 10' O. C. and a 4x6 beam to support the hip. A 2x6 brace from the center of the							
		ce from the top of the wall in he eel roofing to keep birds out.					
*PHYSICAL NOTES: Barn is	s in good condition.						
*IITM ZONF:		*RESTRICTED: Y	or N				
*UTM ZONE:			V: 11				
UTM EASTING: *UTM NORTHING:							










SKETCH MAP



PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 21, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner




PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 21, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 21, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 21, 2013

PHOTO NUMBER: 4

First floor, looking NE, 6x6 posts, 6x6 beam, 2x8

CAMERA DIRECTION: floor joists.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, milk room and tack room in the NW corner of

CAMERA DIRECTION: original barn.



PHOTOGRAPHER: _____

Jim Stone DATE OF PHOTO: June 21, 2013

ROLL NUMBER: PHOTO NUMBER:

6

Hayloft, looking SE, 4x6 posts 10' O. C. and 4x6 beam supporting hip, 2x6 brace from top rafter

CAMERA DIRECTION: down to floor, 10'O. C.





PHOTOGRAPHER: DATE OF PHOTO: June 21, 2013

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 4x6 posts supporting hip, 10' O. C., 2x6 brace from of rafter down to floor 8'

CAMERA DIRECTION: O. C.



PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: June 21, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, vertical truss on each side of hayloft door to reinforce gable end wall, note 1x6 bracing at two hips centered between

CAMERA DIRECTION: 10' O. C. posts.





Farm & Home Publishers, Ltd.

39

CLAY CO., SD



HISTORY

This farm located in the NW ¼ of Section 1, Star Township, Clay County was homesteaded by Lucius Judson.

The 1894 Clay County Atlas lists D. M. Inman as the owner.

The 1901 Clay County Atlas lists Patrick Kilbride as the owner.

The 1912, 1924 and 1937 Clay County Atlas lists Anton Erickson as the owner. The 1937 Clay County Atlas lists L. Judson as the operator.

The 1948 and 1956 Clay County Atlas lists Harl Holm as the owner.