

#### **```SITE INFORMATION**

\*SURVEY DATE: May 16, 2013

\*SURVEYOR: Jim Stone

\*ADDRESS: 46685 301<sup>st</sup> Street \*COUNTY: Clay

\*CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 bi-pass and University Road, North 17 miles to 301<sup>th</sup> Street, turn right, (East) about 1- 1/4 miles, on the right (South) side

LEGAL DESCRIPTION: NE ¼, 28–95 – 51 Glenwood Twp.

*QUARTER 1:	NE 1/4		OWNER NAME:	Daniel	& H	olly	Hed	een			
*QUARTER 2:		C	WNER ADDRESS:	29928	<b>470</b> <sup>t</sup>	<sup>h</sup> Ave	e.				
<b>*TOWNSHIP:</b>	Glenwood		OWNER CITY:	Berest	ford						
*RANGE:	51		OWNER STATE:	South	Dak	ota					
*SECTION:	28		OWNER ZIP:	57004							
ACRES:	160.04		QUAD NAME:								
OWNER CODE 1:	Р										
<b>OWNER CODE 2:</b>											
OWNER CODE 3:											
HISTORIC SIGNI	FICANCE										
*D0	DE:		REGISTER N	AME:							
			MULTIPLE PI	ROPERT	Y N/	AME:					
REASON INELIGIB	LE:										
				C	ATE	GOF	RY:				
NOMINATIO	N STATUS:		SIGN	IFICANC	ELE	EVEL	. 1:	Ν	S	L	
DAT	E LISTED:		SIGN	IFICANC	ELE	EVEL	. 2:	Ν	S	L	
	NUMBER:		_								
HISTORIC DISTRIC	T RATING: C	or NC	CRIT	ERIA 1:	Α	в	С	D			
	PERIOD:		CRIT	ERIA 2:	Α	в	С	D			
			CRIT	ERIA 3:	Α	в	С	D			
			CRIT	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NOT	res:										

#### STRUCTURE DETAILS

\* = REQUIRED FIELD



SHPO ID:		_		
*PROPERTY NAME:				
OTHER NAME:				
<b>CURRENT FUNCTION:</b>	Vacant	FOUNDA	TION:	Poured concrete
	_			Steel over cedar
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SH	APE:	Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYS	TEM:	Balloon framing
		ST	TYLE:	Gambrel roof barn
OCCUPIED:	Yes	T	YPE:	Livestock barn
			-	2x6 studs, 1x8
				diagonal sheathing,
	Yes with			½"x6" cedar lap
ACCESSIBLE:	permission	WALLS:	-	siding
STORIES:	2	SIGNIFICANT PERSON:		August Hoyer
*DATE OF CONSTRUCTION:	Farly 1920's CI	JLTURAL AFFILIATION:		?

ALTERED/MOVED NOTES: <u>Original site.</u> Steel roofing installed over the cedar shingles. 16' x 32' lean-to added on the South side.


INTERIOR NOTES: Two rows of double 2x6 posts with a spacer and 6x6's for beams. Floor joists for the hayloft floor are 2x8's. Milk cow stanchions at the South end and horse stalls in the North end are still in place. Lean-to on the South side appears to be a loafing shed. Counter balanced door into hayloft. OTHER NOTES: 2x6stud walls, 1x8 diagonal sheathing and ½"x 6" cedar lap siding. The rafters are 2x6's with (2) 2x6's for a beam at the hip and (2) 2x6's for posts to support hip, also 2x8's bracing from hip down to the floor behind each post, 10' – 8' – 8' – 10' O. C. Windows are 4"x24" and 9" x 12" four light.

Metal cupola still in place. 9' x 14' calf pen in the SW corner. Granary in the hayloft on the West side with a chute down to first floor to get grain for feeding livestock.

\*PHYSICAL NOTES: Barn is in good condition. A very well thought out floor plan for livestock.

*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				










 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 16, 2013
 PHOTO NUMBER:
 1

 CAMERA DIRECTION:
 Looking NE, SW corner



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	May 16, 2013	PHOTO NUMBER:	2
		CAMERA DIRECTION:	Looking NW, SE corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 16, 2013
 PHOTO NUMBER:
 3






PHOTO NUMBER: 4 CAMERA DIRECTION: Looking SE, NW corner

May 16, 2013





PHOTOGRAPHER: DATE OF PHOTO: ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: North side.

First floor, looking SE, double horse stall on North side.

5



CAMERA DIRECTION: end.

**Jim Stone** 

May 16, 2013





PHOTOGRAPHER:	
DATE OF PHOTO:	


ROLL NUMBER: PHOTO NUMBER:

7 First floor, looking SE, milk cow stanchions and calf pen on the South

CAMERA DIRECTION: end.








PHOTOGRAPHER:Jim StoneDATE OF PHOTO:May 16, 2013

ROLL NUMBER: PHOTO NUMBER:

**CAMERA DIRECTION:** 

9
Hayloft, looking NE,
double 2x8's bracing
from hip down to floor,
behind each post, 10' –
8' – 8' – 10' O. C.





GARFIELD TWP.

C Farm & Home Publishers, Ltd.

۰.

23

CLAY CO., SD



# HISTORY

This farm located in the NE ¼ of Section 28 in Glenwood Township, Clay County was homesteaded by John Johnson.

The 1894 and 1901 Clay County Atlas lists Carl Hoyer as the owner.

The 1912 Clay County atlas lists August Hoyer as the owner.

The 1924 Clay county Atlas lists Emma Hoyer as the owner.

The 1937 and 1948 Clay County Atlas lists C. W. Hoyer as the owner.

The 1956 Clay County Atlas lists Emma Hoyer as the owner.