

	<u>SITE</u>	<u>INF</u>	ORN	<u>IATI</u>	ON
--	-------------	------------	-----	-------------	----

*SURVEY D	ATE: A	pril 15, :	2013	*ADDRESS:	2995	1 469	9 <sup>th</sup> A	ve.			
*SURVE	OR: Ji	m Ston	е	*COUNTY:	Clay						
				*CITY:	Bere	sfor	b				
LOCATION DESCR	IPTION: F	rom Ve	million, Soutl	n Dakota Highway	y 50 Eas	st 2 r	niles	to C	3reer	nfield	Road
North 18-1/2 miles to 300 <sup>th</sup> Street, turn right (East) about 1 mile to 469 <sup>th</sup> Ave., turn left (North) about ½ mile											
on the left (West) s	side.										
LEGAL DESCRIPTION: N 486' of E 214' & W 338' of E 552' of N 166' of the N ½, SE ¼, 14 – 95 – 51											
Glenwood Twp.											
*QUARTER 1:	SE 1/4			OWNER NAME:	Allan						
*QUARTER 2:			OW	NER ADDRESS:	-			е.			
*TOWNSHIP:	Glenwood	<u> </u>		OWNER CITY:							
*RANGE:	51			OWNER STATE:			ota				
*SECTION:	14			OWNER ZIP:	57004	1					
ACRES:	3.87			QUAD NAME:							
OWNER CODE 1:	Р										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGN	IFICANCE										
*D	OF.			DECISTED NA	ME.						
*DOE: *DOE DATE:			REGISTER NAME: MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:			WIOLITEEPN	OPERI	1 111/	MIVI E.	· –				
REAGON INELIGIB	·LE.										
					c	:ATF	EGOF	RY:			
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L								
	TE LISTED:				IIFICANCE LEVEL 2: N S L			L			
REFERENCE											
HISTORIC DISTRIC	_	C or	NC	CRITE	ERIA 1:	Α	В	С	D		
	PERIOD:				ERIA 2:				D		
				CRITE	ERIA 3:	Α	В	С	D		
				CRITE	ERIA 4:	Α	В	С	D		
SIGNIFICANCE NOTES:											


#### STRUCTURE DETAILS




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
<b>CURRENT FUNCTION:</b>	Shop	FOUNDATION:	Poured concrete				
			Steel over cedar				
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	shingles				
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable				
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing				
			Gable roof barn				
OCCUPIED:	Yes	TYPE:	Livestock barn				
			2x6 studs, sheathing ½"x6"				
	Yes with		cedar lap siding				
ACCESSIBLE:	permission	WALLS:	and steel roofing				
STORIES:	2	SIGNIFICANT PERSON:	Charrlin				
*DATE OF CONSTRUCTION:	1914	CULTURAL AFFILIATION:	?				
ALTERED/MOVED NOTES:	Original site. Any e	evidence of horse stalls and milk cov	w stanchions has				
been removed. Roof has bee	n covered with stee	l roofing. Walls covered with vertica	al and horizontal				
steel roofing. Center area of barn has been remodeled into a shop. 2x8 floor joists have been removed							
and replaced with 2x6's during the remodel. The walls were lined at the same time. An 8' x 7' overhead							
was installed in the South wa	II. Metal cupola is g	one. Posts and beams removed.					
INTERIOR NOTES: The orig	inal barn had two ro	ows of 6x6 posts and 6x8 for a beam	. The floor joists				
INTERIOR NOTES: The original barn had two rows of 6x6 posts and 6x8 for a beam. The floor joists  Were 2x8's, which have been removed. Replaced with 2x6's and supported with cables from the peak							
down. Owner said that there was four double horse stalls on the East wall and four on the West wall.							
OTHER NOTES: 2x6 stud walls with ½"x6" cedar lap siding with horizontal and vertical steel.							
Rafters are 2x6's with steel over cedar shingles. East lean-to was built in 2005. It is 6x6 posts with 2x4							
girts, 2x8 rafters 3' O.C., 2x4 purlins and steel roofing on walls and roof. Windows have been removed							
and two tall aluminum combination windows installed on the North wall.							
*PHYSICAL NOTES: Barn is in good condition. Very well maintained.							
*! ITM 70NC-		*DECTRICTED: V -	NI				
*UTM ZONE:		*RESTRICTED: Y o	r IN				
*UTM EASTING:							
*UTM NORTHING:							



#### SKETCH MAP









PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: April 15, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: April 15, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 15, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: April 15, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 15, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, West lean-to, looking NW, wall is lined,

CAMERA DIRECTION: 2x6 rafters.




PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 15, 2013

**PHOTO NUMBER:** 

First floor, center area, looking NW, remodeled shop area, 1951 "H" CAMERA DIRECTION: Farmall being restored.





CLAY CO., SD



#### **HISTORY**

This farm located in the SE ¼ of Section 14, Glenwood Township, Clay County was homesteaded by Mary Johnson.

The 1894 and 1901 Clay County Atlas lists Mary Johnson as the owner.

The 1912 Clay County Atlas lists A. & E. Larson as the owners.

The 1924 and 1937 Clay County Atlas lists A. J. Larson as the owner.

The 1948 and 1956 Clay County Atlas lists E. J. Neary as the owner.