

"SITE INFORMATION							
*SURVEY DATE: December 18	8, 2013 *ADDRESS: _46918 317 th Street						
*SURVEYOR: Jim Stone	*COUNTY: Clay						
	*CITY: Burbank						
LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 East about 4 miles to 469 th Ave.,							
turn left (North) about 1/2 mile to 317 th Str	eet, turn right (East) about ¼ mile on the left (North) side.						
LEGAL DESCRIPTION: SW ¼, 12 – 92 -	- 51 Fairview Twp.						
*QUARTER 1:SW 1/4	OWNER NAME: Mary Agnes Mockler						
*QUARTER 2:	OWNER ADDRESS: 46918 317 th Street						
*TOWNSHIP: Fairview	OWNER CITY: Burbank						
*RANGE:51	OWNER STATE: South Dakota						
*SECTION:12	OWNER ZIP: 57010						
ACRES: 160.00	QUAD NAME:						
OWNER CODE 1: P							
OWNER CODE 2:							
OWNER CODE 3:							
HISTORIC SIGNIFICANCE							
*DOE:	REGISTER NAME:						
*DOE DATE: MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:							
	CATEGORY:						
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L						
DATE LISTED: SIGNIFICANCE LEVEL 2: N							
REFERENCE NUMBER:							
HISTORIC DISTRICT RATING: C or NO							
PERIOD:							
- Lines.	CRITERIA 3: A B C D						
	CRITERIA 4: A B C D						
	CHIENATA D C D						
SIGNIFICANCE NOTES:							


STRUCTURE DETAILS




SHPO ID:							
*PROPERTY NAME:							
OTHER NAME:							
CURRENT FUNCTION:	Vacant		FOUNDA	TION:	Poured concrete		
CURRENT CURRUNCTION.	Ot a war wa			DIAL -	Steel roofing over		
CURRENT SUBFUNCTION:	Storage		ROOF MATE	-	cedar shingles		
HISTORIC FUNCTION:	Dairy barn		ROOF SHAPE:		Gable roof		
HISTORIC SUBFUNCTION:	Hay and grain stora	ge S	TRUCTURAL SY	-	Balloon framing		
				-	Gable roof barn		
OCCUPIED:	yes			TYPE:	Dairy barn		
	Yes with				2x6 studs, and 1x10 shiplap and steel		
ACCESSIBLE:	permission	WA	ALLS:		roofing		
				•			
STORIES:	2	SIGNIFI	CANT PERSON:	Albert	& Margaret Mockler		
*DATE OF CONSTRUCTION:	1945	CULTURA	L AFFILIATION:		German		
ALTERED/MOVED NOTES: Original site. East 32' x 80' open front (South wall) addition added much							
later. Steel roofing applied over cedar shingles. Siding removed and steel roofing applied vertically on							
side walls. 10' x 14' milk room added on the West side. Metal cupola has been removed.							
INTERIOR NOTES 44 will		(1 0	L		blana atti an tha		
INTERIOR NOTES: 11 milk (
North wall at the East end. 8' x 10' granary, 6' x 10' calf pen and 16' x 10' calving pen also still on the							
North wall starting from the West end. Two rows of 6x6 posts and 6x6 beams supporting 2x8 floor joists for the hayloft floor. 6x6 posts are 14' O. C., with steel pipe posts between in the milk cow stanchion areas							
only. Precast concrete feed trough in front of all milk cow stanchions.							
OTHER NOTES: 2x6 stud walls with 1x10 shiplap. The siding has been removed and steel roofing has							
been applied vertically on all exterior walls. Rafters are 2x6's with two 1x6's braces from the center of the							
rafters down to the floor and exterior wall, 4' O. C. Windows are 9" x 12" four light. The cupola is gone,							
probably removed when stee	I roofing was applied	on the roo	f.				
*PHYSICAL							
	n very good conditio	n.	*RESTRICTED	: Y o	r N		
*UTM EASTING:							
*UTM NORTHING:							



SKETCH MAP









PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 18, 2013 ROLL NUMBER: PHOTO NUMBER:

1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone December 18, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: December 18, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: December 18, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 18, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, at 11 milk cow stanchions and concrete feed trough

CAMERA DIRECTION: on South wall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 18, 2013**

PHOTO NUMBER:

First floor, looking NE, 6x6 posts, 6x6 beam, one steel pipe post athe East end where 4 milk cow stanchions are. Cow and calf pens & granary

CAMERA DIRECTION: are on the North wall





PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 18, 2013 ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, calving pen, calf pen and granary on the North

CAMERA DIRECTION: wall.



PHOTOGRAPHER:

DATE OF PHOTO: December 18, 2013

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

8

Hayloft, looking NE, 2x6 rafters and (2) 1x6 braces from the center of the rafters down to the

CAMERA DIRECTION: floor & ext. wall, 4' O. C.





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: December 18, 2013


ROLL NUMBER: PHOTO NUMBER:

9 Hayloft, looking East,

CAMERA DIRECTION: large hayloft door.

East gable end wall and







HISTORY

This farm located in the SW ¼ of Section 12, Fairview Township, Clay County was homesteaded by Carlos Dimmick.

The 1894, 1901, 1912, 1924 and 1937 Clay County Atlas lists August Mockler as the owner.

The 1948 and 1956 Clay County Atlas lists Albert Mockler as the owner.