

#### SITE INFORMATION

\*SURVEY DATE: <u>March 23, 2012</u> \*SURVEYOR: Jim Stone

*ADDRESS:	31707 Meckling Road
*COUNTY:	Clay
*CITY:	Vermillion

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 (West) about 1 mile, turn left (South) on South Dakota Highway 19, and then turn right (West) on timber Road about 5 miles to Meckling Road, turn right (North) about ½ mile, on the left side.

**LEGAL DESCRIPTION:** <u>NE ¼ NE ¼, 14 – 92 – 53, Norway Twp.</u>

*QUARTER 1:	N	E 1/	4				OWNER	NAME:	Sana	M. Iv	erso	n Tr	ust			
*QUARTER 2:						OW	NER AD	DRESS:	126 S.	. Plu	m #2	07				
<b>*TOWNSHIP:</b>	Norway					OWNE	R CITY:	Vermillion								
*RANGE:	53					OWNER	STATE:	South Dakota								
*SECTION:	14					OWN	IER ZIP:	57069								
ACRES:	39.14					QUAD	NAME:									
OWNER CODE 1:																
OWNER CODE 2:	F	S	L	Ρ												
OWNER CODE 3:	F	S	L	Ρ												
HISTORIC SIGNI	FIC	<b>;</b> AN	CE													
*DOE:				REGISTER NAME:												
*DOE DATE:																
REASON INELIGIBLE:																
									C	CATE	GOF	RY:				
NOMINATIO	N ST	ΓΑΤΙ	JS:					SIGN	FICANO	ELE	EVEL	1:	Ν	S	L	
								SIGNI	FICANO	E LE	EVEL	2:	Ν	S	L	
REFERENCE																
HISTORIC DISTRIC								CRITI	ERIA 1:	Α	в	С	D			
	P	ERIC	DD:					CRITI	ERIA 2:	Α	В	С	D			
								CRITI	ERIA 3:	Α	В	С	D			
								CRITI	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NOT	<b>FES</b> :	:														



STRUCTURE DETAILS			
SHPO ID:			
*PROPERTY NAME:	lverson barn		
OTHER NAME:			
CURRENT FUNCTION:	Shop	FOUNDATION:	Poured concrete
	-		Steel roofing over
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	cedar shingles
HISTORIC FUNCTION:	Livestock	ROOF SHAPE:	Gambrel
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gambrel roof barn
OCCUPIED:	Yes	TYPE:	Livestock
			2x6, sheathing,
	Yes with		<sup>1</sup> ∕₂"x6" cedar lap
ACCESSIBLE:	permission	WALLS:	siding
STORIES:	2	SIGNIFICANT PERSON: A	ugust J. Kryger
*DATE OF CONSTRUCTION:	?	CULTURAL AFFILIATION:	Norwegian

 ALTERED/MOVED NOTES:
 Moved to this site from another farm in 1920's, from NW ¼ of NE ¼ Sec. 14

 to this NE ¼ of NE1/4 Sec. 14( about ¼ mile).
 Roof and sidewalls have been covered with

 steel roofing.
 Posts and beams have been removed. Center 14' of hayloft raised to 12'. 5x6 treated

 posts added on each side to support 8' of original hayloft floor for storage and support the raised center

 of hayloft floor.
 Horse stalls and stanchions have been removed. Some of the windows have been

 changed with 1 light residential windows and some of the original windows are covered with steel siding.

 INTERIOR NOTES:


OTHER NOTES: 2x6 rough sawn cottonwood stud walls 14' high, with rough sawn cottonwood

sheathing and 1x2"x6" cedar lap siding. Wall sheathing is diagonal on the gable end walls. Rafters are

2x6 rough sawn cottonwood with rough sawn cottonwood sheathing, cedar shingles and covered with steel roofing.

\*PHYSICAL NOTES: Large lean-to added to North side recently. Barn is in very good condition.



















**PHOTOGRAPHER:** DATE OF PHOTO:

**Jim Stone** March 7, 2012

**ROLL NUMBER:** PHOTO NUMBER: 5 Hayloft, looking West,

note slanted 6x6 post & CAMERA DIRECTION: <u>6x6 beam supporting hip</u>





© Farm & Home Publishers. Ltd.

7



# History

This farm located in the NE ¼ of NE ¼ of Norway Township, Clay County was homesteaded by Ole B. Larson.

The 1894, 1901 and 1912 Clay County Atlas lists Amund Hanson as the owner.

The 1924 and 1937 Clay County Atlas lists August J. Kryger as the owner.

The 1948 and 1956 Clay County Atlas lists Magnus P. Jepson as the owner.

This barn was moved from the 80-acre farm just to the west of this farm. A capstan winch using horse power skidded the barn about <sup>1</sup>/<sub>4</sub> mile across the field in the winter. August J. Kruger may have built or had the original barn built as he owned the 80-acre farm to the west.