

SITE INFORMATION


*SURVEY DA	*ADDRESS: _30280 Greenfield Road												
*SURVEYOR: Jim Stone				*COUN	ΓΥ: Clay	Clay							
				*CI	ΓY: Bere	Beresford							
LOCATION DESCRIPTION: Vermillion, from the intersection of South Dakota Highway 50 bi-pass a University Road, North 15 miles to 303 rd Street, turn right (East) about 3 miles to Greenfield road, turn													
(North) about ¼ mil	e, on the righ	t (East) side, long d	riveway back	into trees.	•							
LEGAL DESCRIPTION	ON: <u>SW 1</u>	⁄4, Exc	N 274' of W 4	00', 35 – 95 –	51 Glenw	ood	Twp.	ı					
*QUARTER 1:		OWNER NAME: Ronald L. & Sandra F. Carlson											
*QUARTER 2:			OW	OWNER ADDRESS:			30280 Greenfield Road						
*TOWNSHIP:	Glenwood			OWNER CIT	TY: Beresford								
*RANGE:	51			OWNER STATE:			South Dakota						
*SECTION:	35			OWNER ZIP: 57004									
ACRES:	155.60			QUAD NAM	E:								
OWNER CODE 1:	Р												
OWNER CODE 2:													
OWNER CODE 3:													
HISTORIC SIGN	FICANCE												
*DOE:				REGISTER NAME:									
*DOE DATE:				MULTIPLE PROPERTY MANE									
REASON INELIGIBLE:													
					CATEGORY:								
NOMINATIO													
	TE LISTED:			SIC	NIFICAN	CE L	EVEL	_ 2:	N	S	L		
REFERENCE	_												
HISTORIC DISTRIC	_		_		ITERIA 1:								
	PERIOD: _				ITERIA 2:								
					ITERIA 3:								
				CR	ITERIA 4:	Α	В	С	D				
SIGNIFICANCE NOTES:													

STRUCTURE DETAILS



SHPO ID:		_								
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Machinery storage	FOUNDATION:	Poured concrete foundation							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel roofing over cedar shingles							
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable							
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing							
		_	Western feeder							
		STYLE:	barn							
OCCUPIED:	OCCUPIED: Yes TYPE:									
			2x4 studs with 1x6							
	Yes with		#106 drop siding and ½"x6" cedar							
ACCESSIBLE:	permission	WALLS:	lap siding and steel							
	•									
STORIES:	2	SIGNIFICANT PERSON: A	xel Odeen							
*DATE OF CONSTRUCTION:		ILTURAL AFFILIATION:	?							
			·							
ALTERED/MOVED NOTES:	Original site Any evid	dence of milk cow stanchions o	r horse stalls has							
-										
been removed. Roof has been covered with asphalt shingles. South and West walls are covered with										
red painted steel roofing. 18'x12' sliding door added on South. Hayloft floor removed. Floor joists raised to top of 2x4 walls (12'-6"). 1x10 sheathing used to truss rafters to floor joists. All posts and										
beams removed. East lean-to appears to have been added at a later date.										
INTERIOR NOTES: Floor jo	ists are 2x6's.									
OTHER NOTES: All walls ar	e 2x4 studs and all rafte	rs are 2x4's, except West lean-t	o which is 2x6							
		siding. The exterior walls have								
	•	re 8"x10" four light, but have b	-							
steel roofing.	iai oiaiiigi iiiiiaoiio iio									
	s in good condition.									
THIOTOLENOTES. Built	s in good condition.									
*UTM ZONE:		*RESTRICTED: Y o	r N							
*UTM EASTING:										
*UTM NORTHING:										









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 5, 2012** **ROLL NUMBER:**

PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 5, 2012**

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 5, 2012 ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking North, 2x4 stud wall, 2x6 floor joists raised to 12'-6", rafter to wall bracing still in place.

CAMERA DIRECTION:



PHOTOGRAPHER: _ DATE OF PHOTO:

December 5, 2012

ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking North up into rafters, 1x10 shiplap used to truss the rafters to floor joists

CAMERA DIRECTION: <u>rafters to floor joists</u>






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December <u>5, 2012</u>

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 2x6 floor joists raised to top of 12'-6"wall, 2x6 bracing from rafters CAMERA DIRECTION: down to wall left in place





© Farm & Home Publishers, Ltd.

23

CLAY CO., SD



HISTORY

This farm located in the SW ¼ of Section 35, Glenwood Township, Clay County was homesteaded by Axel Odeen.

1901, 1912, 1924 and 1937 Clay County Atlas lists Axel Odeen as the owner. He would have built or had this barn built.

The 1948 and 1956 Clay County Atlas lists Anna Odeen as the owner.

