

#### **`SITE INFORMATION**

\*SURVEY DATE: April 5, 2012

\*ADDRESS: 30287 Frog Creek Road

\*SURVEYOR: Jim Stone

\*CITY: Vermillion

\*COUNTY: Clay

LOCATION DESCRIPTION: From the intersection of South Dakota Highway 50 by-pass and South Dakota Highway 19 North 9 miles, turn left (West) on 308<sup>th</sup> Street 3-1/2 miles, turn right (North) on Frog Creek Road 5-1/4 miles , on the left (West) side

LEGAL DESCRIPTION: Friedland Tract 1 in SE <sup>1</sup>/<sub>4</sub> SE <sup>1</sup>/<sub>4</sub>, 31 – 95 – 52 Riverside Twp.

*QUARTER 1:	SE	E 1/4			OV	NER NAME:	Richar	d &	Vikk	i Eilt	s			
*QUARTER 2:					OWNE	R ADDRESS:	30287	Frog	q Cre	ek F	Road			
<b>*TOWNSHIP:</b>						WNER CITY:								
*RANGE:	Ę	52				NER STATE:								
*SECTION:						OWNER ZIP:								
ACRES:						QUAD NAME:								
OWNER CODE 1:	P	)												
<b>OWNER CODE 2:</b>	F	S	L	Ρ										
OWNER CODE 3:	F	S	L	Ρ										
HISTORIC SIGN	IFIC	<b>J</b> AN	CE											
*D	OE:					REGISTER NA	ME:							
				MULTIPLE PROPERTY NAME:										
							С	ATE	GOF	RY:				
NOMINATIO	N ST	ΓΑΤΙ	JS:			SIGNI	FICANC	ELE	VEL	1:	Ν	S	L	
						SIGNI	FICANC	ELE	VEL	2:	Ν	S	L	
REFERENCE	E NU	MBE	ER:											
HISTORIC DISTRIC	T R		IG:	C or	NC	CRITE	ERIA 1:	Α	В	С	D			
	Ρ	ERIC	DD:			CRITE	ERIA 2:	Α	В	С	D			
						CRITE	ERIA 3:	Α	В	С	D			
						CRITE	ERIA 4:	Α	В	С	D			
							<u> </u>	• •						

SIGNIFICANCE NOTES: <u>Metal cupola has large metal numbers 1913, which is the date of construction.</u> The numbers are easily seen from the barnyard.




STRUCTURE DETAILS				
SHPO ID:		_		
*PROPERTY NAME:	Ben Folvik barn			
OTHER NAME:				
CURRENT FUNCTION:	Livestock	FOUNDA	FION:	Poured Concrete
				Asphalt shingles over cedar
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	shingles
HISTORIC FUNCTION:	Livestock	ROOF SHAPE:		Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYS	TEM:	Balloon framing
		ST	YLE:	Gambrel roof barn
OCCUPIED:	Yes	T	YPE:	Livestock barn
	Yes with			2x6, sheathing & <sup>1</sup> ⁄ <sub>2</sub> "x6" cedar lap
ACCESSIBLE:	permission	WA	ALLS:	siding
STORIES:	2	SIGNIFICANT PERSON:	Ben	& Alma Folvik
*DATE OF CONSTRUCTION:	<u>1913</u> CU	LTURAL AFFILIATION:		?

ALTERED/MOVED NOTES: <u>Original site.</u> Horse stalls and milk cow stanchions have been removed. Roof reshingled with asphalt shingles over cedar shingles.

INTERIOR NOTES: Two rows 6x8 clear span beams on the West 12'. Two rows 6x6 posts and 6x6 beams in the East 28'. Posts are 5' O.C. 2x8 floor joists for the hayloft floor. Granary in the hayloft the North-East corner, with a feed room below on the first floor. Manure track and bucket still in place. OTHER NOTES: 2x6 stud walls 12' 8" high with horizontal sheathing on the North and South walls. 2x6 stud walls with horizontal sheathing on gable ends. ½"x6" cedar lap siding on all walls. 2x6 rafters, sheathing. One half of a Shawver truss spaced in 10' – 8' – 4' - 8' – 14' from the East side. Four trusses on the South and four on the North sides of roof. Two 1x6's at each hip for additional bracing. \*PHYSICAL NOTES: Barn is in very good shape. Has a metal cupola, which has the date 1913 as date of construction. The letters are large enough to be read from some distance. Barn has been very well maintained. 9"x 12" four light windows.









4






 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 April 5, 2012
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking NW, SE corner



CAMERA DIRECTION: Looking NE, SW corner





Jim Stone **PHOTOGRAPHER:** April 5, 2012 DATE OF PHOTO:

April 5, 2012

**ROLL NUMBER:** PHOTO NUMBER:

5 First floor, looking East CAMERA DIRECTION: \_posts and beams



PHOTOGRAPHER: DATE OF PHOTO:

**ROLL NUMBER: PHOTO NUMBER:** 

6 First floor, looking North, original manure bucket CAMERA DIRECTION: and manure track





**PHOTOGRAPHER:** DATE OF PHOTO:

Jim	Stone
April	5, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, granary in NE corner, floor on top to CAMERA DIRECTION: keep hay out of granary



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	April 5, 2012	PHOTO NUMBER:	8

Hayloft, ½ of a ShawverCAMERA DIRECTION:truss, looking East





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	April 5, 2012	PHOTO NUMBER:	9

CAMERA DIRECTION: truss, looking East


9
Hayloft, ½ of a Shawver
truss, looking East



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	April 5, 2012	PHOTO NUMBER:	10
-			Haulaft hattam of 1/

Hayloft, bottom of 1/2 CAMERA DIRECTION: Shawver truss and brace





PLEASANT VALLEY TWP.



# HISTORY

This farm located in the SE <sup>1</sup>/<sub>4</sub> of the SE 1/4, in Section 31, Riverside Township, Clay County and homesteaded by Cornelius Nelson.

The 1894 and 1901 Clay county Atlas lists A. Hallam as the owner.

The 1912 and 1924 Clay County Atlas lists Ben Folvik as the owner. The farm was called "Southwest Riverside Farm".

The 1937 and 1948 Clay County Atlas lists Alma Folvik as the owner. In 1937 A. S. Folvik was listed as the operator (renter).

The 1956 Clay County Atlas lists C. E. Friedland as the owner.

#### The following is from

Richard and Vikke Eilts The present owners.

This farm was owned by a Friedland and is known as the Friedland place. Mr. Friedland was a school teacher. Palmer Knutson had him as a teacher when he attended grade school.