

SITE INFORMATION


*SURVEY DATE: June 6, 2012	*ADDRESS: Vacant 453 301th Street			
*SURVEYOR: Jim Stone	*COUNTY: Clay			
	*CITY: <u>Wakonda</u>			
	ction of South Dakota Highway 50 bi-pass and South			
Dakota Highway 19, 15 miles North to 302 nd Street, turn left (West, 9 miles to 453 rd Ave, turn right (North)				
1 mile to 301th Street, turn right and about ¼ m	nile, turn left (North), stop in drive as the entrance is gated.			
LEGAL DESCRIPTION: W ½ W ½ SW ¼ & 33	60' of S 593', 29 – 95 – 53 Star Twp.			
*QUARTER 1: SW 1/4	OWNER NAME: James Nelson			
*QUARTER 2:	OWNER ADDRESS: 45307 300 th Street			
*TOWNSHIP: Star	OWNER CITY: Wakonda			
*RANGE: 53	OWNER STATE: South Dakota			
*SECTION: 29	OWNER ZIP: 57073			
ACRES: 43.18	QUAD NAME:			
OWNER CODE 1: P				
OWNER CODE 2: F S L P				
OWNER CODE 3: F S L P				
HISTORIC SIGNIFICANCE				
*DOE:	REGISTER NAME:			
*DOE DATE:	MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:				
	CATEGORY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L			
REFERENCE NUMBER:				
HISTORIC DISTRICT RATING: C or NC	CRITERIA 1: A B C D			
PERIOD:	CRITERIA 2: A B C D			
	CRITERIA 3: A B C D			
	CRITERIA 4: A B C D			
SIGNIFICANCE NOTES: Billy Carr barn				



STRUCTURE DETAILS				
SHPO ID:				
*PROPERTY NAME:		_		
OTHER NAME:				
OTTER NAME.				
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete	
CURRENT SUBFUNCTION:		BOOE MATERIAL.	Steel over cedar	
	Livestock barn	ROOF MATERIAL:		
		ROOF SHAPE:	Gable	
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Western feeder	
		STYLE:	barn	
OCCUPIED:	No		Livestock barn	
33331 ILD.	110		2x4, with diagonal	
	Yes with		sheathing and steel	
ACCESSIBLE:	permission	WALLS:	siding	
STORIES:	2	SIGNIFICANT PERSON:	Billy Carr	
	Moved in			
*DATE OF CONSTRUCTION:	1940's from	ILTURAL AFFILIATION:	leiob	
DATE OF CONSTRUCTION:	?	ILIURAL AFFILIATION:	Irish	
ALTERED/MOVED NOTES: Moved from another farm in the 1940's. Roof and walls have been covered				
with galvanized steel roofing. Horse stalls have been removed. 16'x32 Lean-to added to the East side.				
12'x16' lean-to added to the West side with a concrete floor and two concrete gutters. It appears to have				
been used for farrowing swine. Several pens appear to have been built in the original barn for swine.				
INTERIOR NOTES. Gy6 neets with 6y6 for a hoom. Became with North to South 10 from the West				
INTERIOR NOTES: 6x6 posts, with 6x6 for a beam. Beams run North to South. 8' from the West				
wall and 8' from the East wall leaving an 8' center alley. 2x8 floor joists for the hayloft floor. The center 30'x32' has 2x12 plank floor. I don't know what is under the plank flooring for floor joists. Wooden				
cupola.				
OTHER NOTES: 2x4 walls 14' high with sheathing on the center 24'x32' (original barn). 2x4 rafters with				
no bracing. 10'x8' granary in the NW corner of hayloft. 2x4 stud walls with sheathing on both additions.				
2x4 rafters on both additions. East addition has a center support for the rafters. Steel brick embossed				
siding on the exterior walls. Most of the windows are gone, but appear to have been 9"x12" four light.				
*PHYSICAL NOTES: Barn is in fair condition. Needs some exterior maintenance.				
I suspect two lowered concrete foundations under the posts and beams. These would support the floor				
joists under the 2x12 plank floor. The floor is level with the top of the exterior foundation.				



SKETCH MAP







PHOTOGRAPHER: __ DATE OF PHOTO: Jim Stone June 6, 2012 ROLL NUMBER: PHOTO NUMBER:

____1

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone June 6, 2012 ROLL NUMBER: PHOTO NUMBER:

/IBEK: Looking SE

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: June 6, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 6, 2012 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: 2x12 plank floor

First floor, looking East,



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, **CAMERA DIRECTION:** remnants of horse stalls





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW into a pen for calves or

CAMERA DIRECTION: sheep



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, 10'x8' granary in

CAMERA DIRECTION: NW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: rafters, no bracing

Hayloft, looking SE, 2x4




PHOTOGRAPHER: Jim Stone DATE OF PHOTO: June 6, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 5'

CAMERA DIRECTION: wall and 2x4 rafters





CLAY CO., SD



HISTORY

This farm, located in the W ½ of W ½ of The SW ¼, of Section 20, Star Township, Clay County was homesteaded by Henry Campbell.

The 1894 and 1901 Clay County Atlas lists Lee & Prentis as the owners.

The 1912 and 1924 Clay County Atlas lists Dominick Carr as the owner.

The 1937 Clay County Atlas lists A. Hansen as the owner.

The 1948 and 1956 Clay County Atlas lists W. F. Carr as the owner.

The Following Is Furnished By

James Nelson

William (Billy) Carr immigrated from Ireland. Date unknown. Married a local lady. They had no children. He had a brother who immigrated also.

They lived on a farm by Highway 46 earlier. They also lived on a farm South of Wakonda. They bought the farm ¾ mile East of this barn and lived there in about the 1920's. He bought the farm where this barn is located later and moved this barn in from another farm in the 1940's. He lost the place east of this barn in the 1930's, but held onto this farm. They moved to this farm then.