

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SITE INFORMATION

*SURVEY DATE: October 19, 2012 *ADDRESS: 46958 307th Street
*SURVEYOR: Jim Stone *COUNTY: Clay
*CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, East 2 miles to Greenfield Road, turn left (North) 10-1/2 miles to 307th Street, turn right (East) 1-2/3rd miles, on the Left (North) side of 307th Street.

LEGAL DESCRIPTION: SE 1/4, 24 - 94 - 51 Garfield Twp

*QUARTER 1: SE 1/4
*QUARTER 2: _____
*TOWNSHIP: Garfield
*RANGE: 51
*SECTION: 24
ACRES: 160

OWNER NAME: Roger L. & Sharon L. Jensen
OWNER ADDRESS: 46958 307th Street
OWNER CITY: Beresford
OWNER STATE: South Dakota
OWNER ZIP: 57004
QUAD NAME: _____

OWNER CODE 1: P
OWNER CODE 2: _____
OWNER CODE 3: _____

HISTORIC SIGNIFICANCE

*DOE: _____
*DOE DATE: _____
REASON INELIGIBLE: _____

REGISTER NAME: _____
MULTIPLE PROPERTY NAME: _____

NOMINATION STATUS: _____
DATE LISTED: _____
REFERENCE NUMBER: _____
HISTORIC DISTRICT RATING: C or NC
PERIOD: _____

CATEGORY: _____
SIGNIFICANCE LEVEL 1: N S L
SIGNIFICANCE LEVEL 2: N S L
CRITERIA 1: A B C D
CRITERIA 2: A B C D
CRITERIA 3: A B C D
CRITERIA 4: A B C D

SIGNIFICANCE NOTES: _____

STRUCTURE DETAILS

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
*PROPERTY NAME: _____
OTHER NAME: _____

CURRENT FUNCTION:	<u>Horse barn</u>	FOUNDATION:	<u>Poured concrete foundation</u>
CURRENT SUBFUNCTION:	<u>Storage</u>	ROOF MATERIAL:	<u>Steel roofing over cedar shingles</u>
HISTORIC FUNCTION:	<u>Livestock barn</u>	ROOF SHAPE:	<u>Gable</u>
HISTORIC SUBFUNCTION:	<u>Hay and grain storage</u>	STRUCTURAL SYSTEM:	<u>Balloon framing</u>
		STYLE:	<u>Gable roof barn</u>
OCCUPIED:	<u>Yes</u>	TYPE:	<u>Livestock barn</u>
	<u>Yes with</u>		<u>2x6 stud with 1x6</u>
ACCESSIBLE:	<u>permission</u>	WALLS:	<u>#106 drop siding.</u>

STORIES: 2 SIGNIFICANT PERSON: Carl Henrickson
*DATE OF CONSTRUCTION: ? CULTURAL AFFILIATION: ?

ALTERED/MOVED NOTES: Moved here in 1950's from farm about 1 mile West. Milk cow stanchions and horse stalls have been removed. Remodeled for raising hogs. Roof covered with galv. steel roofing. Walls have been covered with steel roofing except North wall.

INTERIOR NOTES: Has two rows of 6x6 posts with (3) 2x10's for beams. 2x8 floor joists. Granary is still in place in the NE corner. Walls lined with boards on inside.

OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Rafters are 2x6 with no bracing in hayloft. Windows are 9"x12" four light windows.



*PHYSICAL NOTES: Barn is in good condition. Some of the doors and windows need repair.

*UTM ZONE: _____ *RESTRICTED: Y or N
*UTM EASTING: _____
*UTM NORTHING: _____


* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**


SKETCH MAP



PHOTOGR



* = REQUIRED FIELD



* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, looking North, posts, re-built beam and floor joists



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 6

CAMERA DIRECTION: Hayloft, looking South, 2x6 rafters and hay track

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 19, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 7


CAMERA DIRECTION: Hayloft, looking NE,
granary in NE corner
from the first floor up
into hayloft.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



T-94-N GARFIELD DIRECTORY R-51-W

(Residents - Owners or Renters)
GLENWOOD TWP.



* = REQUIRED FIELD

HISTORY

This farm located in the SE ¼ of Section 24, Garfield Township, Clay County was homesteaded by Claus Madsen.

The 1894, 1901, 1912, 1924, 1937 and 1948 Clay County Atlas lists Carl H. Henrickson as the owner.

The 1956 Clay County Atlas lists T. F. Emigh as the owner.

This farm was known as the “Rock Pine Stock Farm”. Carl Henrickson was known as a breeder of Shorthorn cattle and Chester White hogs.

This barn was built about 1900.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

