

SITE INFORMATION

*SURVEY DATE: Octob	*ADDRESS: 46958 307th Street								
*SURVEYOR: _Jim S	*COUNTY: Clay								
		*CITY:	Beresford						
LOCATION DESCRIPTION: FI	rom Vermillion, Sout	h Dakota Highway	, 50, East	2 mile	s to	Gree	nfield	d Road,	
turn left (North) 10-1/2 miles to 307th Street, turn right (East) 1-2/3rd miles, on the Left (North) side of 307th									
Street.									
LEGAL DESCRIPTION: SE 1/4	, 24 – 94 - 51								
***************************************			_						
*QUARTER 1: SE 1/4		•	Roger L. & Sharon L. Jensen						
*QUARTER 2:	OW	WNER ADDRESS: 46958 307 th Street							
*TOWNSHIP: Garfield		•	R CITY: Beresford						
*RANGE: <u>51</u>		•	South Dakota						
*SECTION: 24		OWNER ZIP:	57004						
ACRES: 160		QUAD NAME:							
OWNER CODE 1: P OWNER CODE 2:									
OWNER CODE 3:									
OWNER CODE 3.									
HISTORIC SIGNIFICANCE									
*DOE:	REGISTER NAME:								
*DOE DATE:	MULTIPLE PROPERTY MANE								
REASON INELIGIBLE:									
			CA	TEGO	RY:				
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:									
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	A B	С	D			
PERIOD:		CRITE	RIA 2:	A B	С	D			
			RIA 3:	A B	С	D			
		CRITE	RIA 4:	A B	С	D			
SIGNIFICANCE NOTES:									


STRUCTURE DETAILS




SHPO ID:		_							
*PROPERTY NAME: OTHER NAME:									
OTTER NAME.									
CURRENT FUNCTION:	Horse barn	_ FOUNDATION							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Steel roofing over .: cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE							
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM	I: Balloon framing						
			E: Gable roof barn						
OCCUPIED:	Yes	TYPE	: Livestock barn						
			2x6 stud with						
ACCECCIDI E	Yes with	NA A L L	sheathing & steel						
ACCESSIBLE:	permission	WALLS	6: roofing						
STORIES:	2	SIGNIFICANT PERSON:	arl H. Henrikson						
*DATE OF CONSTRUCTION:	Early 1900's Cl	JLTURAL AFFILIATION:	Danish						
ALTERED/MOVED NOTES: _with red ptd. steel roofing. A	any evidence of horse st	alls removed. Five box stalls	built on the North side						
of main barn. Any evidence of			he beams have been						
replaced with (4) 2x8's and 6x	৫'s. South lean-to has l	peen added later.							
INTERIOR NOTES: Has two	rows of 4x6 posts with	4x6 for beams. Some beams	have been replaced						
with (4) 2x8's or 6x6's. 2x8 fl	oor joists. Granary and	tack room still in place. All c	louble horse stalls						
and the milk cow stanchions	have been removed.								
OTHER NOTES: 2x6 stud w	alls with 1x12 diagonal s	sheathing on some walls and	horizontal on other						
walls. Walls are covered with steel roofing so I couldn't see any siding. Floor joists are 2x8's. Rafters									
are 2x6's. One row of 2x6's	4' O.C. with 2x6 plate su	pport the rafters on each side	in hayloft. 20' x 29'						
area on North is a hayloft froi	n ground level to the pe	ak. Appears to be the first pa	rt of the barn built.						
*PHYSICAL NOTES: Barn is	s in good condition.								
*UTM ZONE:		*RESTRICTED: Y	or N						
*IITM EASTING.									
*UTM NORTHING:									




SKETCH MAP













PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 19, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 19, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 19, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 19, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking East, re-built posts and beam

CAMERA DIRECTION: in main barn




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October19, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking East, box stalls built in main

CAMERA DIRECTION: barn







HISTORY

This farm located in the SE ¼ of Section 24, Garfield Township, Clay County was homesteaded by Claus Madsen.

The 1894, 1901, 1912, 1924, 1937 and 1948 Clay County Atlas lists Carl H. Henrickson as the owner.

The 1956 Clay County Atlas lists T. F. Emigh as the owner.

This farm was known as the "Rock Pine Stock Farm". Carl Henrickson was known as a breeder of Shorthorn cattle and Chester White hogs.

This barn was built about 1900.

