

SITE INFORMATION

*SURVEY DATE:	December 29	, 2011	*ADDRESS:	46502	2 316	Sth St	reet			
*SURVEYOR:	Jim Stone *COI		*COUNTY:	Y: Clay						
			*CITY:	Verm	illioı	า				
LOCATION DESCRIPTION									٠,	
North 1-1/4 miles on 465 th	^ր Ave, turn rigl	ht (East) on 316th	Street, on lef	t (North	n) sid	de of	roa	d.		
_										
						_	_			
LEGAL DESCRIPTION:	S 232.35' of V	V 197', of SW ¼, o	of SW ¼, 5 - 92	2 - 51, F	airv	iew	Iwp			
*QUARTER 1: SW 1	/4	OW	NER NAME:	Bruce	& R	uby	Plate	9		
*QUARTER 2:		OWNER	46502 316 th Street							
*TOWNSHIP: Fairv	iew	0,	Vermillion							
*RANGE: <u>52</u>		OWI	South Dakota							
*SECTION: 5			57069							
ACRES: 7		Q	UAD NAME:							
OWNER CODE 1: P										
OWNER CODE 2: F	S L P									
OWNER CODE 3: F S	S L P									
HISTORIC SIGNIFICA	NCE									
*DOE:		F	REGISTER NA	ME:						
*DOE: *DOE DATE:			MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:										
_		_								
				С	ATE	GOI	RY:			
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L							
REFERENCE NUM	BER:									
HISTORIC DISTRICT RAT	ΓING: C or	NC	CRITE	RIA 1:	Α	В	С	D		
PEF	RIOD:		CRITE	RIA 2:	Α	В	С	D		
				RIA 3:	Α	В	С	D		
			CRITE	RIA 4:	Α	В	С	D		
SIGNIFICANCE NOTES:	Barn is in ex	cellent condition								

^{* =} REQUIRED FIELD




STRUCTURE DETAILS


SHPO ID:	16 CL 00000583	_											
*PROPERTY NAME:	Cecil Schultz barn												
OTHER NAME:													
CURRENT FUNCTION:	Saddle horses	FOUNDATION:	Poured concrete										
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Asphalt shingles										
HISTORIC FUNCTION:	Livestock	ROOF SHAPE:	Gothic round										
HISTORIC SUBFUNCTION:	Grain & hay storage	STRUCTURAL SYSTEM:	Balloon framing										
		STYLE:	Gothic round roof										
OCCUPIED:	YES	TYPE:	Livestock barn										
400E00IDI E-	VEC	WALL C.	2x4 w/ 1x6 drop										
ACCESSIBLE:	YES	WALLS:	siaing										
STORIES:	2	SIGNIFICANT PERSON: Ce	ecil Shultz										
*DATE OF CONSTRUCTION:	1965 CU	LTURAL AFFILIATION:	German										
ALTERED/MOVED NOTES:	Original site. Four box	stalls, one calf pen and a tack i	room have been										
installed. Walls have been c	overed with steel roofing	. 0riginal windows 4x24 four li	te have been										
replaced with 9x12 four lite windows. South sliding door and hayloft door have been replaced with													
2x4 frame covered with steel.													
NTERIOR NOTES: _Two rows 6x6 posts with 6x6 beam run North and South. 2x6 floor joists for the													
hayloft floor covered with 1x6 shiplap flooring. Granary in the hayloft in SW corner.													
OTHER NOTES: Gothic rou	nd laminated rafters mad	e with 1 x 2's five ply's thick.	!/2" plywood on the										
roof for roof sheathing with asphalt shingles. Barn appears to be a precut package, however I could not													
find any markings as to who the package may have come from. Date of construction confirmed by													
Connie Taggart (Cecil Schultz's daughter). Connie does not think that it was a kit barn.													
*PHYSICAL NOTES: <u>Barn I</u>	nas been straightened by	the Barn Doctors from Minnes	ota. Barn is in										
excellent condition.													
41 714 7 01-7		***************************************											
			or N										
*UTM EASTING:	_												
*UTM NORTHING:													

^{* =} REQUIRED FIELD










PHOTOGRAPHER: Jim Stone **ROLL NUMBER:** DATE OF PHOTO: December 29, 2011

PHOTO NUMBER: CAMERA DIRECTION: Hayloft, looking NW



PHOTOGRAPHER: **ROLL NUMBER:** Jim Stone DATE OF PHOTO: December 29, 2011 **PHOTO NUMBER:**

Hayloft peak, looking

CAMERA DIRECTION: North





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 29, 2011

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: looking SW

Hayloft & granary,



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: December 29, 2011

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: 1-1/2" x 5", five ply

Hayloft, laminated rafter





PHOTOGRAPHER: Jim Stone December 29, 2011 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North,

CAMERA DIRECTION: box stalls on East wall



PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone **December 29, 2011** **ROLL NUMBER:**

PHOTO NUMBER:

6

CAMERA DIRECTION: Looking NE, SW corner





PHOTOGRAPHER: ___ DATE OF PHOTO:

Jim Stone December 29, 2011 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner


PHOTOGRAPHER: _ DATE OF PHOTO:

Jim Stone December 29, 2011 ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner







HISTORY

This farm located in the SW ¼ of Section 5, Fairview Township, Clay County was homesteaded by Daniel B. Wadworth.

The 1894, 1901 and 1912 Clay County Atlas lists Daniel B. Wadworth as the owner. In 1912 the farm was called "Maple Grove Farm".

The 1924, 1937, 1948 and 1956 Clay County Atlas lists Guy H. Brooks as the owner. The farm was called "Walnut Park" in 1937.

The Following Is Furnished By

Connie (Schultz) Taggart

Cecil Schulz lived here for many years. He is 90 years old.

He could not remember the year that he built the barn.

He thinks that it was a precut package but is not sure.

He doesn't remember where he bought the package if it was a package.

I discovered that Connie Taggart was his daughter. I visited with Connie and found out that Cecil built the barn with the help of his sons in 1965. It was not a package kit.

