

SITE INFORMATION

*SURVEY DATE: November 6, 2012

*SURVEYOR: Jim Stone

*ADDRESS: 4704 East Main Street

*COUNTY: <u>Clay</u> *CITY: Vermillion

LOCATION DESCRIPTION: <u>Main Street in Vermillion, East to Crawford Road, about 3-1/2 miles East</u> to Fairview Ave. keep driving East, will be gravel for the last ½ mile, on the left (North) side

LEGAL DESCRIPTION: __Lots 5 & 6 Chaussee, SW ¼, SW ¼ & E 1/2 , SW ¼, 15 – 92 – 51 Fairview Twp.

*QUARTER 1:	SW 1/4		OW	NER NAME:	Curtis	J. &	Mel	cena	Ber	nard		
*QUARTER 2:			OWNER	ADDRESS:	POB	ox 6₄	41					
*TOWNSHIP:	Fairview		01	WNER CITY:	Yankto	on						
*RANGE:	51		OW	NER STATE:	South	Dak	ota					
*SECTION:	15		(OWNER ZIP:	57078	- 064	41					
ACRES:	13		Q	UAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNIFI	CANCE											
			F		ME							
*DOE DATE:			REGISTER NAME: MULTIPLE PROPERTY NAME:									
REASON INELIGIBLE						1 117						
	-											
					С	АТЕ	GOF	۲۲:				
NOMINATION S	TATUS:			SIGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
DATE LISTED:												
REFERENCE N												
HISTORIC DISTRICT F	RATING:	C or NC		CRITE	ERIA 1:	Α	В	С	D			
F	PERIOD:			CRITE	ERIA 2:	Α	в	С	D			
				CRITE	ERIA 3:	Α	в	С	D			
				CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOTES	2.											
	J											
STRUCTURE DET	AILS											

* = REQUIRED FIELD



SHPO ID:		_	
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete foundation
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Asphalt shingles over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		- STYLE:	Western feeder barn
OCCUPIED:	No	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6 stud with 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON: C	harles Chaussee
*DATE OF CONSTRUCTION:	1900 to 1915 CU	ILTURAL AFFILIATION:	French

ALTERED/MOVED NOTES: Original site. Milk cow stanchions have been removed. Any evidence of horse stalls removed. Roof covered with asphalt shingles. Two box stalls installed in the West side. Milk cow stanchions were added later or remodeled later.

INTERIOR NOTES: <u>Has two rows of 4x6 posts with 4x6 for sill and beam on each side of the center 14'.</u> These walls are 18' high. Hayloft has been removed in the center except for South 10'. Granary in the South end of center area. 2x6 joists for hayloft in the center. Double 2x6 joists 4' O. C. in the East and West sides. Hay feed racks on each side of center 14' area.


OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Most of the studs are double on the East

and West walls. Rafters are 2x6 with truss bracing in the center area. Windows are 9"x12" four light. Evidence points to a beef cattle feeder barn. May have been a separate horse barn. All of the 2x6's for studs, floor joists and rafters and 4x6's for posts, sills and beams are rough sawn cottonwood.

*PHYSICAL NOTES: <u>Barn is in good condition.</u> Needs some repairs on some doors and windows and some siding repair on lower North wall.

*UTM ZONE:	*RESTRICTED:	Y or I	N
*UTM EASTING:			
*UTM NORTHING:			









PHOTOGRAPHER:Jim StoneRODATE OF PHOTO:November 6, 2012PHO

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION:

1
Looking NE, SW corner



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 November 6, 2012
 PHOTO NUMBER:
 2

 CAMERA DIRECTION:
 Looking NW, SE corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 November 6, 2012
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking SW, NE corner



PHOTOGRAPHER:Jim StoneDATE OF PHOTO:November 6, 2012

PHOTO NUMBER: 4 CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 6, 2012

ROLL NUMBER: PHOTO NUMBER:

5 Looking North in West side, double 2x6 ceiling CAMERA DIRECTION: _joists 4' O.C.







PHOTOGRAPHER: DATE OF PHOTO: Jim Stone November 6, 2012 ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 7 Looking South in center of barn, 10' of hayloft still in place, granary on South wall and hay feed CAMERA DIRECTION: rack on side.




PHOTOGRAPHER: Jim Stone DATE OF PHOTO: November 6, 2012 ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 8 Looking South in East side, concrete feed CAMERA DIRECTION: trough for milk cows.

* = REQUIRED FIELD





* = REQUIRED FIELD

8



HISTORY

This farm located in the SW ¼ of the SE 1/4 and the E ½ of the SW ¼ in Section 15, Fairview Township, Clay County was homesteaded by Charles Chaussee.

The 1894, 1901, and 1912 Clay County Atlas lists Charles Chaussee as the owner.

The 1924 and 1937 Clay County Atlas lists F. Chaussee as the owner.

The 1948 and 1956 Clay County Atlas lists Clive Hancock as the owner.

In the 1912 Clay County Atlas it is listed as the River View Farm. I can't find when the name was changed to HillsideView. The date 1912 painted on the front of barn may be the date that the barn was built, but again I can't find any proof.

