


<b>"SITE INFORMATION</b>						
*SURVEY DATE:	July 11, 2013	*ADDRESS:	45685 301th Street			
*SURVEYOR:	Jim Stone	*COUNTY:	Clay			
		*CITY:	Wakonda			
LOCATION DESCRIPTION:	From Vermillion	, the intersection of Sou	th Dakota Highway 50 bi-pass and			
South Dakota Highway 19, North 15 miles to 302 <sup>nd</sup> Street, turn left (West) about 4miles to 458 <sup>th</sup> Ave., turn						
right (North) 1 mile to 301st Street, turn left (West) about 1/4 mile, on the left (South) side.						
LEGAL DESCRIPTION: NE ¼, 26 – 95 – 53 Star Twp.						
*QUARTER 1: NE 1/	4	OWNER NAME:	James & Ruth Williams Living Trust			
*QUARTER 2:		•	45694 301 <sup>nd</sup> Street			
*TOWNSHIP: Star	<u></u> r	OWNER CITY:				
*RANGE: 53		OWNER STATE:	South Dakota			
*SECTION: <u>26</u>		OWNER ZIP:	57073			
ACRES: <u>166.28</u>		QUAD NAME:				
OWNER CODE 1: P						
OWNER CODE 2:						
OWNER CODE 3:						
HISTORIC SIGNIFICAN	CE					
		DEGISTED NA	DECICTED NAME.			
			REGISTER NAME: MULTIPLE PROPERTY NAME:			
DEACON INCLICIBLE.			OI ERTITIAME.			
REAGON INCEIGIBLE.						
			CATEGORY:			
NOMINATION STATUS:		SIGNIF	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:		SIGNIF	FICANCE LEVEL 2: N S L			
REFERENCE NUMBE						
HISTORIC DISTRICT RATIN	G: C or NC	CRITE	RIA 1: A B C D			
PERIOD:		CRITE	RIA 2: A B C D			
			RIA 3: A B C D			
		CRITE	RIA 4: A B C D			
SIGNIFICANCE NOTES:						

#### STRUCTURE DETAILS



SHPO ID:						
*PROPERTY NAME:						
OTHER NAME:						
			Native stone, sand			
CURRENT FUNCTION:	Horse barn	FOUNDATION:	and lime mortar			
	•	2005 144752141	Steel roofing over			
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:				
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	-			
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:				
		STYLE	-			
OCCUPIED:	OCCUPIED: Yes TYPE:					
	Yes with		2x6 studs, 1x8 #106 drop siding and steel			
ACCESSIBLE:	permission	WALLS:	siding			
			<del></del>			
STORIES:	2	SIGNIFICANT PERSON:	Charles F. Mayer			
*DATE OF CONSTRUCTION:	Pre 1890	CULTURAL AFFILIATION:	?			
ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions has been removed.						
24' x 35' lean-to added to the West side. The exterior walls have been covered with 1-1/4"x26" corrugated,						
galvanized steel roofing applied vertically. Windows have been covered with the steel roofing. Roof						
covered with 1-1/4" x 26" corrugated Galvanized steel roofing.						
· · · · · · · · · · · · · · · · · · ·						
INTERIOR NOTES: Two rows of 4x6 posts, and 4x6 beam support the 2x6 joists for the hayloft floor.						
Two rows of 4x6 posts and a 4x6 beam support the center of the rafters in the hayloft. Three double horse						
stalls are still in place on the East wall.						
OTHER NOTES: 2x6 stud walls, with 1x8 #106 drop siding. Rafters are 2x6's. Windows were 8" x10"						
four light.						
*PHYSICAL NOTES: Barn is in fair condition. Lean-to roof is falling in.						
*UTM ZONE:		*RESTRICTED: Y	or N			
*UTM NORTHING:						









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 11, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

IED: Im Stone POLL NUMBER:

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 11, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 11, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July11, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: **DATE OF PHOTO:** 

Jim Stone July 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking East, 4x6 post, 4x6 beam, 2x6 joists, one of three double horse stalls on

CAMERA DIRECTION: East wall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking SW, can not tell what was on

CAMERA DIRECTION: the West wall.





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: July 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking NE, 4x6 posts and 4x6 beam supporting 2x6 rafters, note 2x4 horizontal brace

CAMERA DIRECTION: above 4x6 beam.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 11, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking SE, 4x6 posts, 4x6 beam

**CAMERA DIRECTION:** supporting rafters.





© Farm & Home Publishers, Ltd. 39 CLAY CO., SD



### **HISTORY**

This farm located in the NE ¼ of Section 26, Star Township, Clay County was homesteaded by Thomas Cotton.

The 1894, 1901, 1912, 1924 and 1937 Clay County Atlas lists Charles F. Mayer as the owner.

The 1948 Clay County Atlas lists Carrie Mayer as the owner.

The 1956 Clay County Atlas lists Charles F. Mayer as the owner.

