


"SITE INFORMATION	<u>ON</u>										
*SURVEY DATE:	Novembe	er 8, 2013	*ADDRESS:	: 31186 456 th Ave.							
*SURVEYOR: Jim Stone			*COUNTY:	Clay							
	*CITY:	Meckl	Meckling								
LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 west to Meckling and 457 th											
Ave., turn right (North) about 1-1/2 miles to 312 th Street, turn left (West) 1 mile to 456 th Ave., turn right ((North) about ¼ mile on the right (East side).											
((North) about ¼ mile o	n the right (Eas	t side).									
LEGAL DEGODIDATION	0144/ 44	00 50 14 - 11	· 								
LEGAL DESCRIPTION:	SW 14 -	93 – 53 Mecki	ng Iwp.								
		Linda C	. Chris	stianse	n						
*QUARTER 1:					LE - Lola M. & Charles H. Johnson Jr.						
*QUARTER 2:				31186 456 th Ave.							
*TOWNSHIP:N	Meckling		OWNER CITY:								
*RANGE:	53		WNER STATE:								
*SECTION:	14		OWNER ZIP:	57069							
ACRES:	163.01		QUAD NAME:								
OWNER CODE 1: P	1										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNIFIC	CANCE										
			DEGISTED N	\ \ \ \ \ \ \ \ \ \ \							
*DOE:			REGISTER NAME:								
*DOE DATE:			MULTIPLE PR	OPERTY	NAI	1E: _					
REASON INELIGIBLE:											
				•	A T F C	ODV.					
NOMINATION OTATUO			CATEGORY: SIGNIFICANCE LEVEL 1: N S L								
NOMINATION STATUS: DATE LISTED:			SIGNIFICANCE LEVEL 1: N S L								
REFERENCE NU	MRED:		SIGNI	FICANCE	LLV	CL Z.	IN	3	L		
HISTORIC DISTRICT RA			CDITE	ERIA 1:	٨	B C	П				
	ERIOD:			ERIA 1:							
• •				ERIA 3:							
				ERIA 4:							
			OMIL	VI) V TI		_					
SIGNIFICANCE NOTES:											



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:		-							
OTHER NAME:									
_									
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Asphalt shingles over cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof						
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gable roof barn						
OCCUPIED:	No	TYPE:	Livestock barn						
	Yes with		2x6 studs, 1x6" car						
ACCESSIBLE:	permission	WALLS:	siding						
STORIES	: 2 5	SIGNIFICANT PERSON:	Charles W. Rainey						
*DATE OF CONSTRUCTION		LTURAL AFFILIATION:	?						
	<u> </u>		•						
ALTERED/MOVED NOTES:	Original site. Asphalt sh	ningles applied over cedar shin	gles.						
INTERIOR NOTES: Two 14'	x 10' granaries on the Fa	ast side. Two spaced 2x6's for	nosts and a 6x6 heam						
that runs 18' from the West wall over to the two granaries. One double horse stall is still in place on the West side. Another double horse stall was on the North side in the west end, but has been removed.									
OTHER NOTES: 2x6 stud walls with 1x6" car siding on all four walls. The dividing wall between the									
main barn and the North lean-to has 1x8 shiplap up 8' high and has open studs above in hayloft. The rafters are 2x6's with 2x4 bracing from rafters down to the exterior wall at the floor level and 2x6 bracing									
		I' O. C. Windows are 9" x 12" f							
	ast granaries and the No	rth lean-to appear to have been							
*PHYSICAL									
NOTES: Barn is	in poor to fair condition.	*RESTRICTED: Y o	or N						
*UTM EASTING:									
*UTM NORTHING:									



SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 8, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 8, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: ___ DATE OF PHOTO: Jim Stone November 8 , 2013 ROLL NUMBER: __ PHOTO NUMBER: __ CAMERA DIRECTION:

Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 8, 2013 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION:

Looking SE, NW corner





PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone November 8, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: to granary on East side

First floor, looking SE in



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 8, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, spaced double 2x6 posts, 6x6 beam, 2x6 floor joists, double horse stall on south side of

CAMERA DIRECTION: West end.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 8, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SW, 2x6 rafters, 2x4 bracing from rafters down to floor, 2x4 bracing from bottom of rafters down to hayloft CAMERA DIRECTION: floor, both 4' O. C.



PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: November 8 , 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking West, 2x6 rafters and West

CAMERA DIRECTION: gable end.





CLAY CO., SD



History

This farm located in the SW ¼ of Section 14, Meckling Township, Clay County was homesteaded by Edward Rederich.

The 1894 Clay County Atlas lists Daniel S. Good as the owner.

The 1901 Clay County Atlas lists Susan Good as the owner.

The 1912 and 1924 Clay County Atlas lists Charles W. Rainey as the owner.

The 1937 Clay County Atlas lists Mrs. Charles W. Rainey as the owner. I. W. Whittaker is listed as the operator, (renter).

The 1948 Clay County Atlas lists Elis Rainey as the owner.

The 1956 Clay County Atlas lists Charles H. Johnson as the owner.

