

SITE INFORMATION


*SURVEY DATE: Novem	ber 17, 2012	*ADDRESS: 46138 311th Street							
*SURVEYOR: _Jim Sto	one	*COUNTY:	Clay						
		*CITY:	Y: Wakonda						
LOCATION DESCRIPTION: Fro	om the intersection of	South Dakota H	lighway	50 l	oi-pa	iss a	nd S	outh	1
Dakota Highway 19, North 6 miles	s to 311th Street, turn	left (West) 1-1/4	4 miles	on t	he ri	ght	(Nort	h) si	de.
LEGAL DESCRIPTION: Parcel	s A & B of SW ¼, 10	- 93 - 52 Spirit	Mound	Twp).				
*QUARTER 1: SW 1/4	0	OWNER NAME: Francis J. & Margaret J. Schiebe					ieher		
*QUARTER 2:		ER ADDRESS:	- -						
*TOWNSHIP: Spirit Mound		OWNER CITY: Wakonda							
*RANGE: 52		OWNER STATE: South Dakota							
*SECTION: 10		OWNER ZIP: 57073							
ACRES: 17.49		QUAD NAME:							
OWNER CODE 1: P		-							
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIFICANCE									
*DOE:		REGISTER NAME:							
*DOE DATE:		MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:									
			С	ATE	GOR	Y:			
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L				L			
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	Α	В	С	D		
PERIOD:		CRITE	RIA 2:	Α	В	С	D		
		CRITE	RIA 3:	Α	В	С	D		
		CRITE	RIA 4:	Α	В	С	D		
SIGNIFICANCE NOTES:									

STRUCTURE DETAILS



SHPO ID:		_								
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Raising ducks and dog training	_ FOUNDATION:	Poured concrete foundation Asphalt shingles							
OURRENT OUREUNATION	0.	2005 MATERIAL	over cedar							
CURRENT SUBFUNCTION:	Storage	_ ROOF MATERIAL:	shingles							
HISTORIC FUNCTION:	Livestock barn	_ ROOF SHAPE:								
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing Wisconsin dairy							
		STYLE:	barn							
OCCUPIED:	Yes	TYPE:	Livestock barn							
	Yes with		2x6 studs with Sheathing and ½"x6" cedar lap							
ACCESSIBLE:	permission	WALLS:	siding							
STORIES:	2	SIGNIFICANT PERSON:	Chris Nelson							
*DATE OF CONSTRUCTION:	1910 to 1920 CL	ILTURAL AFFILIATION:	Norwegian							
ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or horse stalls has been removed. Roof has been shingled with asphalt shingles. Large hayloft door has been framed in										
and sided to match rest of barn. Windows added at top of this door for light in hayloft. Metal cupola has been removed.										
nas been removed.										
		ı (3) 2x8's for a beam. Floor joi								
2x6 wall divides North 28' from the South 26'. Some walls still in place for horse stalls, but not enough										
evidence to know layout. Some of the walls appear to have been remodeled using existing material.										
OTHER NOTES: 2x6 stud walls with sheathing and ½"x6" cedar lap siding. Rafters are site built from										
3/4" x 1-3/4" four ply. These are 2' O.C. Another rafter is site built from 3/4" x 12" about 9'-6" long, four										
plies thick. These are 6' O.C. Windows are 8"x10" four light over 8"x10" four light, except for four on the										
South wall and two on the East wall, which are 8"x10" four light.										
*PHYSICAL NOTES: Barn is in very good condition. Owners plan on painting the barn in 2013.										
Roof will need re-roofing soon. Owners plan on putting steel roofing on roof.										
*UTM ZONE:		*RESTRICTED: Y o	r N							
*IITM EASTING.										
*UTM NORTHING:										









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

November 17, 2012

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: ____ DATE OF PHOTO: November 17, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

November 17, 2012

ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking East feed alley in center of

CAMERA DIRECTION: barn




PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: November 17, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, CAMERA DIRECTION: open North side of barn






PHOTOGRAPHER: _____
DATE OF PHOTO:

Jim Stone November 17, 2012 ROLL NUMBER: PHOTO NUMBER:

. . . .

Hayloft, looking North, four ply rafters 2' O.C. & four ply 1x12. 6' O. C.

CAMERA DIRECTION: four ply 1x12, 6' O. C.



PHOTOGRAPHER: ____ DATE OF PHOTO:

Jim Stone November 17, 2012 ROLL NUMBER: PHOTO NUMBER:

8

Hayloft, looking North, gothic round rafters, ote 2' O.C. and 6' O. C.

CAMERA DIRECTION: note 2' O.C. and 6' O. C.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone November 17, 2012 ROLL NUMBER: PHOTO NUMBER:

9

Hayloft, looking North, gothic round rafters and ECTION: North gable end.

CAMERA DIRECTION:







HISTORY

This farm located in the SW ¼ of Section 10, Spirit Mound Township, Clay County was homesteaded by John Anderson.

The 1894 Clay county Atlas lists D. C. Shull as the owner.

The 1901, 1912, 1924 and 1937 Clay County Atlas lists Christian Nelson as the owner.

The 1948 Clay County Atlas lists Anna Nelson as the owner.

The 1956 Clay County Atlas lists J. H. Hood as the owner.

Christian (Chris) Nelson would have built or had this barn built.

Christian Nelson is a (first generation Norwegian). His parents immigrated to the United States and he was born in the United States.

His daughter married John Hood and they lived here and farmed for several years.