

SITE INFORMATION


*SURVEY DATE: June	21, 2012	*ADDRESS:	31789 Armstrong Road									
*SURVEYOR: Jim S	*COUNTY:											
		*CITY:	Vermi	llion								
LOCATION DESCRIPTION: From Vermillion West on South Dakota Highway 50 about 1 mile, turn												
left (South) on South Dakota Highway 19, about 250' turn right (West) on Timber Road. Fallow Timber												
Road about 4-3/4 miles to Armstrong Road, turn left (South) about ¼ mile on the right (West) side.												
LEGAL DESCRIPTION: N ½ SE ¼ & SE ¼ SE ¼, 14 – 92 – 53 Norway Twp.												
			Trudio Moov ETAL LE Soroh									
*QUARTER 1: SE 1/4	OWNER NAME:	Trudie Macy ETAL, LE – Sarah E: Larson										
*QUARTER 2:	OW					841 Valley View Drive						
*TOWNSHIP: Norway		OWNER CITY:			·							
*RANGE: 53		OWNER STATE:			South Dakota							
*SECTION: 14		OWNER ZIP:			57069							
ACRES:119.37		QUAD NAME:										
OWNER CODE 1: P												
OWNER CODE 2: F S L	Р											
OWNER CODE 3: F S L	Р											
HISTORIC SIGNIFICANCE												
HISTORIC SIGNIFICANCE	ļ											
*DOE:	REGISTER NAME:											
*DOE DATE:	MULTIPLE PR	OPERTY	Y NAN	ΛΕ: _								
REASON INELIGIBLE:												
		CATEGORY:										
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L						L					
DATE LISTED:		SIGNII	FICANCI	E LEV	'EL 2:	N	S	L				
REFERENCE NUMBER:												
HISTORIC DISTRICT RATING:			RIA 1:									
PERIOD:			RIA 2:									
		CRITE	RIA 3:	Α	в с	D						
		CRITE	RIA 4:	Α	в с	D						
		_	_									
SIGNIFICANCE NOTES: Sarah and Anna Larson (sisters who never married) lived here, farmed the land												
and milked 12 to 14 cows.	_											



STRUCTURE DETAILS											
SHPO ID:											
*PROPERTY NAME:			•								
OTHER NAME:											
CURRENT FUNCTION:	Vacant		FOUNDA	TION:	Poured concrete						
CURRENT SUBFUNCTION:			ROOF MATERIAL:		Cedar shingles						
HISTORIC FUNCTION:	Livestock barn		ROOF SHAPE:		Gambrel						
HISTORIC SUBFUNCTION:	Hay and grain storage		STRUCTURAL SYS	STRUCTURAL SYSTEM:							
			S	Gambrel roof barn							
OCCUPIED:	No			Livestock barn							
ACCESSIBLE:	Yes with permission		w	2x6, sheathing & ½"x6" cedar lap siding							
STORIES:	2	S	SIGNIFICANT PERSON:	Chris	stian Larson						
	Late 1800's to										
*DATE OF CONSTRUCTION:		CU	LTURAL AFFILIATION:	N	lorwegian						
ALTERED/MOVED NOTES:	Original site.										
_											
INTERIOR NOTES: 4x6 pos	ts and (3) 2x8's h	neam to	support havloft floor F	our nos	sts at the North end						
			_ · · _ ·	•							
were 6x6 posts. Joists were 2x8. Horse stalls, milk cow stanchions, calf pen and granary are still in place. 2x6's for studs, rafters and bracing, 2x8 floor joists, 4x6 and 6x6 posts and 2x8 beams were rough											
sawn cottonwood. There are	4x6 posts in the	gable er	nd walls to support the	ends of	the beams.						
OTHER NOTES: Windows w	ere 9"x12" four l	light. 2x	6 walls 14' high with sh	eathing	and ½"x6" siding.						
Sheathing is diagonal on the gable end walls. Rafters are braced rafters with no posts to support the hip.											
The diagonal path of the bean	ns at the North a	lley is in	teresting.								
*PHYSICAL NOTES: Barn is	in poor condition	on. Roo	f is leaking. Without a n	ew roo	f this barn will not						
last long.											



SKETCH MAP







PHOTOGRAPHER: _____ DATE OF PHOTO: Jim Stone June 21, 2012 ROLL NUMBER:

PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone June 21, 2012 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West, horse stalls facing North

CAMERA DIRECTION: wall



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, cow stanchions

CAMERA DIRECTION: on West wall





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, stanchions, horse stall &

CAMERA DIRECTION: granary on East wall



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North,upper braced

CAMERA DIRECTION: rafter system





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 21, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North lower braced rafter

CAMERA DIRECTION: system



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 2, 2012


ROLL NUMBER: PHOTO NUMBER:

10

Hayloft, looking South,

CAMERA DIRECTION: gable end







HISTORY

Christian Larson homesteaded the SE ¼, except the SW ¼ (40 acres) of Section 14 and the N ½ of the NW ¼ and the N ½ of the NE ¼ of Section 23. The 80 acres in Section 23 was most likely a timber claim.

The 1894, 1901 and 1912 Clay County Atlas lists Anna Larson as the owner.

The 1924 and 1937 Clay County Atlas lists Anna and Sarah Larson as the owners.

The 1948 and 1956 Clay County Atlas lists Trudy D. Macy as the owner.

The Following information was furnished by Marion Kryger who lived in the area his whole life.

Christian Larson and his wife had three children. Anna, Sarah and Emil. Sarah and Anna never married and stayed on the farm after the parents died. The two sisters farmed the land and milked 12 to 14 cows. The barn has 14 milk cow stanchions. The two sisters lived here the rest of their lives.

Emil lived in Vermillion. He married Trudie Macy. They had two children. Twila and Trudie. Twila married Dick Stevens and Trudie married Marshall Macy. Trudie and Marshall had a son Robert (Bob) who became a banker.