

SITE INFORMATION

*SURVEY DATE: January 8, 2013

*ADDRESS: <u>46913 303rd Street</u> *COUNTY: Clay

*SURVEYOR: Jim Stone

*CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, East 2 miles to Greenfield Road, Turn left (North) 15-1/2 miles to 303rd Street, turn right (East) about 1-1/8 mile, on right (South) side

LEGAL DESCRIPTION: E1/2, NW ¼ & N ½ (N 35.78 A), W1/2, NW ¼, 1 – 94 – 51 Garfield Twp.

*QUARTER 1:	NW 1/4		0	WNER NAME:	Gerald	1 & F	loyd	l Bi	rkela	nd		
*QUARTER 2:			OWNE	R ADDRESS:	46872	303	rd St	reet				
*TOWNSHIP:			C	OWNER CITY:	Beres	ford						
*RANGE:	51		OV	NER STATE:	South	Dak	ota					
*SECTION:				OWNER ZIP:	57004							
ACRES:	112.39			QUAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNI	FICANCE											
*DOE:			REGISTER N A	ME:								
				MULTIPLE PR	OPERT	Y N/	AME:					
REASON INELIGIBL	.E:		<u> </u>									
					C	ATE	GOF	۲Y:				
NOMINATION				SIGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
	E LISTED:			SIGNI	FICANC	ELE	EVEL	. 2:	Ν	S	L	
REFERENCE	NUMBER:											
HISTORIC DISTRIC	FRATING:	C or NC	C	CRITE	ERIA 1:	Α	В	С	D			
	PERIOD:			CRITE	ERIA 2:	Α	В	С	D			
					ERIA 3:							
				CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOT	'ES:											
STRUCTURE DE	TAILS											



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Storage	FOUNDATION	Poured concrete foundation
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Steel roofing over
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM	: Balloon framing
		STYLE	: Gable roof barn
OCCUPIED:	Yes	TYPE	: Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x6 R.S. studs, 1x6 #106 drop siding and ½"x 6" cedar lap siding
STORIES:	2	SIGNIFICANT PERSON:	Claus Frick
*DATE OF CONSTRUCTION:	1920's	CULTURAL AFFILIATION:	Swedish

 ALTERED/MOVED NOTES:
 Original site.
 Milk cow stanchions and horse stalls have been removed.

 Roof has been covered with steel roofing.
 14'x36' lean-to added on the South side at a later date.

 Posts have been removed and replaced with 4" round steel pipe posts.
 Interior has been remodeled

 for a dairy barn a long time ago.
 Concrete floor poured with gutters and milk room built in the NW


 corner, which could have been a granary before the remodel.

INTERIOR NOTES: <u>Has three rows of 4" round steel posts, with (3) 2x8's for a beam, which run North to</u> South (the short way). 2x6 rough sawn cottonwood floor joists run the long way East to West.

OTHER NOTES: 2x6 rough sawn cottonwood stud walls with 1x6 #106 drop siding and ½"x6" cedar lap siding. Windows are 9"x12"four light on the East and South walls and 4"x24" four light on the West and North walls. Metal cupola still in place, but it is a design that I have not seen before. Two rough sawn cottonwood 2x8 posts with a 2x6 beam support the center of the rafters on each side in the hayloft. *PHYSICAL NOTES: Barn is in very good condition.

*UTM ZONE:	*RESTRICTED: Y or N
*UTM EASTING:	
*UTM NORTHING:	





REQUIRED FIELD

3







PHOTO NUMBER: 2 CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	January 8, 2013	PHOTO NUMBER:	4
-		CAMERA DIRECTION:	Looking SE, NW corner

REQUIRED FIELD






PHOTOGRAPHER:	Jim Stone
DATE OF PHOTO:	January 8, 2013

ROLL NUMBER: PHOTO NUMBER:

```
5
                       First floor, looking SE,
                       Steel posts, (3) 2x8's
CAMERA DIRECTION: beam and 2x6 floor joists
```



CAMERA DIRECTION: <u>West corner.</u>





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:
DATE OF PHOTO:	January 8, 2013	PHOTO NUMBER:

Hayloft, looking SE, 2x8 post and 2x6 beam supporting center of rafters

7



PHOTOGRAPHER: Jim Stone DATE OF PHOTO: January 8, 2013

ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 8 Hayloft, looking South and up, 2x6 rafters and roof sheathing, all rough sawn cottonwood.

REQUIRED FIELD



T-94-N		GLENW	DIRECTORY		R-51-V
464th AVE UNIVERS	TY AVE	Christoffact Kindstr 406.27 4 4 4 4 9 8 9 8 9 8 9 8 9 8 9 8 9 8 9 8	Calson K Calson 30337 • 30332 30337 • Terty Gary lensin Carton 447 9 • 46730	2 С С С С С С С С С С С С С	e46913 St 1 leff Broat d03975
C Tentorff Teldorff Johnon 30437 7 berg = 30451	Oriand Sternpulat = 30472 Bennis Ocmanel 30485 46504 30485	• Merie Christensen 30404 9	Asten Lunquist 46733 10	M Schurch 30433 # NEWDALE ST	*** *** *** *** *** *** *** *** *** **
305th ST Bear 20535 18 Frickson #6422	**************************************	Dean Indextrom #30524 16 Duane Hundquist 46633 #	■Roland Cyfe 30534 15 46776 St=	Randall jensen 30540 14 j Taylor Jensen 46820 46886	Charles Jossia 30536 Ave 30531 13 [ohn t Isner 30577
306th ST PDos Indestrom 30624 19	Italianten Olegen reds00 46507 reds0 46507 reds0 46507 reds0 46507 reds0 46507 reds0 20 State 306417 Marton Splite State Splite	21	M Boug Hamerum Hays 46741 22 22 314 46750 8140 8140 8140 8140 8140 8140 8140 814	23 Kendal Swee ■46836 군	24 46904 erraren 951 - 46978
terry Whichen 46449 follman 46442 follman 46442 follman Hansen 46415 30 10 Hansen 46415 30	117335 11755	Mike Zwier B0724 Jameison D0750 28 Marvin Christensen 30766	5 27 Hein 30768 kaptenad 46756	Ao 1 5 kg Ao 1 5 kg	25 Eric Alexander • 6926
308th ST	Craty 50859 15055 1505 1505 1505 1505 1505 1505 1	33 Larry Larson 30869 = David Alexander 30872 ~~~~	Curtis #J085hm 30856 34 30879 Rd =	Don Field lenser Fried 20027 20027 35	Lamic Eryce Jamic Lensen 30834 30845 / 30845 / 30845 / Javid Howard 40970 H

PRAIRIE CENTER TWP.

© Farm & Home Publishers, Ltd.

21

CLAY CO., S



HISTORY

This farm located in the NW ¼ of Section 1, Garfield Township, Clay County was homesteaded by Olf Lindberg.

The 1894 Clay County Atlas lists John Hedberg as the owner.

The 1901, 1912 and 1924 Clay County Atlas lists Claus Frick as the owner.

The 1937 Clay County Atlas lists Hilma A. Johnson as the owner.

The 1948 and 1956 Clay County Atlas lists Hilmer Johnson as the owner.

