

```SITE INFORMATION

*SURVEY DATE: March 29, 2014

*SURVEYOR: Jim Stone

*ADDRESS: 29720 463rd Ave.

*COUNTY: Clay

*CITY: Centerville

LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 19 miles to 298th Street, turn right (East) about 1 mile to 463rd Ave., turn left (North) about ³/₄ mile, on the right (East) side.

LEGAL DESCRIPTION: NW 1/4, Lots 1 & 2 Exc R/W, 1 –95 – 52 Riverside Twp.

| *QUARTER 1: | NW 1/4 | OWNER NAM | ME: Milton D. & Susan M. Brue | |
|------------------|--------------|--------------|----------------------------------|--|
| *QUARTER 2: | | OWNER ADDRES | SS: 29720 463 rd Ave. | |
| *TOWNSHIP: | Riverside | _ OWNER CIT | TY: Centerville | |
| *RANGE: | 52 | OWNER STAT | TE: South Dakota | |
| *SECTION: | 1 | _ OWNER Z | CIP: <u>57014</u> | |
| ACRES: | 147.06 | QUAD NAM | ИЕ: | |
| OWNER CODE 1: | Р | | | |
| OWNER CODE 2: | | | | |
| OWNER CODE 3: | | | | |
| | | | | |
| | | | | |
| HISTORIC SIGN | IFICANCE | | | |
| *D0 | 0E: | REGISTER | R NAME: | |
| *DOE DA | TE: | MULTIPLE | E PROPERTY NAME: | |
| REASON INELIGIB | LE: | | | |
| | | | | |
| | | | CATEGORY: | |
| NOMINATIO | N STATUS: | SIC | GNIFICANCE LEVEL 1: N S L | |
| DAT | TE LISTED: | SIC | GNIFICANCE LEVEL 2: N S L | |
| | NUMBER: | | | |
| HISTORIC DISTRIC | TRATING: C o | or NC CF | RITERIA 1: A B C D | |
| | PERIOD: | CF | RITERIA 2: A B C D | |
| | | CF | RITERIA 3: A B C D | |
| | | CF | RITERIA 4: A B C D | |
| | | | | |
| SIGNIFICANCE NO | TES: | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| STRUCTURE DE | TAILS | | | |



| | _ | | |
|------------------------|--------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | |
| | | | |
| | | | Notivo otono no |
| Storage | FOUNDA | TION: | Native stone, no mortar |
| Storage | | RIAL: | Some steel roofing over cedar shingles |
| _ivestock barn | ROOF SH | APE: | Gambrel roof |
| Hay and grain storage | STRUCTURAL SYS | TEM: | Balloon framing |
| | ST | YLE: | Gambrel roof barn |
| /es | Т | YPE: | Livestock barn |
| res with permission | WALLS: | - | 2x6 studs and 1x6 #106 drop siding |
| | | - | |
| 2 | SIGNIFICANT PERSON: | Cla | us L. Isackson |
| 1910 to 1920 CU | LTURAL AFFILIATION: | | Swedish |
| | Storage ivestock barn lay and grain storage les ves ves with permission 2 S | Storage ROOF MATE Livestock barn ROOF SH lay and grain storage STRUCTURAL SYS ST STRUCTURAL SYS Ves T Ves T Ves T Structure Structure Structure Structure | Storage ROOF MATERIAL: ivestock barn ROOF SHAPE: lay and grain storage STRUCTURAL SYSTEM: STYLE: STYLE: Yes TYPE: Yes with WALLS: 2 SIGNIFICANT PERSON: Clag |

ALTERED/MOVED NOTES: Original site. 18 single horse stalls still in place, but the mangers have been removed and each stall is divided for two lambing pens. Steel roofing applied directly to the sheathing with cedar shingles removed on the South lower side only. A 48' x 54' open sided lean-to added on the

South side. Two 12' x 48' low three sided lean-to's added to the West and East sides of the 48' x 54' leanto and are open into the same lean-to. A 36' wide x 78' open sided addition added on the East side.

 INTERIOR NOTES:
 Four rows of 4x6 posts, 6x6 beams and 2x8 floor joists for the hayloft floor. Two

 more rows of 4x6 posts with short 4x6's above each post in 5' – 6" from the North and South walls.

 18 single horse stalls without mangers are still on place but remodeled into two lambing pens each.

 OTHER NOTES:
 2X6 stud walls with 1x6 #106 drop siding. Windows are 9" x 12" four light over 9"x 12"

 four light for double hung windows.
 Rafters are 2x6's with (2) 2x6's for a beam at the hip and 4x6 posts

 from the hip slanted in 5' at the bottom. The 4x6 posts are 12' – 8' - 12' - 10' – 12' O. C. and support


 the roof hip.

 *PHYSICAL
 Barn is in fair condition.


 *UTM EASTING:
 *RESTRICTED: Y or N



SKETCH MAP








PHOTOGR






PHOTOGR

* = REQUIRED FIELD

5







* = REQUIRED FIELD









PHOTOGRAPHER: DATE OF PHOTO: Jim Stone March 29, 2014

ROLL NUMBER: PHOTO NUMBER:

5 First floor looking East into single horse stall remodeled into two lambing pens

CAMERA DIRECTION: lambing pens.



| PHOTOGRAPHER: | Jim Stone | ROLL NUMBER: | |
|----------------|----------------|---------------|--|
| DATE OF PHOTO: | March 29, 2014 | PHOTO NUMBER: | |

PHOTO NUMBER: 6 First floor looking East, walk alley along the CAMERA DIRECTION: North wall of barn.





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone March 29, 2014 ROLL NUMBER: PHOTO NUMBER:

7 First floor, looking South into feed alley, note stairs to hayloft on the south wall

CAMERA DIRECTION: _south wall.




| PHOTOGRAPHER: | Jim Stone | ROLL NUMBER: | |
|----------------|----------------|---------------|---|
| DATE OF PHOTO: | March 29, 2014 | PHOTO NUMBER: | 8 |
| | | | |

CAMERA DIRECTION: 2x6 at the roof hip.

Hayloft, looking NE, 4x6 posts supporting double 2x6 at the roof hip.






| PHOTOGRAPHER: | Jim Stone | ROLL NUMBER: |
|----------------|----------------|---------------|
| DATE OF PHOTO: | March 29, 2014 | PHOTO NUMBER: |
| | | |

| 9 | |
|--------------------------|--|
| Hayloft, looking West at | |
| large hayloft door and | |
| West gable end wall. | |

CAMERA DIRECTION: V





PLEASANT VALLEY TWP.

C Farm & Home Publishers, Ltd.

35

CLAY CO., SD



HISTORY

This farm located in the NW ¼ of Section 1, Riverside Township, Clay County was homesteaded by George Lowrie.

The 1894 Clay County Atlas lists Arne Thoreson as the owner.

The 1901 Clay County Atlas lists Gust A & Claus L. Isackson as the owners.

The 1912 Clay County Atlas lists Claus L. Isackson as the owner.

The 1924, 1937, 1948 and 1956 Clay County Atlas lists Jacob J. Brue as the owner.

Adrian and Helen Isackson

Adrian Isackson was born in Bringtofta Parish, Sweden in 1831. He was married to Helen Johnson who was born July 4, 1845. They married in Sweden and immigrated to the United States in 1868, to the NW ¼ of Section 19 in Glenwood Township, Clay County, where they homesteaded.

Their children were; Gust (1857 – 1922), Claus (1859), John (1863), Amanda (1873), Christina (1876), Emil (1879), and Phillip (1883).

Adrian died Jan. 2, 1924 and Helen died in 1908.