

#### **SITE INFORMATION**


*SURVEY DATE: May 2	*ADDRESS:	30035 Frog Creek Road					
*SURVEYOR: Jim Stone		*COUNTY:	*COUNTY: Clay				
		*CITY:	Wakonda				
LOCATION DESCRIPTION: <u>F</u>	rom the intersect	ion of South Dakota I	ا-lighway 50 bi	oass and	South	h	
Dakota Highway 19, North 15 m	iles to 302 <sup>nd</sup> Stre	et, turn left (West) 3 n	niles to Frog C	reek Roa	ıd, turr	n right	
(North) 1-1/2 miles on the left (\	Nest) side.						
LEGAL DESCRIPTION: <u>S 1,4</u>	12' of E 617' of N	$E \frac{1}{4} 19 - 95 - 52$ Rive	erside Twp				
*QUARTER 1: NE 1/4		OWNER NAME:	Colin Olsen				
*QUARTER 2:			S: 30035 Frog Creek Road				
*TOWNSHIP: Riverside		OWNER CITY:	-				
*RANGE: 52		OWNER STATE:					
*SECTION: 19		OWNER ZIP:					
ACRES: 18.66		QUAD NAME:					
OWNER CODE 1: P							
OWNER CODE 2: F S L	Р						
OWNER CODE 3: F S L	Р						
HISTORIC SIGNIFICANCE							
*DOE:		REGISTER NA	REGISTER NAME:				
*DOE DATE:		MULTIPLE PR	MULTIPLE PROPERTY NAME:				
REASON INELIGIBLE:							
			CATEGO				
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L				
DATE LISTED:		SIGNII	FICANCE LEVE	L 2: N	S	L	
REFERENCE NUMBER:							
HISTORIC DISTRICT RATING:			ERIA 1: A B				
PERIOD:			RIA 2: A B				
			RIA 3: A B				
		CRITE	ERIA 4: A B	С	)		
CIONIEIO ANGE NOTES							
SIGNIFICANCE NOTES:							



STRUCTURE DETAILS								
SHPO ID:								
*PROPERTY NAME:		_						
OTHER NAME:								
CURRENT FUNCTION:	Ultra-Light airplane hanger	FOUNDATION:	Poured concrete					
		_	Steel over cedar					
CURRENT SUBFUNCTION:	Shop and storage	_ ROOF MATERIAL:	shingles					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable					
HISTORIC SUBFUNCTION:	Hay storage.	_ STRUCTURAL SYSTEM:	Balloon framing					
		STYLE:	Gable roof barn					
OCCUPIED:	Yes	TYPE:	Livestock barn					
			2x6, with sheathing					
ACCESSIBLE:	Yes with	MALLS.	& ½"x6" cedar lap					
ACCESSIBLE.	permission	WALLS:	siding					
STORIES:	2	SIGNIFICANT PERSON:	?					
*DATE OF CONSTRUCTION:		JLTURAL AFFILIATION:	?					
DATE OF CONSTRUCTION.	1929	LIONAL AITILIATION.	•					
ALTERED/MOVED NOTES: Original site. Horse stalls and milk cow stalls have removed. Walls are								
Insulated and covered for shop. West 24' have been removed for a folding door for the airplane. The								
gable end is supported by a four ply 2x12 beam. Feed room in the NW corner has been removed.								
gazie cha le capportou by a rour pry zariz bourin i cou room in the 1919 control into book removed.								
INTERIOR NOTES: 4'x9' milk room in the NE corner and a 9' x 9' calf pen west of milk room. Two rows								
6x6 posts and 6x6 beam. 4'x9' alley on the SW corner of main barn with gates at each end. Was used as								
calf pen also. South 16'-6" x 28'-6" lean-to was for hogs.								
OTHER NOTES: 2x6 stud walls 13' high on the North and South sides. The South walls of lean-to is 2x6								
stud wall 8' high. 2x6 stud walls on the gable ends. Horizontal sheathing and ½"x6" cedar lap siding.								
4"x24" four light windows. 2x	6 rafters with a 2x4 lam	inated on one side. 2x6 bracing	g from top of wall in					
hayloft down to floor joists.								
*PHYSICAL NOTES: Barn is in very good condition. Siding is painted. Looks very nice.								



#### SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 7, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: March 7, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking SW, NE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Hayloft, looking East, rafters & hayloft door





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NE,

CAMERA DIRECTION: shop area



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone March 7, 2012 **ROLL NUMBER:** 

**PHOTO NUMBER:** 

First floor, looking SE, where milk cow

**CAMERA DIRECTION: stanchions were** 





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: March 7, 2012


**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: into 4' x 9' milk room

First floor, looking North

\* = REQUIRED FIELD





CI AV CO. SD



### **HISTORY**

This farm located, in the NE ¼ of Section 19, Riverside Township, Clay County was homesteaded by Alfred Hall.

The 1894 and 1901 Clay County Atlas lists Edwin Hall as the owner.

The 1912 and 1924 Clay County Atlas lists R. D. Hall as the owner.

The 1937 Clay County Atlas lists Metropolitan Life Insurance Co. as the owner.

The 1894 and 1901 Clay County Atlas lists Edwin Hall as the owner.

