

SITE INFORMATION

*SURVEY DATE: June 5, 2012

*ADDRESS: <u>30174 458th Ave.</u>

*COUNTY: Clay

*SURVEYOR: _Jim Stone

*CITY: Wakonda

 LOCATION DESCRIPTION:
 From the intersection of South Dakota Highway 50 bi-pass and South

 Dakota Highway 19, 15 miles
 North to 302nd Street, turn left (West), 4 miles turn right (North), about ¼ mile

 On the right (East) side.

LEGAL DESCRIPTION: Dose Tract 1 SW ¼, 30 – 95 – 52 Riverside Twp.

*QUARTER 1:	SN	/ 1/4				OWNER NA	ME:	Henry	& C	aroly	n Ya	ankov	wski		
*QUARTER 2:	:				0	WNER ADDRE	SS:	30174 458 th Ave.							
	Riverside					OWNER CI	TY:	Wakonda							
	52							South Dakota							
*SECTION:						OWNER 2	ZIP:	57073							
ACRES:		7.69				QUAD NA									
OWNER CODE 1:															
OWNER CODE 2:	F	S	L	Ρ											
OWNER CODE 3:	F	S	L	Ρ											
HISTORIC SIGN	IFIC	JAN	ICE												
*D	OE:					REGISTE	R NA	ME:							
REASON INELIGIB															
						_									
						-		C	ATE	GOF	RY:				
NOMINATIO	N S	ΓΑΤΙ	JS:			S	IGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
							IGNI	FICANC	ELE	EVEL	. 2:	Ν	S	L	
HISTORIC DISTRIC							RITE	ERIA 1:	Α	в	С	D			
	Ρ	ERIC	DD:			С	RITE	ERIA 2:	Α	в	С	D			
							RITE	ERIA 3:	Α	в	С	D			
						С	RITE	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NO	TES	: _	Loca	ally k	nown as Mrs. D	Dose farm from	<u>ı the</u>	<u>mid 1</u> 9	<u>40's</u>	<u>to n</u> o	ow.				



STRUCTURE DETAILS				
SHPO ID:		-		
*PROPERTY NAME:				
OTHER NAME:				
CURRENT FUNCTION:	Vacant	FOUNDA	TION:	Poured concrete
				Steel roofing over
CURRENT SUBFUNCTION:		ROOF MATE	RIAL:	cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SH	IAPE:	Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYS	TEM:	Balloon framing
		ST	TYLE:	Gambrel roof barn
OCCUPIED:	Yes	1	TYPE:	Livestock barn
	Yes with			2x6, sheathing &
ACCESSIBLE:	permission	WA	ALLS:	cedar siding
STORIES:	2	SIGNIFICANT PERSON:	Dav	vid Horlocker
*DATE OF CONSTRUCTION:	1915 to 1925 CU	LTURAL AFFILIATION:		?
		-		

ALTERED/MOVED NOTES: <u>Original site.</u> Roof has been covered with steel roofing. Owner has installed three vinyl double hung windows on the North end of First floor.

INTERIOR NOTES: <u>Three rows 6x6 & 4x6 posts with 6x6 beam 9' O. C. 2x8 floor joists for hayloft floor.</u> Center feed alley has a 3' high concrete wall for feed trough wall for milk cow stanchions. Original milk cow stanchions are still in place. One double horse stall in the NW corner.

OTHER NOTES: Large 16'x8' granary in NW corner of hayloft. 2x6 stud walls 14'8" tall on East and

West sides. 2x6 walls 18' tall on the North and South gable ends with 2x6 studs above to roofline.

Horizontal sheathing with 1/2x6" cedar lap siding. 2x6 rafters with sheathing , cedar shingles and steel roofing. Concrete floors with gutters for milk cows. 2x6 and 2x8 rafter bracing in hayloft.


*PHYSICAL NOTES: <u>Barn is in very good condition. Needs some siding and sheathing on the SE</u> Corner. Some windows need to be replaced. Metal cupola.




Ð

Û

SKETCH MAP





* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone June 5, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION: Looking NW, SE corner

1



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	June 5, 2012	PHOTO NUMBER:	2
		CAMERA DIRECTION:	Looking NE, SW corner






 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 June 5, 2012
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking SE. NW corner



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 June 5, 2012
 PHOTO NUMBER:
 4

 CAMERA DIRECTION:
 Looking SW, NE corner

June 5, 2012





PHOTOGRAPHER: ____ DATE OF PHOTO: ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 5 First floor, looking East, original milk cow CAMERA DIRECTION: stanchions



PHOTOGRAPHER:Jim StoneDATE OF PHOTO:June 5, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: milk cow stanchions

6 First floor, looking east, milk cow stanchions





PHOTOGRAPHER:Jim StoneDATE OF PHOTO:June 5, 2012

ROLL NUMBER: PHOTO NUMBER: Hayloft CAMERA DIRECTION: corner

7 Hayloft, granary in NW corner



PHOTOGRAPHER:	Jim Stone				
DATE OF PHOTO:	June 5, 2012				

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: _rafter bracing

8 Hayloft, looking SW, hip rafter bracing






PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	June 5, 2012	PHOTO NUMBER:	9
			Havloft looking SW

nayion, looking Sw, CAMERA DIRECTION: lower rafter bracing





ΩE





HISTORY

This farm located in the SW ¼ of Section 30, Riverside Township, Clay County was homesteaded by David Horlocker.

The 1894 and 1901 Clay County Atlas lists David Horlocker as the owner.

The 1912 Clay County Atlas lists James Horlocker as the owner.

The 1924 and 1937 Clay County Atlas lists Claud A. Withers as the owner.

The 1948 and 1956 Clay County Atlas lists Elis Dose as the owner.