

SITE INFORMATION

*SURVEY DATE:	, 2012	*ADDRESS: 31339 463rd Ave.										
*SURVEYOR:		*COUNTY:	Clay									
	*CITY:	Vermillion										
LOCATION DESCRIPTIO	N: Vermillio	n, from the inters	ection of Sout	th Dako	ta H	ighw	ay 5	0 bi-	pass	and		
South Dakota Highway 19, North 3 miles to 314 th Street, turn right (East) ½ mile to 463 rd Ave., turn left												
(North) about ¾ mile on the left (West) side. LEGAL DESCRIPTION: Andersen Tract 2, NE ¼, 26 – 93 – 52 Spirit Mound Twp.												
LEGAL DESCRIPTION:	Andersen T	ract 2, NE 1/4, 26	– 93 – 52 Spi	rit Mou	nd T	wp.						
*QUARTER 1: NE	≣ 1/4	OW	NER NAME:	l iea V		C						
			R ADDRESS:									
	·			Sioux City								
	52		•	lowa								
				51106								
	3.23		UAD NAME:									
OWNER CODE 1: P		_										
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNIFICA	NICE											
HISTORIC SIGNIFICA	AINCE											
*DOE:			REGISTER NAME:									
*DOE DATE:			MULTIPLE PR	OPERT	Y N	AME:	: <u> </u>					
REASON INELIGIBLE: _												
						GOF	•					
NOMINATION STATUS:												
DATE LIS	-		SIGNIF	FICANC	EL	EVEL	. 2:	N	S	L		
REFERENCE NUM	-											
HISTORIC DISTRICT RA		_		RIA 1:								
PE	RIOD:			RIA 2:								
				RIA 3:								
			CRITE	RIA 4:	Α	В	С	D				
SIGNIFICANCE NOTES												
SIGNIFICANCE NOTES:												


STRUCTURE DETAILS




SHPO ID:			_								
*PROPERTY NAME:											
OTHER NAME:											
CURRENT FUNCTION:	Vacant		FOUN	DATION:	Poured concrete foundation						
GOTALENT FORGITON.	Vadant			<i>5</i> /(1101()	Steel roofing over						
CURRENT SUBFUNCTION:	Storage		ROOF MA	cedar shingles							
HISTORIC FUNCTION:	Livestock barn		ROOF	SHAPE:	Gambrel roof						
HISTORIC SUBFUNCTION:	Hay storage		STRUCTURAL	Balloon framing							
				STYLE:	Gambrel roof barn						
OCCUPIED:	No			TYPE:	Livestock barn						
ACCESSIBLE:	Yes with permission			WALLS:	2x6 studs with 1x6 #106 drop siding and steel siding						
STORIES:		-	SIGNIFICANT PERSOI	_	?						
*DATE OF CONSTRUCTION:	?	CU	LTURAL AFFILIATIO	N:	?						
ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or horse stalls has											
been removed. Roof has been covered with steel roofing. Walls have been covered with vertical steel											
roofing. Concrete foundation	n and floor appe	ars to na	ive been poured later	•							
INTERIOR NOTES: Has two	rows of 6x6 pos	sts, with	6x6 for a beam. 2x6 f	loor joists	for hayloft floor.						
4x4 posts 8' O.C. in hayloft the											
(2) 1x6's brace each hip. 2x6 brace 8' O.C. center of top rafter down to bottom of lower rafter. (2) 1x6's brace rafters down to bottom of wall in hayloft floor. These are centered between 4x4 posts.											
OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding and vertical steel roofing. Studs are 16"											
O. C. All 2x4 rafters, 2x6 studs, floor joists, bracing 4x6 sills and 6x6's are rough sawn cottonwood.											
Windows are 14"x20" two ligi											
O. C. 6x6 posts in North and rafters 3' down from hip.	South walls to s	support (ends of 6x6 beams. 2x	x6 and 2x4	l beams support						
*PHYSICAL NOTES: Barn is	s in fair to good	conditio	n.								
*UTM ZONE:			*RESTRICTI	ED: Y o	r N						
*UTM EASTING:											
*UTM NORTHING:											
											



SKETCH MAP









PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 5, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 5, 2012**

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 6x6 posts, 6x6 beams CAMERA DIRECTION: and 2x6 floor joists.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone December 5, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SW, 4x4 posts and 2x6 bracing. Note posts support rafters about 3' below

CAMERA DIRECTION: hip





Jim Stone PHOTOGRAPHER: DATE OF PHOTO: December 5, 2012

ROLL NUMBER: PHOTO NUMBER:


Hayloft, Looking SE, rafter bracing, note (2) 1x6 bracing from rafters down to bottom of wall in

hayloft, centered

CAMERA DIRECTION: <u>between 4x4 posts</u>.

* = REQUIRED FIELD





SPIRIT MOUND TOWNSHIP SECTION 23

- 1 McDonald, Ben 31284 2 Freidel, Mike 31288 3 46292
- 4 Wood, Robert 46296

© Farm & Home Publishers, Ltd.

37

CLAY CO., SD



HISTORY

This farm Located in the NE ¼ of Section 26, Spirit Mound Township, Clay County was homesteaded by Wm. Harris.

The 1894 and 1901 Clay County Atlas lists H. V. Moody as the owner.

The 1912 Clay County Atlas lists Stanlslas DeLaurier as the owner.

The 1924 Clay County Atlas lists E. C. Ryan as the owner.

The 1937 Clay County Atlas lists J. Himovitz as the Owner.

The 1948 and 1956 Clay Atlas lists Gerald LaFerriere as the owner.

