

### SITE INFORMATION

*SURVEY D	ATE: <u>Febr</u> ι	2013	*ADDRESS	*ADDRESS: 46083 303 <sup>rd</sup> Street							
*SURVEYOR: Jim Stone				*COUNTY	Clay						
				*CITY	Centerville						
LOCATION DESCR	IPTION: F	rom Ver	million, Sout	n Dakota Highwa	y 50 bi-p	oass	and	Sou	th Da	akota	1
Highway 19, North 15 miles to 302 <sup>nd</sup> Street, turn left (West) I mile to 461st Ave., turn South 1 mile to 303 <sup>rd</sup>											303 <sup>rd</sup>
street, turn right (W	/est) about ½	4 mile, c	on the left (So	uth) side, vacate	d place.						
LEGAL DESCRIPTI	ON: Lots	1 & 2, N	E ¼, 4 – 94 –	52 Pleasant Valle	ey Twp.						
*QUARTER 1:	NE 1/4			OWNER NAME:	: Loann Kjeldseth & Jane So						nmer
*QUARTER 2:	14= 174		OW	NER ADDRESS:							
*TOWNSHIP:	Pleasant V	allev		OWNER CITY:							
*RANGE:	52	unoy		OWNER STATE:							
*SECTION:	4			OWNER ZIP:							
ACRES:	148.10			QUAD NAME:							
OWNER CODE 1:	P										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGN	IFICANCE										
*DOE:				REGISTER NA	ΔМΕ·						
*DOE DATE:				MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:					.01 =			_			
					C	CATE	GOF	RY:			
NOMINATION STATUS:				SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:				SIGNI	FICANO	E LI	EVEL	<b>2</b> :	N	S	L
REFERENCE	NUMBER:										
HISTORIC DISTRIC	T RATING:	C or	NC	CRITI	ERIA 1:	Α	В	С	D		
	PERIOD:			CRITI	ERIA 2:	Α	В	С	D		
				CRITI	ERIA 3:	Α	В	С	D		
				CRITI	ERIA 4:	Α	В	С	D		
SIGNIFICANCE NOTES:											


#### STRUCTURE DETAILS



SHPO ID:		_								
*PROPERTY NAME:										
OTHER NAME:										
<b>CURRENT FUNCTION:</b>	Vacant	FOUNDATION:	Poured concrete							
	_		Steel roofing over							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:								
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE: STRUCTURAL SYSTEM:	Gable							
HISTORIC SUBFUNCTION:	Hay and grain storage	Post frame								
		STYLE:	Western Feeder barn							
OCCUPIED:	No	TYPE:	Livestock barn							
OCCOPIED.	INO	IIPE.	4x6 and 6x6 posts,							
			with 2x6 girts 4' O.							
			C. and 12" vertical							
ACCESSIBLE:	?	WALLS:	board siding							
STORIES:	1	SIGNIFICANT PERSON:E	dward Heller							
*DATE OF CONSTRUCTION:	Early 1900's CU	LTURAL AFFILIATION:	?							
ALTERED/MOVED NOTES:	Original site. Steel roo	ofing has been applied on the r	oof.							
INTERIOR NOTES			(4)(4) (0) 001 f							
	•	gh on each side of the center 2								
a beam to support the center of the rafters. Three double horse stalls and 7 milk cow stanchions are										
still in place on the North side. Two 9'x6' granaries are still in place along center of the West wall.										
OTHER NOTES: 4x6 and 6x6 posts with 2x6 girts, 4' O. C. and 1x12 vertical siding on exterior walls.										
Windows are 10"x12" four light. Rafters are 2x6, 32" O. C. There is a feed bunk and a hay feed rack										
above it along the North wall	in the South area. The o	center area 24' wide by 50' long	and is a hayloft							
from the ground level to the	peak. It is 31' from the g	round to the peak.								
*PHYSICAL NOTES: Barn is in fair condition. Needs repairs on doors and windows. Some of the										
battens are missing on the si	ding.									
*IITM ZONE-		*DESTRICTED: V	N							
			DI IN							
*UTM EASTING:										
*UTM NORTHING:										




#### SKETCH MAP





#### SKETCH MAP



#### **PHOTOGR**

\* = REQUIRED FIELD





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **February 5, 2013** 

**ROLL NUMBER: PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013 **ROLL NUMBER:** 

**PHOTO NUMBER:** 

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013 ROLL NUMBER: PHOTO NUMBER:

R: \_\_\_\_\_3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013 ROLL NUMBER:

PHOTO NUMBER:

4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, South side, looking NE, feed bunk

CAMERA DIRECTION: and hay feed rack above



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, North side, looking NE, seven milk

CAMERA DIRECTION: cow stanchions





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 5, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, center area, looking SE, hay feed rack and 6x6 posts 20'

CAMERA DIRECTION: high with bracing



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone February 5, 2013

**ROLL NUMBER:** PHOTO NUMBER:

First floor, looking SE, 6x6 post 20' high, (2) 2x6's for a beam to support rafters and

CAMERA DIRECTION: bracing





CLAY CO., SD

© Farm & Home Publishers, Ltd.

31



### **HISTORY**

This farm located in the NE ¼ of Section 4, Pleasant Valley Township, Clay County was homesteaded by Lennder Pierce.

1894,1901 and 1912 Clay County Atlas lists George Wright as the owner.

1924 and 1937 Clay County Atlas lists Edward Heller as the owner.

The 1948 and 1956 Clay County Atlas lists L. A. Heller as the owner.

The following information is from

### Wakonda, South Dakota Centennial book 1885 - 1985

Edward Heller and his wife Flora (Smith) and two children, Alva and Pearl, came to South Dakota in 1902 from Geneseo, Illinos. They settled on their farm six miles East and one mile South of Wakonda. Their daughter Ruby was born here. In 1910 they moved to LeMars, Iowa where Lewis was born, but they returned to their South Dakota farm the next year. Their youngest child Doris, was born in 1916. They continued farming until they retired in 1939 and moved to Centerville. Edward died in 1944 and Flora in 1965.

Lewis Heller and Alice Bixler were married August 18, 1933. They are both graduates of Centerville High School. They lived on the same East Heller farm since 1939. They experienced many floods. In 1983 there were five floods from February 28 to July 7.

They have two daughters, Jane and Loann. Jane married Gary Sommer. Gary Sommer died in 1984. Loann married George Kjeldseth in 1968.