

SITE INFORMATION

*SURVEY DATE: February 3, 2012

*SURVEYOR: Jim Stone

*ADDRESS: <u>31176 471st Ave.</u>

*COUNTY: Union

*CITY: Burbank

LOCATION DESCRIPTION: <u>SD Highway 50 east of Vermillion to I 29, turn left (North) about 4-1/2</u> miles to SD highway 48 exit, turn right (East) ½ mile, turn (North) on 471st Ave, about 1-1/3 miles on the right (East) side.

LEGAL DESCRIPTION: <u>W 1/2 of SW 1/4, Section 17, Township 93N, Range 50</u>

*QUARTER 1:	SW 1/4					OWNER NAME: Elizabeth Merrigan											
*QUARTER 2:						OWNEF		SS: <u>31176 471st Ave</u>									
*TOWNSHIP:	Spink					0	OWNER CITY: Burbank										
	50								South Dakota								
*SECTION:	17					(OWNER	ZIP:	57010								
ACRES:	80																
OWNER CODE 1:	Ρ)															
OWNER CODE 2:	F	S	L	Ρ													
OWNER CODE 3:	F	S	L	Ρ													
HISTORIC SIGN		`Δ Ν	CF														
*DOE:					REGISTER NAME:												
*DOE DATE:					MULTIPLE PROPERTY NAME:												
REASON INELIGIB	LE:																
NOMINATION STATUS:						S	SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:						S	SIGNIF	ICANC	ELE	EVEL	. 2:	Ν	S	L			
REFERENCE	E NU	MB	ER:														
HISTORIC DISTRIC				-			C	RITE	RIA 1:	Α	В	С	D				
	P	ERIC)D:				C	RITE	RIA 2:	Α	В	С	D				
							C	RITE	RIA 3:	Α	В	С	D				
							C	RITE	RIA 4:	Α	В	С	D				
SIGNIFICANCE NOTES: Barn is in excellent condition.																	
-																	



STRUCTURE DETAILS			
SHPO ID:	17 CL 00000581	_	
*PROPERTY NAME:	Edward Merrigan barn		
OTHER NAME:			
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete
			Steel roofing over
CURRENT SUBFUNCTION:		ROOF MATERIAL:	Cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gambrel roof
OCCUPIED:	Yes	TYPE:	Livestock barn
	Yes -with permission from Liz		2x6 w/ sheathing & ½"x6´cedar lap
ACCESSIBLE:	Merrigan	WALLS:	siding
STORIES:	2 5	SIGNIFICANT PERSON: <u>Edwa</u>	rd Merrigan
*DATE OF CONSTRUCTION:	<u>1916</u> CU	LTURAL AFFILIATION:Iris	sh

ALTERED/MOVED NOTES: Original site. Steel roofing over the cedar shingles. Concrete floor poured over existing concrete floor. Horse stalls and milk cow stanchions have been removed. Sliding doors on the East and West ends have been replaced with two 8'x7' steel overhead doors. 8'x16' milk room has been added on the South side on the SW corner. Deck has been added on the West side which is the same level as the hayloft floor with stairs down to the ground level to the South.

INTERIOR NOTES: <u>Two rows 6x6 posts with 6x6 beams. 2x10 floor joists for hayloft floor. Two</u> 10'x10'x 14'8" high granaries on NW corner. These go through the hayloft floor up into the hayloft.

OTHER NOTES: 2x6 stud walls 14'8" high with horizontal sheathing on all four walls. ½"x6" cedar lap Siding. 9x12 four light windows. One metal cupola on roof. Roof is braced with double 2x6 from the hip down to the floor in 3 equal spaced places on each side in hayloft. 2x6 bracing from top of wall in hayloft out and down to the hayloft floor and to the posts and beams below.


*PHYSICAL NOTES: Barn is in excellent condition. It has been very well maintained.

*UTM ZONE:

*RESTRICTED: Y or N


* = REQUIRED FIELD





1





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 February 3, 2012
 PHOTO NUMBER:
 1







PHOTOGRAPHER:Jim StoneDATE OF PHOTO:February 3, 2012

ROLL NUMBER: PHOTO NUMBER: 3 CAMERA DIRECTION: Looking NW, SE corner



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 February 3, 2012
 PHOTO NUMBER:
 4

 CAMERA DIRECTION:
 First floor, looking East





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone February 3, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, CAMERA DIRECTION: granaries in NW corner


5



Jim Stone **ROLL NUMBER: PHOTOGRAPHER:** February 3, 2012 6 DATE OF PHOTO: PHOTO NUMBER:

Hayloft, looking West, CAMERA DIRECTION: note lower roof bracing










PHOTOGRAPHER:Jim StoneDATE OF PHOTO:February 3, 2012

ROLL NUMBER: _____ PHOTO NUMBER: ______ H

Hayloft, looking West, CAMERA DIRECTION: framing at the peak

9



* = REQUIRED FIELD

SOUTH

DAKOTA STATE

HISTORICAL SOCIETY



HISTORY

The Following Is From Liz Merrigan

Grandfather – Edward Merrigan bought this farm (a homestead claim) in 1892 from Anders Anderson who homesteaded here. Edward Merrigan built this barn in 1916. His son John Earl Merrigan helped to build the barn.

John Earl Merrigan aka Earl Merrigan was Elizabeth Merrigan's father.

Earl Merrigan removed the horse stalls about 1954 and added stanchions to enlarge his dairy. They only milked 3 to 4 cows before. He also added the milk room on the SW corner.