

SITE INFORMATION									
*SURVEY DATE:	August 4, 2011	*ADDRESS:			31	551 \$	S. D.	Hwy 1	Э
*SURVEYOR:	Jim Stone								
									,
LOCATION DESCRIPTION: Fro	om S. D. Hwy 50 and S	6. D. Hwy 19 1 ½	² miles No	rth on	the	left s	ide o	of	
Hwy 19									
LEGAL DESCRIPTION: NE ¼ o	of SW1/4, except Lot I	1-2, Section 2-9	2-52, Verm	illion	Tow	nshij	D		
		,	,						
*QUARTER 1: SW 1/4		WNER NAME:							
*QUARTER 2:		ER ADDRESS:			y 19				
*TOWNSHIP: <u>Vermillion tv</u>		OWNER CITY:							
*RANGE: <u>52 west</u>		WNER STATE:							
*SECTION: 2		OWNER ZIP:	57069						
ACRES: <u>37.38</u>		QUAD NAME:							
OWNER CODE 1: P									
OWNER CODE 3: F S L	Р								
HISTORIC SIGNIFICANCE									
*DOE:		REGISTER NA	ME						
*DOE DATE:		MULTIPLE PR		JAMF					
				,	· _				
			САТ	EGO	RY:				
NOMINATION STATUS:		SIGNI	FICANCE I	EVEL	. 1:	Ν	S	L	
DATE LISTED:		SIGNI	FICANCE I	EVEL	_ 2:	Ν	S	L	
REFERENCE NUMBER:									
HISTORIC DISTRICT RATING:		CRITE	ERIA 1: A	В	С	D			
PERIOD:		CRITE	ERIA 2: A	В	С	D			
_		CRITE	ERIA 3: A	В	С	D			
		CRITE	ERIA 4: A	В	С	D			

SIGNIFICANCE NOTES:Barn is in very good condition, has lean to built on West side (possiblybuilt with original barn), lean to on the north (built later) and lean to on East (most recent). Walls androof are covered with steel roofing.The gothic windows on the South were added recently for light.Barn is balloon framed with heavy posts and beams and beam bracing in hayloft.



STRUCTURE DETAILS

SHPO ID:	2 CL 0000057	<u>'1</u>	
*PROPERTY NAME:	Martin Weeks Jr. bar	n	
OTHER NAME:			
			Native stone, lime
CURRENT FUNCTION:	Shop and storage	FOUNDATION:	and sand mortar
	Herb drying and herb		Steel over cedar
CURRENT SUBFUNCTION:	storage	ROOF MATERIAL:	shingles
HISTORIC FUNCTION:	Agriculture	ROOF SHAPE:	Gable
	Livestock and		Balloon framing with heavy post and heavy
HISTORIC SUBFUNCTION:	agriculture	STRUCTURAL SYSTEM:	beam bracing
-		STYLE:	Bank bqrn
OCCUPIED:	YES	TYPE:	Livestock barn
ACCESSIBLE:	YES	WALLS:	2 x 6 purlins, 1x12 vertical siding, ½" x 6" cedar siding & ptd. steel roofing
STORIES:	3	SIGNIFICANT PERSON:	Egbert L. Collar
*DATE OF CONSTRUCTION:	1880's	CULTURAL AFFILIATION:	English

ALTERED/MOVED NOTES: Original site. Walls and roof have been covered with steel roofing. Gothic windows have been added to the South recently. 18' x 51' lean-to added on the North side later. 12' x 32' lean-to added on the East side more recent.

INTERIOR NOTES: <u>Unique balloon construction with 6 x 6 posts and 6x 6 beams in basement, (beams</u> run North and South). 6 x 6 posts and 6 x 6 beams on the first floor, (beams run East and West).

All of the posts line up and the 6 x 6 beam bracing in the hay mow rest on the tops of the posts.

Floor joists are 2 x 6 rough sawn cottonwood.

OTHER NOTES: <u>Walls and rafters are 2 x 6 rough sawn cottonwood</u>. Wall and roof sheathing are $\frac{3}{4}$ " x 12" rough sawn cottonwood. Siding is cedar lap and cedar shingles on the roof.

Barn has a 4x4 track in the peak. There is a special trolley with two wheels on each side that rolls on the 4x4 track to move hay up and into the hayloft.

*PHYSICAL NOTES: Barn is in very good condition.


*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				


* = REQUIRED FIELD



SKETCH MAP

SKETCH MAP






PHOTOGRAPHS

* = REQUIRED FIELD









PHOTOGRAPHER: Jim Stone DATE OF PHOTO: August 4, 2011

ROLL NUMBER: PHOTO NUMBER:

1 Looking Southwest, CAMERA DIRECTION: Northeast corner of barn



PHOTOGRAPHER: Jim Stone **ROLL NUMBER:** August 4, 2011 PHOTO NUMBER: 2 DATE OF PHOTO: Looking Southeast,

CAMERA DIRECTION: Northwest corner of barn





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	August 4, 2011	PHOTO NUMBER:	3
			Looking northeast,


CAMERA DIRECTION: barn

Looking northeast, Southwest corner of barn



PHOTOGRAPHER:	Jim Stone		
DATE OF PHOTO:	August 4, 2011		

ROLL NUMBER:	
PHOTO NUMBER:	
	In bas
CAMERA DIRECTION:	horse







PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	August 4, 2011	PHOTO NUMBER:	5
		CAMERA DIRECTION:	First floor, looking south




PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	August 4, 2011	PHOTO NUMBER:	6
_		CAMERA DIRECTION:	Hayloft, looking NE





7
Hayloft, looking north





9



History

This SW ¼ of Section 2, Vermillion Township, Clay County was homesteaded by Brindle Oleson.

The 1894, 1901, 1912 and 1924 Clay County Atlas lists Egbert L. Collar as the owner.

The 1937 Clay County Atlas lists H. Lee as the owner and W. H. Hinchliff as the operator (renter).

The 1948 and 1956 Clay County Atlas lists Martin Weeks Jr. as the owner.

This barn was built when Egbert L. Collar lived on this farm. He also owned the land in Vermillion where Prentis Park is located today. He had a large fruit orchard on the property. He sold fruit and had customers who would pick their own fruit and save. Families canned a lot of fruit and vegetables at that time.

In 1923 Egbert L. Collar and his wife sold the property to Lee Prentis for \$7000.00 with \$500.00 down. Mr. Lee Prentis then deeded the land to the City of Vermillion for a city park. The City of Vermillion would have title to the land as long as they developed and maintained a public park on the property.