

### SITE INFORMATION


*SURVEY DA	TE: Aug. 14, 20	*ADDRESS: 31704 Bergen Ave.									
*SURVEYOR: Jim Stone			*COUNTY:	Clay							
			- *CITY:	*CITY: Meckling							
LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 West about 1 mile to South											
Dakota highway 19, turn left (South) about 300' to Timber Road, turn right (West) about 6 miles to											
Bergen Ave., turn right (North) about 1/4 <sup>th</sup> mile, on the right (East) side.											
LEGAL DESCRIPTION: Lot J, NW ¼, NE ¼, 15 – 92 – 53 Norway Twp.											
LEGAL DEGOKII TIC		74, INC 74, 13 – 32	2 – 33 Norway II								
*QUARTER 1: <u>NE 1/4</u>			OWNER NAME: Glen Gilbertson								
*QUARTER 2:	*QUARTER 2: OV				: 31704 Bergen Ave.						
*TOWNSHIP: _	Norway	<u> </u>	OWNER CITY:	Meckling							
*RANGE: _	53		OWNER STATE:	South Dakota							
*SECTION: _	15	<u> </u>	OWNER ZIP:	57069							
ACRES: _	3.8	_	QUAD NAME:								
OWNER CODE 1:	P										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNI	FICANCE										
		DECICIED NAME									
*DOE:			REGISTER NAME: MULTIPLE PROPERTY NAME:								
*DOE DAT	MULTIPLE PR	OPERI	Y NA	\IVI ⊑:	_						
REASON INELIGIBL	-E:										
				C	ΔTF	GOF	γ.				
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L							_	
	NUMBER:		0.0							_	
HISTORIC DISTRIC	·	or NC	CRITE	ERIA 1:	Α	В	С	D			
	PERIOD:			ERIA 2:							
				ERIA 3:							
			CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOTES:											

#### STRUCTURE DETAILS



SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
<b>CURRENT FUNCTION:</b>	Machinery storage	FOUNDATION								
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Some steel over cedar shingles							
HISTORIC FUNCTION:	Western Feeder barn	ROOF SHAPE								
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM								
motoric sobi one flore.	Tiay Storage	SINOCIONAL SISILI	Western feeder							
		STYLE	: barn							
OCCUPIED:	Yes	TYPE	: Livestock barn							
	Yes with									
ACCESSIBLE:	permission	S: _2x6, 1x 8" shiplap								
0700150	4									
STORIES:	1	SIGNIFICANT PERSON:	Elling Myron							
*DATE OF CONSTRUCTION:	1880 to 1890 C	CULTURAL AFFILIATION:	Norwegian							
ALTERER/MOVER NOTES	M 1 1 1		Jaffan - Laan ta an							
<del>-</del>		, reason poured concrete foun								
		ean-to on the South was adde								
built from rough sawn cottonwood. 30' x 60' lean-to built, between 1955 to 1965 on the North. Wooden										
cupola is gone. Roof is covered with steel over cedar shingles. Barn had a hayloft floor about 8' above										
ground level before it was converted into a Western feeder barn. All evidence of any stalls or stanchions are gone. Windows are gone, except for two on the South side.										
are gener rimaeme are gene	, except for the on the									
INTERIOR NOTES: Other th	an being converted into	o a Western Feeder barn and th	ne feed rack on the							
South wall, there is not any the	ning to report. Main ba	rn has 4x6 sills and lean-to has	s (2) 2x6's for a							
sills, all rough sawn cottonwo	ood.									
OTHER NOTES: Windows w	ere 9"x12" four light a	nd 9"x12" four light over 9"x12	" four light on the							
East and West gable ends. W	alls are 2x6 rough saw	n cottonwood with 1x8 shiplap	for siding, except							
the South wall which has been changed to double 2x6, 4' O. C. and is open except for the feed rack										
at the bottom. West sliding door has been enclosed and the sliding door moved to the lean-to on the North. Rafters are 2x4 rough sawn cottonwood with 1x6 rough sawn cottonwood bracing.										
		roof is not leaking yet. Needs								
doors and windows.	<u> </u>	Too is not loaning you moods	oomo ropano on							
*IITM 70NE:		*RESTRICTED: Y	or N							
*UTM ZONE: *UTM EASTING:		NEGINIOIED.	Oi II							
*HTM NORTHING:										









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 17, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: Aug. 17, 2012 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner



///



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 17, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 17, 2012 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone

DATE OF PHOTO: Aug. 17, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

South lean-to, looking West, feed rack on North

CAMERA DIRECTION: wall



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 17, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Main barn, looking West, 2x6 wall, 1x8 shiplap, 2x4 rafters and 1x6

CAMERA DIRECTION: bracing





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone Aug. 17, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Main barn, looking West, double 2x6 studs 4' O. C.

CAMERA DIRECTION: and 2x4 rafters



PHOTOGRAPHER: DATE OF PHOTO: 1880's to 1890's

ROLL NUMBER:


PHOTO NUMBER: 8
CAMERA DIRECTION: Original barn





PHOTOGRAPHER: ? ROLL NUMBER: 9
DATE OF PHOTO: 1890's to 1900's PHOTO NUMBER: 9
CAMERA DIRECTION: Barn after remodeling







#### **HISTORY**

This farm, located in the NW ¼ of the NE ¼, Section 15, Norway Township, Clay County was homesteaded by Elling Olson.

The 1894 Clay County Atlas lists S. S. Myron as the owner.

The 1901 Clay County Atlas lists Elling M. Myron as the owner.

The 1912 Clay County Atlas lists J. G. Iverson as the owner.

The 1924 Clay County Atlas lists Elling M. Myron as the owner.

The 1937 Clay County Atlas lists E. & J. Iverson as the owners.

The 1948 Clay County Atlas lists Arthur Iverson as the owners.

The 1956 Clay County Atlas lists D. E. Myron as the owners.

### The Following Information Is Furnished by Milo Gilbertson

Elling Myron lived on this farm at the time the barn was built. Milo Gilbertson bought this farm from Don Myron, a son of Elling Myron. Milo and Sally Gilbertson lived here for most of their life. They farmed and raised a lot of hogs.

Milo said that a Nels Peterson immigrated from Sweden in 1914. He was a carpenter and built kitchen cabinets for Elling Myron in 1917 in the house that still stands today. Glen Gilbertson the son of Milo and Sally Gilbertson bought the farmstead and lives in the house.

Nels Peterson is believed to have built the barn about 1920. He built other barns and did carpentry work in the area. He just disappeared from the area. He died in 1943 and had requested to be buried at the Norwegian Cemetery. This would be the Meckling Cemetery.

Nels Peterson was married in Sweden, but did not bring his family to America. He was going to make his fortune and then send for his family. His wife finally divorced Nels, but stayed in Sweden. Milo did not know why he did not send for his family after he established his life in America.