

SITE INFORMATION

*SURVEY DATE: <u>March 9, 2012</u> *SURVEYOR: Jim Stone

ADDRESS:	45255 304 th Street
*COUNTY:	Clav

*CITY: Volin

LOCATION DESCRIPTION:From the intersection of South Dakota Highway 50 bi-pass and SouthDakota Highway 19, 11 miles North to 306th Street, turn left (West), 10 miles to 452nd Ave, turn right2 miles to 304th Street, turn right (East) about ¼ miles on the right (South) side

LEGAL DESCRIPTION: <u>W ½</u>, NE ¼, 7 – 94 – 53, Bethel Twp.

								_						
	NE 1/4	•				NAME:	-				ods			
*QUARTER 2:					OWNER AD	DRESS:	45255	304 ^t	^h Str	eet				
*TOWNSHIP: E	<u>3ethe</u>				OWNE	R CITY:	Volin							
*RANGE:	53W				OWNER	STATE:	South	Dak	ota					
*SECTION:	7				OWN	ER ZIP:	57072							
ACRES:	79.19)				NAME:								
OWNER CODE 1:	Р													
OWNER CODE 2: F	S	L	Р											
OWNER CODE 3: F	S	L	Р											
HISTORIC SIGNIF		ICE												
*DOE	::				REGI	STER NA	AME:							
								Y NA	ME:	1				
REASON INELIGIBLE														
							С	ATE	GOF	RY:				
NOMINATION	STAT	US:				SIGNI	FICANC	ELE	VEL	. 1:	Ν	S	L	
						SIGNI	FICANC	ELE	VEL	. 2:	Ν	S	L	
REFERENCE N														
HISTORIC DISTRICT			-			CRITE	ERIA 1:	Α	в	С	D			
	PERIC	OD:				CRITE	ERIA 2:	Α	в	С	D			
						CRITE	ERIA 3:	Α	в	С	D			
						CRITE	ERIA 4:	Α	в	С	D			
SIGNIFICANCE NOTE	S:	Land	d ma	ortgage was s	atisfied fror	n Americ	an Free	hold	Lai	nd N	lorta	age (Co.	
London, England 189														



STRUCTURE DETAILS			
SHPO ID:			
*PROPERTY NAME:	Elmore Gronlund ba	rn	
OTHER NAME:			
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete
			Asphalt shingles
CURRENT SUBFUNCTION:		ROOF MATERIAL:	over wood shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gothic round
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gothic round barn
OCCUPIED:	Yes	TYPE:	Livestock
			2x6 & 2x8 , ¾" x
	Yes with		12" sheathing,
ACCESSIBLE:	permission	WALLS:	¹ / ₂ "x8" lap siding
STORIES:	2	SIGNIFICANT PERSON: Elmor	e Gronlund
*DATE OF CONSTRUCTION:	1935 - 1936	CULTURAL AFFILIATION: S	wedish

ALTERED/MOVED NOTES: <u>Original site. Re-shingled with asphalt shingles and painted. The 9"x12"</u> four light windows have been replaced with 9"x12" vinyl four light windows.

INTERIOR NOTES: <u>6x6 posts and 6x6 beams. 2x10 floor joists for hayloft floor. 2x6 stud walls 7'-3"</u>						
on East and West sides with 12" concrete foundation. 2x8 stud walls 18' high on gable end walls with						
³ / ₄ "x 10" horizontal sheathing and ¹ / ₂ "x8" cedar lap siding on all four walls. 2x6 stud walls on top of the						
2x8 gable ends up to rafters.						
OTHER NOTES: Rafters are round gothic built out of ³ / ₄ " x 1-1/2" cedar, 6 plies thick. They appear to						
be factory assembled. ³ /4" x 10" sheathing on roof with cedar shingles and covered with asphalt						
shingles. Two ¾" x 1-1/2"cedar, 7 plies thick round gothic rafters are mounted on each gable end, about						
8' O. C. in the center of the wall. These arches are fastened to the 6x6 beam under the floor. They curve						
into the hayloft gable end wall and meet the wall about $\frac{1}{2}$ way up and then curve out and fastened to the						

into the hayloft gable end wall and meet the wall about ¹/₂ way up and then curve out and fastened to the second rafter from the gable end. There are several braces back to the gable stud wall.


*PHYSICAL NOTES:	All of the windows are 9" x 12" four light windows. Metal cupola in the center of
roof ridge. Barn is in	good condition. With the curved arches braces on the gable end walls this barn is
very well braced.	


*UTM ZONE:	*RESTRICTED:	Υ	or	Ν
*UTM EASTING:				
*UTM NORTHING:				

* = REQUIRED FIELD



SKETCH MAP









* = REQUIRED FIELD









PHOTOGRAPHER: **Jim Stone** DATE OF PHOTO: March 9, 2012

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION: horse stalls

5 First floor, looking West



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	March 9, 2012	PHOTO NUMBER:	6
_			First floor, looking North

h, CAMERA DIRECTION: milk cow stanchions

March 9, 2012




7 Lean-to Note curve of



PHOTO NUMBER:

PHOTOGRAPHER: ____ DATE OF PHOTO:







PHOTOGRAPHER: Jim Stone DATE OF PHOTO: March 9, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, note 3/4"x 1-1/2", 7 ply arch rafter bracing CAMERA DIRECTION: North wall

9



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:
DATE OF PHOTO:	March 9, 2012	PHOTO NUMBER:

10 Hayloft, note top of CAMERA DIRECTION: curved arch bracing





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	March 9, 2012	PHOTO NUMBER:	11

Hayloft, note bottom of camera DIRECTION:






PHOTOGRAPHER:	?	ROLL NUMBER:	
DATE OF PHOTO:	1990's	PHOTO NUMBER:	12
		CAMERA DIRECTION:	Looking SW, NE corner



PHOTOGRAPHER:	?	ROLL NUMBER:	
DATE OF PHOTO:	1990's	PHOTO NUMBER:	13
_		CAMERA DIRECTION:	Looking SE, NW corner





11



HISTORY

This farm located in the W1/2 of the NE ¼ of Section 7, Bethel Township, Clay County was homesteaded by Daniel Clough.

The 1894 Clay County Atlas lists Peter Finnegan as the owner.

The 1910 and 1912 Clay County Atlas lists H. C. Hanson as the owner.

The 1924 Clay County Atlas lists Anna D. M. Hanson as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists Elmore A. Gronlund as the owner.

Ray and Ramona have the abstract on this farm dating back to homesteading time.

An interesting fact is, in 1898 the farm was cleared by satisfaction of mortgage by American Freehold Land Mortgage Co., London, England.

Farm was owned by a family by the name of Moore's

Elmore Gronlund bought this farm in 1934 from the Moore's. He built the barn in 1935 and 1936.

Bernard and Marjorie Doohen bought the farm in 1979.

Ray and Ramona Woods bought the farm from Marjorie Doohen in 1996.