

SITE INFORMATION


*SURVEY DATE: October 15, 2	15, 2012 *ADDRESS: 45272 312 th Street									
*SURVEYOR: Jim Stone	*COUNTY:	Clay								
·	*CITY:	*CITY: Meckling								
LOCATION DESCRIPTION: From the West edge of Vermillion, South Dakota Highway 50, West to										
Meckling, 4-1/2 miles West to 453 rd Ave, turn left (South), about ¾ mile to 312 th Street, turn right (West)										
about ¼ mile on the right (North) side.										
LEGAL DESCRIPTION: Hanson tract 1, In S 1/2, SE 1/4, 18 – 93 – 53 Meckling Twp.										
	1, 0 1/2, 02 /4, 10 00 00	g	p.							
*QUARTER 1: SE 1/4	OWNER NAME:	Michael Dean Clark								
*QUARTER 2:	OWNER ADDRESS:	2975 Cass Ave.								
*TOWNSHIP: Meckling	OWNER CITY:	Salix								
*RANGE:53	OWNER STATE:	Iowa								
*SECTION:18	OWNER ZIP:	51052								
ACRES: 3.19	QUAD NAME:	i:								
OWNER CODE 1: P										
OWNER CODE 2:										
OWNER CODE 3:										
HISTORIC SIGNIFICANCE										
*DOE:	MULTIPLE DD	REGISTER NAME:								
*DOE DATE: MULTIPLE PROPERTY NAME:										
REASON INELIGIBLE:	 -									
		CATE	EGOR'	γ.						
NOMINATION STATUS:				_	N	S	L			
DATE LISTED:					S	L				
REFERENCE NUMBER:										
HISTORIC DISTRICT RATING: C or	NC CRITE	RIA 1: A	В	С	D					
PERIOD:		RIA 2: A								
		RIA 3: A								
		RIA 4: A								
SIGNIFICANCE NOTES:										

STRUCTURE DETAILS



SHPO ID:		_						
*PROPERTY NAME:								
OTHER NAME:								
CURRENT FUNCTION:	Horse barn	FOUNDATION:	Poured concrete foundation					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Cedar shingles					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel					
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing					
		STYLE:	Gambrel roof barn					
OCCUPIED:	Yes	TYPE:	Livestock barn					
ACCESSIBLE:	Yes with permission	WALLS:	2x6 stud with 1x8 sheathing & ½"x6"cedar lap siding.					
	•							
STORIES:	2	SIGNIFICANT PERSON:E	ric Lunde					
*DATE OF CONSTRUCTION:	1890 to 1900 CU	LTURAL AFFILIATION:	?					
ALTERED/MOVED NOTES: Original site. Milk cow stanchions have been removed. One double								
horse stall removed.								
INTERIOR NOTES: Has three	e rows of 6x6 posts with	4x6 for beams. 2x10 floor jois	ts. Granary and					
three double horse stalls still in place. One double horse stall and the milk cow stanchions have been								
removed.	•							
OTHER NOTES: 2x6 stud w	alls with 1x8 sheathing a	nd ½"x6" cedar lap siding. Rat	fters are 2x6 with					
2x6 bracing 0n each rafter at the hip. Two 2x6 for a plate at the hip. 2x6 bracing 6' O.C. from center of								
lower rafters down to the floor and from the top of wall down to the floor. Two short 1x10's bracing at								
hip and at bottom of lower ra	fter and top of the wall.	Very ornate metal cupola. 9"x1 of barn to the height of walls a	2" four light					
*PHYSICAL NOTES: Barn is in fair condition. Needs roofing now. Some siding is missing at the								
bottom of walls. Doors and windows need repair. Concrete foundation is crumbling in a few places.								
*UTM ZONE:		*RESTRICTED: Y o	or N					
*UTM EASTING:			-					
*UTM NORTHING:								









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 15, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 15, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, stalls of some

CAMERA DIRECTION: type with feed bunks



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: South, 4' feed alley

First floor, looking





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, CAMERA DIRECTION: double horse stalls



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft. Looking North, lower rafter bracing 6'

CAMERA DIRECTION: O.C.





PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: October 15, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, upper rafter bracing at

CAMERA DIRECTION: hip. 2' O.C.







HISTORY

Nathan Worley homesteaded this land. He actually homesteaded the S $\frac{1}{2}$ of the SE $\frac{1}{4}$ and the S1/2 of the SW1/4 all in Section 18, Meckling Township.

Eric Lunde bought this farm in 1890. The barn was built between 1890 and 1900.

The 1901 Clay County Atlas lists Eric Lunde as the land owner.

The 1912 Clay County Atlas lists the owner as Eric Lunde Estate.

The 1924, 1937, 1948 and 1956 Clay County Atlas lists Ingrid Lunde (Mrs. Eric Lunde) as the owner. The 1937 Atlas lists A. Lunde as the operator (renter).