

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SITE INFORMATION

*SURVEY DATE: January 15, 2013 *ADDRESS: 30361 Greenfield Road
*SURVEYOR: Jim Stone *COUNTY: Clay
*CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, East 2 miles to Greenfield Road, Turn left (North) 14 miles, on left (West) side, vacated place

LEGAL DESCRIPTION: SE¼, 3 – 94 – 51 Garfield Twp.

*QUARTER 1: SE 1/4
*QUARTER 2: _____
*TOWNSHIP: Garfield
*RANGE: 51
*SECTION: 3
ACRES: 156.47

OWNER NAME: L'nora Bylander
OWNER ADDRESS: 114 N. Willow Street
OWNER CITY: Vermillion
OWNER STATE: South Dakota
OWNER ZIP: 57069
QUAD NAME: _____

OWNER CODE 1: P
OWNER CODE 2: _____
OWNER CODE 3: _____

HISTORIC SIGNIFICANCE

*DOE: _____
*DOE DATE: _____
REASON INELIGIBLE: _____

REGISTER NAME: _____
MULTIPLE PROPERTY NAME: _____

NOMINATION STATUS: _____
DATE LISTED: _____
REFERENCE NUMBER: _____
HISTORIC DISTRICT RATING: C or NC
PERIOD: _____

CATEGORY: _____
SIGNIFICANCE LEVEL 1: N S L
SIGNIFICANCE LEVEL 2: N S L
CRITERIA 1: A B C D
CRITERIA 2: A B C D
CRITERIA 3: A B C D
CRITERIA 4: A B C D

SIGNIFICANCE NOTES: _____

STRUCTURE DETAILS

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
 *PROPERTY NAME: _____
 OTHER NAME: _____

CURRENT FUNCTION:	<u>Storage</u>	FOUNDATION:	<u>Poured concrete foundation</u>
CURRENT SUBFUNCTION:	<u>Storage</u>	ROOF MATERIAL:	<u>Galv. steel roofing over cedar shingles</u>
HISTORIC FUNCTION:	<u>Livestock barn</u>	ROOF SHAPE:	<u>Gable</u>
HISTORIC SUBFUNCTION:	<u>Hay and grain storage</u>	STRUCTURAL SYSTEM:	<u>Balloon framing Western feeder barn</u>
OCCUPIED:	<u>No</u>	STYLE:	<u>Livestock barn</u>
ACCESSIBLE:	<u>Yes with permission</u>	TYPE:	<u>2x4 studs with 1x6 #106 drop siding</u>
WALLS:			
STORIES:	<u>2</u>	SIGNIFICANT PERSON:	<u>Erick Messler</u>
*DATE OF CONSTRUCTION:	<u>1900 to 1920</u>	CULTURAL AFFILIATION:	<u>Swedish</u>

ALTERED/MOVED NOTES: Original site. Roof covered with 26" galvanized corrugated steel roofing. 16'x28' lean-to added on the West side and 12' x 28' lean-to added on the East side.

INTERIOR NOTES: Has two rows 6" round posts, with (2) 2x6's for a beam on the West and (1) 2x6 for a beam on the East. One row of 6" posts and a 2x4 to support the center of the rafters in the East lean-to. 2x6 floor joists for hayloft floor. Two rows of 2x4 posts with 2x4 beam to support the center of rafters in hayloft.

OTHER NOTES: 2x4 stud walls with 1x6 #106 drop siding in the center of the barn. 2x6 studs and 1x6 #106 drop siding in the West addition. 6" round posts, 3' 6" O. C. and 1x6 106 drop siding in the East lean-to. Rafters are 2x4's except the West lean-to where they are 2x6's. No windows. Five single horse stalls, three double cattle stalls and granary in the NW corner are still in place. Granary in hayloft is still in place in the NW corner. All of the 2x4 studs and rafters, 2x6 studs and rafters and beams are rough sawn cottonwood.

*PHYSICAL NOTES: Barn is in very poor condition.

*UTM ZONE: _____ *RESTRICTED: Y or N
 *UTM EASTING: _____
 *UTM NORTHING: _____

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, center area,
looking South, horse
stalls on East wall.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 6

CAMERA DIRECTION: First floor, center area,
looking North, Cow stalls
and granary on West
wall.

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 7

First floor, East lean-to, looking SE, no foundation, posts 3'-6" O. C. and siding for walls.

CAMERA DIRECTION: _____



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: January 15, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 8

Hayloft, looking South and up into hayloft, 2x4 posts and 2x4 beam supporting rafters, granary in NW corner of hayloft

CAMERA DIRECTION: _____

* = REQUIRED FIELD

HISTORY

This farm located in the SE ¼ of Section 3, Garfield Township, Clay County was homesteaded by Erick Mepler.

The 1894, 1901, and 1912 Clay County Atlas lists Erick Messler as the owner.

The 1924 Clay County Atlas lists Oscar Messler as the owner.

The 1937, 1948, and 1956 Clay County Atlas lists Dan Bylander as the owner.

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

