


```SITE INFORMA	<b>NOITA</b>											
*SURVEY DA	TE:	May 16, 2	2013	*ADDRESS	S: 31450 452nd Ave.							
*SURVEY	е	*COUNTY	Clay									
				*CITY	Beres	sforc	i					
LOCATION DESCRI	LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 bi-pass and University Road,											
North 19 miles to 299th Street, turn left, (West) about ½ mile, you will need to walk about ½ mile North												
to vacated farmstead.												
LEGAL DESCRIPTION	ON: <u>W 1</u>	⁄₂, SE ¼, 7	7-95-52 Gle	nwood Twp.								
*QUARTER 1:	SE 1/4			OWNER NAME: Nada Landeen								
*QUARTER 2:					3904 E. 15 th							
*TOWNSHIP:	Glenwo	od		OWNER CITY:								
*RANGE:	51			OWNER STATE:	South	South Dakota						
*SECTION:	7			OWNER ZIP:	57103							
ACRES:	79.69			QUAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNI	FICANC	E										
	_			DEGICTED N	A B 4 🗁							
*DOE:				REGISTER NAME: MULTIPLE PROPERTY NAME:								
*DOE DATE: REASON INELIGIBLE:				WIOLITPLE	KOPEKI	T IN	AIVI Œ.					
REASON INELIGIBI	-E. <u> </u>											
					C	ATE	GOF	RY:				
NOMINATION STATUS:				SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:				SIGNI	FICANC	ELE	EVEL	2:	N	S	L	
REFERENCE	NUMBER											
HISTORIC DISTRIC	T RATING	: C or	NC	CRITI	ERIA 1:	Α	В	С	D			
	PERIOD	):		CRITI	ERIA 2:	Α	В	С	D			
				CRITI	ERIA 3:	Α	В	С	D			
				CRITI	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOT	ES:											

#### STRUCTURE DETAILS



SHPO ID:		<u></u>							
*PROPERTY NAME:									
OTHER NAME:									
<b>CURRENT FUNCTION:</b>	Vacant	FOUNDATION:	Poured concrete						
<b>CURRENT SUBFUNCTION:</b>	Storage	ROOF MATERIAL:	Cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gambrel						
HISTORIC SUBFUNCTION:	Hay and grain stora	ge STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Bank barn						
OCCUPIED:	Yes	TYPE:	Livestock barn						
			6"x 8' concrete & 2x6						
	Yes with		studs, 1x8 diagonal						
ACCESSIBLE:	permission	WALLS:	sheathing, ½"x6" cedar lap siding						
AGGEGGIBEE.	permission	WALLO.	ccdar lap slaing						
STORIES:	2	SIGNIFICANT PERSON:	Erick Norling						
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:	Swedish						
ALTERED/MOVED NOTES:	Original site. Horse	stalls have been removed, but one	complete stall is still						
ALTERED/MOVED NOTES: Original site. Horse stalls have been removed, but one complete stall is still on the West side.									
INTERIOR NOTES: Two row	s of 6x6 posts and 6x	6's for beams. Floor joists for the	hayloft floor are 2x8's.						
Three granaries on the West wall. These granaries are all 10' East to West, two are 8' North to South and									
the North granary is 14'. The	se granaries are 13' h	igh and extend into the hayloft 6'.							
OTHER NOTES: The East ar	nd North walls are 6"	x 8' poured concrete. The South a	nd West walls and						
above concrete walls on the l	East and North are 2x	6 stud walls, 1x8 diagonal sheathi	ng and ½"x 6" cedar						
lap siding. Rafters are 2x6's	with a 2x6x4' brace at	the hip and a 2x6 brace from top	of wall down to the						
floor 10' O. C. Barn had no	cupola. 10' x 11' dou	ble sliding doors at ground level i	nto hayloft.						
*PHYSICAL NOTES: Barn is	s in fair condition. A	section of the North concrete wall	has fell in.						
*UTM ZONE:		*RESTRICTED: Y o	r N						
*UTM EASTING:									
*UTM NORTHING:									









PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone May 16, 2013 ROLL NUMBER: PHOTO NUMBER:

1

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: ___ DATE OF PHOTO:

Jim Stone May 16, 2013 ROLL NUMBER: PHOTO NUMBER:

CAMERA DIR

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 16, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Basement, looking NW, only horse stall still in CAMERA DIRECTION: place on the West side.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 16, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Basement, looking NE, 6x6 posts, 6x6 beams, 2x8 joists, note section

CAMERA DIRECTION: of North wall that fell in.





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: May 16, 2013

**ROLL NUMBER:** PHOTO NUMBER:

Hayloft, looking NW, 2x6 rafters with 2x6 brace down to the floor, 10'

CAMERA DIRECTION: O.C.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 16, 2013


ROLL NUMBER:

**PHOTO NUMBER:** 

Hayloft, looking NW, 2x6 rafters with 2x6 brace 4'

CAMERA DIRECTION: <u>long at the hip.</u>





© Farm & Home Publishers, Ltd.

23

CLAY CO., SD



### **HISTORY**

This farm located in the SE ¼ of Section 7, Glenwood Township, Clay County was homesteaded by Erick Norling.

The 1894 and 1901 Clay County Atlas lists Erick Norling as the owner.

The 1912 Clay County Atlas lists Clara Norling as the owner.

The 1924 Clay County Atlas lists A. P. Engman as the owner.

The 1937 and 1948 Clay County Atlas lists Elmer Johnson as the owner.

The 1956 Clay County Atlas lists E. C. Landeen as the owner.

