


"SITE INFORMATION


*SURVEY DA	TE:A	pril 8, 2	014	*ADDRES	SS: <u>463</u> 1	46317 298 th Street						
*SURVEYOR: Jim Stone			ne	*COUNT	Y: Clay	Clay						
				*CIT	Y: Cen	Centerville						
LOCATION DESCR	IPTION: F	rom Vei	million, inte	rsection of Sou	th Dakota	a Hig	hway	/ 50 l	bi-pa	ss ar	nd	
South Dakota High					(East) ab	out	1-1/4	mile	s on	the	right	
(South) side, lane is	s just a traii	back in	to the farmst	ead.								
LEGAL DESCRIPTI	ON: W 1/2	NW 1/1	12 _05 _ 52	Piverside Two								
LLGAL DLGCKIF II	ON. <u>W /2,</u>	1444 1/4	, 12 –93 – 32	Kiverside i wp.	•							
				Gerald D. Benjamin & Jean Ann								
*QUARTER 1:				: Girard - Living Trust								
*QUARTER 2:			OV			32175 473rd Ave.						
*TOWNSHIP:		Riverside				Elk Point						
*RANGE:		52				South Dakota						
*SECTION:				OWNER ZII								
ACRES:	81.86			QUAD NAMI	E:							
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGN	IFICANCE											
*DOE:				REGISTER	NAME:							
*DOE DATE				MULTIPLE PROPERTY MAME								
DEASON INELIGIBLE:					PROPER	I I IN	AIVI L	• –				
KLASON INLLIGIB	LL											
						CATI	EGOI	RY:				
NOMINATIO		SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L									
REFERENCE	NUMBER:											
HISTORIC DISTRIC					ITERIA 1:	Α	В	С	D			
	PERIOD:			CR	ITERIA 2:	Α	В	С	D			
					ITERIA 3:							
				CR	ITERIA 4:	Α	В	С	D			
SIGNIFICANCE NO	TES:											



STRUCTURE DETAILS										
SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
• · · · · · · · · · · · · · · · · · · ·										
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete							
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:								
			Gable / partial hip							
LUCTORIO FUNCTIONI	I in a sta ala la ann	DOOF CHARE	roof with dormer to							
HISTORIC FUNCTION:	-	ROOF SHAPE:	North							
HISTORIC SUBFUNCTION:	Hay and grain storage									
		STYLE:								
OCCUPIED:	No	TYPE:								
			2x6 studs, 1x10							
ACCECCIDI E	Yes with	MALL C.	shiplap, ½"x 6"							
ACCESSIBLE:	permission	WALLS:	cedar lap siding							
STORIES:	. 2 S	SIGNIFICANT PERSON:	Frick Swedherg							
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	Swedish							
DATE OF CONSTRUCTION.	1910 10 1920	LIONAL AITILIATION.	OWCUISII							
ALTERED/MOVED NOTES: Original site.										
ALTEREDINIOVED NOTES.	Original Site.									
INTERIOR NOTES: Two row	vs of (3) nly 2x6 nosts 4	6 heams and 2x6 floor joists fo	or the havioft and							
INTERIOR NOTES: Two rows of (3) ply 2x6 posts, 4x6 beams and 2x6 floor joists for the hayloft and granaries floor. Flooring is diagonal. Two single and two double horse stalls and four double milk cow										
stanchions still in place in the basement.										
		"v6" coder lan ciding Chinlan	is harizontal on the							
OTHER NOTES: 2X6 stud walls with 1x10 shiplap, ½"x6" cedar lap siding. Shiplap is horizontal on the										
South wall and diagonal on the other three walls. Windows are 9" x 12" four light. Rafters are 2x6's. The West 20' of the first floor has two granaries. The center 20' of the first floor is the hayloft and the										
East 14' is two more granaries. North wall of the basement is 12" x 8' high poured concrete and the East										
side is 8' high for 12' and the	en stepped down to 4' hig	ment is 12" x 8" nign poured co ih and down to 2" high on the E st of the basement is 2x6 stud v	ast end of the South							
*PHYSICAL										
NOTES: Barn is	in very poor condition.	*RESTRICTED: Y o	r N							
*UTM EASTING:										
*UTM NORTHING:										










SKETCH MAP



PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 8, 2014 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 8, 2014 PHOTO NUMBER: CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April, 2014 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: April 8, 2014 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 8, 2014

ROLL NUMBER: PHOTO NUMBER:

Basement, looking NE at double milk cow stanchions on the North

CAMERA DIRECTION: wall at the East end.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 8, 2014

ROLL NUMBER: PHOTO NUMBER:

Basement, looking NW, horse stalls on the west

CAMERA DIRECTION: side, facing North.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 8, 2014

ROLL NUMBER: PHOTO NUMBER:

Basement. Looking North into a single horse

CAMERA DIRECTION: stall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 8, 2014

ROLL NUMBER: PHOTO NUMBER:

Basement, looking NE into a double horse stall,

CAMERA DIRECTION: note plank floor.





PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone April 8, 2014

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW into 20' x 20' hayloft

CAMERA DIRECTION: area.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone April 8, 2014


ROLL NUMBER: PHOTO NUMBER:

10

First floor, looking SE into two granaries on the

CAMERA DIRECTION: East side.





© Farm & Home Publishers, Ltd. 35 CLAY CO., SD



HISTORY

This farm located in the West ½ of the NW ¼ of Section 12, Riverside Township, Clay County was homesteaded by Sting Hansdaler.

The 1894 Clay County Atlas lists Christina Swedberg as the owner.

The 1901, 1912 and 1924 Clay County Atlas lists Erick Swedberg as the owner.

The 1937 Clay County Atlas lists Dorthy & Don Swedberg as the owners.

The 1948 and 1956 Clay County Atlas lists Don Swedberg as the owner.

