

"SITE INFORMA"	<u> </u>								
*SURVEY DAT	E: Decembe	er 16, 2013 *ADD	RESS:	31449 University Road					
*SURVEYO	-		OUNTY:						
				Vermillion	1				
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and									
University Road, North about 2-1/2 miles on the left (West) side.									
LEGAL DESCRIPTION: _Turner Tract 2, SE ¼, NE 1/4 & NE ¼, NE 1/4, 36 – 93 – 52 Spirit Mound Twp.									
*QUARTER 1:	NE 1⁄4	OWNER I	NAME:	Roger E. T	urner				
*QUARTER 2:		OWNER ADD	RESS:	ESS: 31449 University Road					
*TOWNSHIP:	Spirit Mound	OWNER	CITY:	Vermillion					
*RANGE:	52	OWNER S	TATE:	South Dakota					
*SECTION:	36	OWNE	R ZIP:	57069					
ACRES:	8.05	QUAD N	IAME:						
OWNER CODE 1:	P								
OWNER CODE 2:									
OWNER CODE 3:									
HISTORIC SIGNIF	ICANCE								
*DOE	REGIS	REGISTER NAME:							
*DOE DATE		MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE				_					
		CATEGORY:							
NOMINATION			_ SIGNIFICANCE LEVEL 1: N S L						
	LISTED:		SIGNII	FICANCE LE	VEL 2:	N	S	L	
	IUMBER:	NO.	ODITE	-DIA 4 A	D 0	_			
HISTORIC DISTRICT				RIA 1: A					
PERIOD:				RIA 2: A					
				RIA 3: A					
			CKITE	INIA 4. A	ьс	D			
SIGNIFICANCE NOTES:									


STRUCTURE DETAILS




SHPO ID:								
*PROPERTY NAME:								
OTHER NAME:								
			Native rock and					
CURRENT FUNCTION:	Vacant	FOUNDATION:	poured concrete					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Cedar shingles					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof					
LISTORIC SUBELINCTION.	Llav otorogo	STRUCTURAL SYSTEM.	Post & beam &					
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	balloon framing					
000110150			Western feeder barn					
OCCUPIED:	NO	IYPE:	Livestock barn 2x6 studs, 1x12					
			vertical siding, 1x6					
			#106 drop siding					
	Yes with		and 1x2"x6" cedar					
ACCESSIBLE:	permission	WALLS:	lap siding					
STORIES:	Very early	SIGNIFICANT PERSON:	Eugene J. Lennon					
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:						
ALTERED/MOVED NOTES:	Original site. 1x12	vertical siding covered with ½"x 6"	cedar siding on the					
ALTERED/MOVED NOTES: Original site. 1x12 vertical siding covered with ½"x 6" cedar siding on the East and South walls. The West wall with 1x12 vertical siding has been covered with 1x6 #1x6 drop								
siding. The evidence of most horse stalls and milk cow stanchions has been removed.								
			· · ·					
INTERIOR NOTES: The cen	ter 24' of the barn is	s 4x6 posts and 4x6 beams 10' O. C.	with 4x4 angle					
bracing at the top of the posts into the top 4x6 beam. The East and West walls are open except for plank								
dividers at the bottom of the wall. The North 24' x 20' is hayloft from the ground level to the peak. The South 24' x 20' has a hayloft floor is about 8' high. One double horse stall and a granary are still in place								
South 24' x 20' has a hayloft in the East lean-to.	loor is about 8' hig	h. One double horse stall and a grar	ary are still in place					
	alla with Ove girta 4	O C and 4x42 vertical ciding exec	nt the North well and					
		O. C. and 1x12 vertical siding, exce						
		O. C. and 2x6 and 4x6 girts and the 1 's. All of the 2x4 rafters, 2x6 studs a						
<u>~</u>		<u> </u>	<u>-</u>					
		x6's are milled lumber. A 2x6 dividin						
West in the center of the center barn has 1x6 #106 drop siding on the North side of the wall. Lean-to's and this wall appear to have been built with the center barn. The barn has a 6x6 sill under all walls.								
*PHYSICAL								
NOTES: Barn is i	n good condition.	*RESTRICTED: Y o	r N					
*UTM EASTING:								
*UTM NORTHING:								












SKETCH MAP



PHOTOGR





PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone December 16, 2013 ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 16, 2013 ROLL NUMBER:

PHOTO NUMBER:

2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 16, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: December 16, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone **December 16, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, East lean-to, looking NW at double

CAMERA DIRECTION: horse stall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 16, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 4x6 posts, 4x6 beam, 2x6 and 4x6 girts, 4' O. C.

CAMERA DIRECTION: with 1x12 vertical siding.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 16, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SW, 4x6 posts, 4x6 girts and beams with 4x4 angle

CAMERA DIRECTION: bracing at the top.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 16, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking South,

South gable end and

CAMERA DIRECTION: hayloft door.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 16, 2013

ROLL NUMBER: PHOTO NUMBER:

Center barn area, 2x6 dividing wall with 1x6 #106 drop siding, Raised CAMERA DIRECTION: hayloft at the South end.

PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone December 16, 2013


ROLL NUMBER: PHOTO NUMBER:

10

First floor, looking SW at stud wall with girts 4' O. C. and 1x12 vertical

CAMERA DIRECTION: siding siding.





SPIRIT MOUND TOWNSHIP SECTION 23

- 1 McDonald, Ben 31284
- 2 Freidei. Mike 31288
- 4 Wood, Robert 46296

O Farm & Home Publishers, Ltd.

37

CLAY CO., 9



History

This farm located in the SE ¼ of Section 26, Bethel Township, Clay County was a School Section and could not be homesteaded. It could be rented or bought with the income going to support schools in that township.

The 1894 and 1901Clay County Atlas lists Henry Ester as the owner.

The 1912 and 1924 Clay County Atlas lists Eugene J. Lennon as the owner.

The 1937 Clay County Atlas lists Mrs. Eugene J. Lennon as the owner and E. Lennon as the operator (renter).

The 1948 and 1956 Clay County Atlas lists Eugene J. Lennon Jr. as the owner.