

SITE INFORMATION

*SURVEY DATE: September 17, 2012

*SURVEYOR: Jim Stone

*ADDRESS: <u>31828 Fairview Ave.</u>

*COUNTY: <u>Clay</u>

*CITY: Vermillion

LOCATION DESCRIPTION: From the intersection of East Main Street and Crawford Road in Vermillion, East on Main Street 1- 3/4 miles to Fairview Ave., turn right (South), about ¼ mile on the left (East) side.

*QUARTER 1:	NE 1/4		OWNER NAME:	Alex L	& :	Step	hani	e Uff	ord		
*QUARTER 2:			IER ADDRESS:	3821 E	ast	Main	Stre	eet			
*TOWNSHIP:		_	OWNER CITY:	Vermil	lion						
*RANGE:	51	O	WNER STATE:	South	Dak						
*SECTION:		_	OWNER ZIP:	57069							
ACRES:	67.06	_	QUAD NAME:								
OWNER CODE 1:	Р										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNIE											
*DO	E:		REGISTER NA	ME:							
*DOE DAT	E:		MULTIPLE PR	OPERT	Y NA	ME:					
REASON INELIGIBL	E:										
				С	ATE	GOF	Y:				
NOMINATION	STATUS:		SIGNI	FICANC	E LE	EVEL	1:	Ν	S	L	
DATE	E LISTED:		SIGNI	FICANC	ELE	VEL	2:	Ν	S	L	
REFERENCE	NUMBER:										
HISTORIC DISTRICT	RATING: C or	r NC	CRITE	ERIA 1:	Α	В	С	D			
	PERIOD:		CRITE	ERIA 2:	Α	В	С	D			
			CRITE	ERIA 3:	Α	В	С	D			
			CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NOT	ES:										
STRUCTURE DET	TAILS										

* = REQUIRED FIELD



SHPO ID:		_	
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Livestock	FOUNDATION:	Brick foundation
CURRENT SUBFUNCTION:	Straw and grain storage	ROOF MATERIAL:	Asphalt shingles over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Western feeder barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x4 stud with 1x6 #106 drop siding.
STORIES:	2	SIGNIFICANT PERSON:F	ranklin Taylor
*DATE OF CONSTRUCTION:	1905 CU	ILTURAL AFFILIATION:	English

ALTERED/MOVED NOTES: ____Original site. Lean-to added to the West and North sides and milk room added to the East side. Foundation is brick, but has been plastered with masonry in places.

Foundation's are poured concrete on the West and North lean-to's and the milk room. A lot of the 1x6 siding has been replaced with 1x8 shiplap. Roof has asphalt shingles over the cedar shingles.

Wood cupola is gone.


INTERIOR NOTES: <u>Has one row 6x6 posts and a 4x6 for a beam. 2x10 floor joists. Granaries and a</u> 14' x 24' milk room are still in place. All evidence of horse stalls is gone. Milk cow stanchions are still in place.

OTHER NOTES: Walls are 2x4 with 1x6 #106 drop siding, but most of the siding has been replaced with 1x8 shiplap. Huge limestone blocks under the granaries on the West side in original barn. Limestone blocks were extra's from the Court House construction, in 1912.

*PHYSICAL NOTES: Barn is in good condition.


*UTM ZONE:	*RESTRICTED:	Y or N	I
*UTM EASTING:			
*UTM NORTHING:			








SKETCH MAP



PHOTOGR





* = REQUIRED FIELD







PHOTO NUMBER: 4 CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone September 17, 2012










PHOTOGRAPHER: _ DATE OF PHOTO: Jim Stone September 17, 2012 ROLL NUMBER: PHOTO NUMBER:

First floor, looking South in East lean-to. Milk cow CAMERA DIRECTION: stanchions

7



PHOTOGRAPHER: DATE OF PHOTO: Jim Stone September 17, 2012 ROLL NUMBER: PHOTO NUMBER:



original stanchions at CAMERA DIRECTION: the South end.





PHOTOGRAPHER: DATE OF PHOTO: September 17, 2012

ROLL NUMBER: PHOTO NUMBER:


9 First floor, looking South, granaries on West CAMERA DIRECTION: side of center barn




PHOTOGRAPHER: **Jim Stone ROLL NUMBER:** DATE OF PHOTO: September 17, 2012 10 **PHOTO NUMBER:** Hayloft, looking NW,

granary in hayloft, galv. CAMERA DIRECTION: <u>steel row boat above</u>









- Ast
- m 5225 Be
- rs, Dave 4745 Ou

n & H.

O Fa

........

Kn n, Richard 5101 n, David 31761 10 Mogck, John 4733 Dave 4745 11 Miller, Stan 4901 s, Dave 4745 11 Miller, Stan 4901 site, Loren 31765 12 Hovden, Donald 4905 5 6

Sch

2509 Crew, M 2531 Neitzke, Mark 2703 Cook, Cleland 2711 Miskimins, Robin 21 Ahmed, Mike 2925

11



HISTORY

This farm located in the S ¹/₂ of the NE ¹/₄ of Section 21, Fairview Township, Clay County was homesteaded by Franklin Taylor.

The 1894 Clay County Atlas lists Franklin Taylor as the owner.

The 1901 Clay County Atlas lists W. A. Ufford as the owner.

The 1912 Clay County Atlas lists Franklin Taylor as the owner.

The 1924, 1937, 1948 and 1956 Clay County Atlas lists Margaret E. Ufford as the owner and the farm was called "Wayside Farm". It was a stopping place in the horse power and wagon days. They had a scale to weigh grain or livestock and they bought and sold grain.