


SITE INFORMATION

*SURVEY DATE: _July 2	2, 2012	*ADDRESS:	45667 J	45667 Jetly Park Street				
*SURVEYOR: _ Jim S	Stone	*COUNTY:	Clay					
		*CITY:	Meckling					
LOCATION DESCRIPTION: <u>F</u>								
Highway 19, West about 5-3/4 n	niles to 459 th Ave., tu	ırn left (South) abo	out 200 fee	et and	turn	right	t (We	st),
About 1-1/3 mile on the left (So	uth) side.							
LEGAL DESCRIPTION: SE 1/4	, EXC Lot G-1, 35 –	93 – 53 Meckling T	wp.					
*QUARTER 1: SE 1/4		OWNER NAME: Henrietta Sealy						
*QUARTER 2:		•	45667 Jetly Park Street					
*TOWNSHIP: Meckling		OWNER CITY: Meckling						
*RANGE: 53		OWNER STATE: South Dakota						
*SECTION: 35		OWNER ZIP: 57069						
ACRES: 156.89		QUAD NAME:						
OWNER CODE 1: P		•						
OWNER CODE 2: F S L	Р							
OWNER CODE 3: F S L	Р							
	ı							
HISTORIC SIGNIFICANCE								
*DOE:	REGISTER NAME:							
*DOE DATE: MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:								
-								
			CA	TEGO	RY:			
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N			N	S	L	
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L				L		
REFERENCE NUMBER:		-						
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1: A	В	С	D		
PERIOD:		CRITE	RIA 2: A	В	С	D		
		CRITE	RIA 3: A	В	С	D		
		CRITE	RIA 4: A	В	С	D		
SIGNIFICANCE NOTES: Fred	l Demann							




STRUCTURE DETAILS								
SHPO ID:								
*PROPERTY NAME:		-						
OTHER NAME:								
• · · · · · · · · · · · · · · · · · · ·								
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Galv. Corr. steel					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable					
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:	Post and Beam					
		-	Western feeder					
		STYLE:	barn					
OCCUPIED:	Yes	TYPE:	Livestock barn					
			6x6 posts and 3x4					
	Yes with		beams, 1x12 vertical siding w/					
ACCESSIBLE:	permission	WALLS:						
	F							
STORIES:	2	SIGNIFICANT PERSON:	Fred Demann					
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	German					
ALTERED/MOVED NOTES:	Original site. Cedar sh	ningles removed when corrugate	ted galvanized steel					
was installed on roof. Horse stalls and milk stanchions have been removed.								
INTERIOR NOTES: Post and	d beam construction. 8x	8 posts with 6x8 beams about 1	12' O. C. in the center					
22' x 50'. 4x6 angle braces with 6x6 beam at the top for a center support for rafters. All of the posts and								
beams are mortise and tendon. Round pegs were not used. Large spikes secure all tendons.								
OTHER NOTES: Sills are 6 x 8. Exterior walls were 6x6 posts with 3x4 beams, except the two 8x8								
posts in the East gable end. The 1x12 vertical siding had battens to cover the cracks. Hayloft was from								
the ground level to the peak in this 22'x 50' area. This area would hold about 80 tons of loose hay.								
*PHYSICAL NOTES: Barn is	s in poor condition.							







SKETCH MAP



PHOTOGR

* = REQUIRED FIELD






PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: July 2, 2012 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 8x8 posts w/ 6x8 beams mortise and tendon

CAMERA DIRECTION:



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 2, 2012 **ROLL NUMBER:**

PHOTO NUMBER:

CAMERA DIRECTION: beams center structure

First floor, posts and





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, posts and beams on the West end **CAMERA DIRECTION:** next to West lean-to.



MECKLING TWP





HISTORY

This farm located in the SE ¼ of section 35, Meckling township, Clay County was homesteaded by Fredrick Branson.

The 1894 and 1901 Clay County Atlas lists Albert M. Edgerton as the owner.

The 1912 and 1924 Clay County Atlas lists Fred L. Demann as the owner.

The 1937 Clay County Atlas lists Albert M. Edgerton as the owner.

The 1958 and 1956 Clay County Atlas lists Caroline Sealey as the owner.

The Following Information Was Furnished by Jane Slattery

Fred Demann purchased the SE ¼ of Section 35, Meckling Township from Albert and Melinda Edgerton on March 19, 1902. Henrietta Sealy who has lived here all of her married life, says that there was a shack for a house in1902. The current home was built in 1904 or 1905. A man by the name of Herman Peterson or a man named Johnson built this house. The barn was built between 1904 and 1909

Fred and Sophia Demann's daughter Caroline inherited this farm. Caroline's son Harold Sealy inherited the farm from her.

Jane Slattery a great granddaughter of Fred Demann has a picture of the farm, which is prior to 1917. The date is a guess, based on the people and the new Avery tractor.