


SITE INFORMATION

*SURVEY DATE: July 9, 2012			45753 Timber Road							
*SURVEYOR: Jim Si	tone									
		*CITY:	Vermillio	n						
LOCATION DESCRIPTION: From intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, West about 1mile to South Dakota Highway 19 South, turn left about 300' to Timber Road,										
ingina, 10, 1100, about fillio to count banda inginay to count, turn for about ood to filliber Road,										
turn right (West) about 5-1/2 miles to Benson Landing, turn left (South) about ¼ mile, take left lane at the										
Y in the road and fallow in the farm.										
LEGAL DESCRIPTION: Weber Tract 1, SW ¼, SE ¼, 14 – 92 – 53 Norway Twp.										
*QUARTER 1: SE 1/4	(OWNER NAME:			Terry J. Linda L. Weber					
*QUARTER 2:		OWNER ADDRESS:								
*TOWNSHIP: Norway		OWNER CITY:								
*RANGE: 53		OWNER STATE:								
*SECTION: 14		OWNER ZIP:								
ACRES: 9.98		QUAD NAME:								
OWNER CODE 1: P										
OWNER CODE 2: F S L	P									
OWNER CODE 3: F S L	P									
HISTORIC SIGNIFICANCE										
*505-		DECICIED NAME								
	*DOE: REGISTER NAME:									
*DOE DATE:		MULTIPLE PROPERTY NAME:								
REASON INELIGIBLE:										
			CATE	GORY:						
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L								
REFERENCE NUMBER:										
HISTORIC DISTRICT RATING:	•	CRITE	RIA 1: A	в с	D					
PERIOD:		CRITE	RIA 2: A	в с	D					
	_	CRITE	RIA 3: A	в с	D					
		CRITE	RIA 4: A	в с	D					
SIGNIFICANCE NOTES:										



STRUCTURE DETAILS									
SHPO ID:									
*PROPERTY NAME:									
OTHER NAME:									
O MER NAME.									
CURRENT FUNCTION:	Livestock	FOUNDATION							
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Steel over cedar .: shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	: Gambrel						
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM	l: Balloon framing						
		STYLE	·						
OCCUPIED:	Yes		: Livestock barn						
00001 125.	Yes with		2x6, sheathing &						
ACCESSIBLE:	permission	WALLS	5: 1x12 vertical siding						
	•								
STORIES:	2	SIGNIFICANT PERSON: Geo	orge (Buck) Buchanaon						
*DATE OF CONSTRUCTION:	?	CULTURAL AFFILIATION:	?						
ALTERED/MOVED NOTES: Original site. Some of the stalls and stanchions removed. Roof has been covered with steel roofing. Gable roof addition has been added to the West end. Lean-to has been									
added to the East end. These additions are much newer that the original barn.									
INTERIOR NOTES: Has one	row (3) 2x6's for p	osts and (3) 2x6's for beam to supp	oort hayloft floor.						
Joists were 2x6. All of the 2x	6's for studs, rafte	rs and bracing, 2x6 floor joists, 2x6	posts and 2x6 beams						
and sheathing are rough sawn cottonwood.									
OTHER NOTES: Windows were 8"x10" four light. Has a very small metal cupola.									
*PHYSICAL NOTES: Barn is	s in good condition	n. Doors need repair and some win	dows need replacing.						
<u></u>	<u> </u>		<u></u>						









PHOTOGRAPHER: Jim Stone July 9, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking East, (3) 2x6's for post and (3) 2x6's for beam, 2x6

CAMERA DIRECTION: joists



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

6

First floor, Looking East, CAMERA DIRECTION: Horse stall in SE corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: lower rafter bracing

Hayloft, looking West,



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: upper rafter bracing

Hayloft, looking West,





Norm & Hame Publishers 114 29 CLAY CO., SD



HISTORY

This farm, located in the SW ¼ of the SE ¼, Section 14, Norway Township, Clay County was homesteaded by Carl Nygard.

The 1894 Clay County Atlas lists Anna Larson as the owner.

The 1901 Clay County Atlas lists Carl Nygard as the owner.

The 1912 Clay County Atlas lists Laura Colbenson as the owner.

The 1924, 1937 and 1948 Clay County Atlas lists George (Buck) Buckanan as the owner.

The 1956 Clay County Atlas lists Carl Nygard as the owner.