


""SITE INFORMATION							
*SURVEY DATE: July 24,	2013 *ADDRESS:	RESS: 31310 459 th Ave.					
*SURVEYOR: Jim Stor		Clay					
	*CITY:	Meckling					
LOCATION DESCRIPTION: From Ve	ermillion, intersection of South I	Dakota Highway 50 bi-pass and					
South Dakota Highway 19, North about 1-1/4 miles to Bluff Road, turn left (West), fallow Bluff Road about							
3-1/2 miles to 312 th Street, turn left (West) 2 miles to 459 th Ave., turn left (South), about 1/8 mile, on the							
left, (East) side.							
LEGAL DESCRIPTION: W ½, NW ¼, 29 – 93 – 52 Spirit Mound Twp							
*QUARTER 1: NW 1/4	OWNED NAME.	Dorene Becker ETAL					
*QUARTER 1: NW 1/4	-						
*TOWNSHIP: Spirit Mound	-	OWNER ADDRESS: 31341 459 th Ave.					
*RANGE: 52	OWNER STATE:						
*SECTION: 29	-	OWNER STATE: South Dakota OWNER ZIP: 57069					
ACRES: 80.24	QUAD NAME:	37003					
OWNER CODE 1: P							
OWNER CODE 2:							
OWNER CODE 3:							
HISTORIC SIGNIFICANCE							
*DOE:	REGISTER NA	REGISTER NAME:					
*DOE DATE:		MULTIPLE PROPERTY NAME:					
REASON INELIGIBLE:							
		CATEGORY:					
NOMINATION STATUS:	SIGNII	SIGNIFICANCE LEVEL 1: N S L					
DATE LISTED:	SIGNII	FICANCE LEVEL 2: N S L					
REFERENCE NUMBER:							
HISTORIC DISTRICT RATING: C or	NC CRITE	RIA 1: A B C D					
PERIOD:	CRITE	RIA 2: A B C D					
		RIA3: A B C D					
	CRITE	RIA4: A B C D					
SIGNIFICANCE NOTES:							


STRUCTURE DETAILS



SHPO ID:						
*PROPERTY NAME:						
OTHER NAME:						
CURRENT FUNCTION:	Vacant	FOUNDA'	TION:	Poured concrete		
			•	Asphalt shingles over cedar shingles		
CURRENT SUBFUNCTION:	JRRENT SUBFUNCTION: Storage		ROOF MATERIAL:			
HISTORIC FUNCTION: Livestock barn		ROOF SHAPE:		Gambrel roof		
LISTORIC SUBEUNCTION.	Hay and grain	STRUCTURAL SYS	TENA.	Dalloon framing		
HISTORIC SUBFUNCTION:	storage			Balloon framing		
			ΓYLE:	Gambrel roof barn		
OCCUPIED:	Yes Yes with		TYPE:	Livestock barn 2x6 studs, 1x6		
ACCESSIBLE:	permission	WALLS:		vertical car siding		
	por inicoroni		•	Tormour our oraning		
STORIES:	2	SIGNIFICANT PERSON:	G	eorge F. Groves		
*DATE OF CONSTRUCTION:	-	CULTURAL AFFILIATION:		?		
DATE OF CONCINCION.	1010 to 1020	OULIGINAL AITIEIATION.				
ALTERED/MOVED NOTES. Original site. A 24'v44' granery and a 7'v44' granery added in the NW serner						
ALTERED/MOVED NOTES: Original site. A 21'x14' granary and a 7'x14' granary added in the NW corner and along North wall. The 21' x 14' granary goes up 5'-10" into hayloft. It has a floor over it for hay storage						
		ofing. Concrete gutter in the m				
in with concrete.	vereu with steer ro	omig. Concrete gutter in the h	IIIK COV	v area mas been mileu		
iii witii concrete.						
INTERIOR NOTES: Two rows of 4x6 posts, and (3) 2x6's for a beam and one row of 6x6 posts with a 6x6						
beam support the 2x8 joists for the hayloft floor. Six milk cow stanchions are still in place on the East side.						
Two double horse stalls are still in place on the West side. The two granaries are still in place on the North						
wall.						
OTHER NOTES: 2x6 stud walls, with 2x6 girts 5' O. C. and 1x6 vertical car siding. Rafters are 2x6's with						
two 1x6's bracing on each hip. Windows were 9" x12"four light. All of the exterior 2x6 studs, 2x6						
laminated beams and 2x6 rafters are rough sawn cottonwood. The 2x8 floor joist, 4x6 posts 6x6 posts and						
6x6 beams and all of the 2x6's for the granaries are milled lumber.						
*PHYSICAL NOTES: Barn is in good condition.						
*UTM ZONE:		*RESTRICTED:	ν	r N		
			. 0	1 14		
*UTM EASTING:						
*UTM NORTHING:						











PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, 4x6 post, (3) 2x6's beam, 2x8 joists and milk cow CAMERA DIRECTION: stanchions on East side.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, double horse stall still in

CAMERA DIRECTION: place





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013 ROLL NUMBER: PHOTO NUMBER:

7

First floor, looking SW, into 22'x14' granary the goes up 5'-10" into havloft.

CAMERA DIRECTION: hayloft.



PHOTOGRAPHER: _____
DATE OF PHOTO: ____

Jim Stone July 23, 2013 ROLL NUMBER:

PHOTO NUMBER:

Hayloft. looking SE, (2) 1x6's bracing rafters at

CAMERA DIRECTION: _the hip.

the hip.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 24, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft. looking SE, (2) 1x6's bracing rafters at

CAMERA DIRECTION: the hip, upper view.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 24, 2013

ROLL NUMBER: PHOTO NUMBER:

10

Hayloft. looking South, South gable end, note horizontal girts 5' O. C. for nailers for vertical

CAMERA DIRECTION: siding.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 24, 2013


ROLL NUMBER: PHOTO NUMBER:

11

Hayloft. looking North, 22'x14' granary 5'-10" up into hayloft. Had a floor over the granary for hay storage above granary, floor partially

CAMERA DIRECTION: removed.





SPIRIT MOUND TOWNSHIP

- SECTION 23

 1 McDonaid, Ben 31284

 2 Freidel, Mike 31288

 3 46292

• Farm & Home Publishers, Ltd.

37

CLAY CO., SD



HISTORY

This farm located in the NW $\frac{1}{4}$ of Section 29, Spirit Mound Township, Clay County was homesteaded by Tom Halverson.

The 1894 and 1901 Clay County Atlas lists A Hallam as the owner.

The 1912 and 1924 Clay County Atlas lists George F. Groves as the owner.

The 1937 Clay County Atlas lists Northwestern Life Insurance Co. as the owner and Hans & Oren Lewison as the operators (renters).

The 1948 and 1956 Clay County Atlas lists C. M. Olson as the owner.

