

<u>```SITE INFORM</u>	ATION											
*SURVEY D	ATE: July 2	24, 2013	*ADDRESS:	31327 459 th Ave.								
*SURVE	YOR: Jim S	tone	*COUNTY:	Clay								
			*CITY:	Meckling								
LOCATION DESCRIPTION: From Vermillion, from intersection of South Dakota Highway 50 bi-pass and												
South Dakota Highway 19, North about 1-1/4 miles to Bluff road, turn left (West), fallow Bluff Road about												
3-1/2 miles to 313th Street, turn left (West), 2 miles to 459th Ave., turn left (South) about ¼ mile on the right												
(West) side.												
LEGAL DESCRIPTION: E ½, NE ¼ Ex 412.85' of N 637.9' of S 1098.86' of SE ¼, NE ¼, 30 – 93 – 52												
Spirit Mound Twp.												
*QUARTER 1:	NE 1/4		OWNER NAME:	Dorene Be	cker ET	AL						
*QUARTER 2:		ow	NER ADDRESS:	31341 459 th Ave.								
*TOWNSHIP:	Spirit Mound		OWNER CITY:	Meckling	Meckling							
*RANGE:	52		OWNER STATE:	South Dak	South Dakota							
*SECTION:	30		OWNER ZIP: <u>57069</u>									
ACRES:	71.01		QUAD NAME:									
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGNIFICANCE												
*DOE:			REGISTER NAME: MULTIPLE PROPERTY NAME:									
*DOE DATE:				OPERITNA	AIVIE: _							
REASON INELIGIE	3LE:											
				CATE	GORY:							
NOMINATIO	N STATUS.		SIGNIFICANCE LEVEL 1: N S L									
NOMINATION STATUS: DATE LISTED:												
REFERENCE NUMBER:			O.O.T.	10/1102 21				_				
HISTORIC DISTRIC		_	CRITE	ERIA 1: A	в с	D						
PERIOD:				RIA 2: A								
				RIA 3: A								
				RIA 4: A								
SIGNIFICANCE NOTES:												


STRUCTURE DETAILS




SHPO ID:										
*PROPERTY NAME:										
OTHER NAME:										
CURRENT FUNCTION:	Granary	FOUNDATI	ON:	Poured concrete						
•			•	Asphalt shingles over						
CURRENT SUBFUNCTION: Storage		ROOF MATER	cedar shingles Gable roof							
HISTORIC FUNCTION:	Horse barn	ROOF SHA	ROOF SHAPE:							
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYST	STRUCTURAL SYSTEM:							
		STY	LE:	Gable roof barn						
OCCUPIED:	Yes	TY	TYPE:							
	V 141			2x6 studs, 1x6 car						
ACCESSIBLE:	Yes with permission	WALLS:		siding and 1x8 shiplap inside						
ACCESSIBLE.	permission	WALLS.	•	Silipiap iliside						
STORIES:	2	SIGNIFICANT PERSON:	G	eorge F. Groves						
*DATE OF CONSTRUCTION:	1912 to 1924	CULTURAL AFFILIATION:		?						
ALTERED/MOVED NOTES: _	Present owner belie	eves that the barn was moved v	vhen	it was remodeled into						
a granary. Any evidence of he	orse stalls is remove	ed. Floor joists support the wo	od fl	oor. I can not see the						
joists but can see a 2x6 on a 4	x6 beam in the doo	rways. Barn was divided with	a 12'	high 2x6 wall with 1x8						
shiplap, in the center both wa	ays. This makes fou	ır 12' x 16' granaries 12' high. I	Floori	ng is removed in the						
	2x8 joists are remov	ed on the North 16'. 1x12 boar	ds cr	oss brace the top of						
the walls.										
INTERIOR NOTES: Two row	s of 6x6 posts, and	6x6 beam support the 2x8 joist	s for	the havloft floor.						
2x6 stud walls 12' high with 1x8 shiplap divide the East and West sides and another wall divides the North and South sides. This makes four 12' x 16' x 12' high granaries.										
OTHER NOTES: 2x6 stud walls, with 1x6 car siding and 1x8 shiplap liner on the inside. Rafters are										
2x4's. Windows were 9"x12" four light, but have all been framed in.										
*PHYSICAL NOTES: Barn /	granary is in good c	condition								
OIGAL NOTES. Ballin	granary is in good o									
			Y o	r N						
*UTM EASTING:										
*UTM NORTHING:										



SKETCH MAP









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July 23, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, 6x6 post, 6x6 beam, 2x8 joists, note 1x12 bracing

CAMERA DIRECTION: above.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 6x6 posts, 6x6 beam, 2x8

CAMERA DIRECTION: floor joists.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, 6x6 beam, 6x6 post is CAMERA DIRECTION: missing, and 2x8 joists.



PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 23, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SE, 6x6 beam, 6x6 post is

CAMERA DIRECTION: missing and 2x8 joists.







HISTORY

This farm located in the NE ¼ of Section 30, Spirit Mound Township, Clay County was homessteaded by William Schrader.

The 1894 Clay County Atlas lists William Schrader as the owner.

The 1901 Clay County Atlas lists A. Hallam as the owner.

The 1912 and 1924 Clay County Atlas lists George F. Groves as the owner.

The 1937 Clay County Atlas lists NorthWestern Life Insurance Co. as the owner and Hans & Oren Lewison as the operators (renters).

The 1948 and 1956 Clay County Atlas lists C. M. Olson as the owner.

