

SITE INFORMATION

*Sl

SURVEY DATE:	October 26, 2012	*ADDRESS:	32028 Ponderosa Drive
*SURVEYOR:	Jim Stone	*COUNTY:	Clay
		*CITY:	Burbank

LOCATION DESCRIPTION: From intersection of Main Street and Dakota Street in Vermillion, South about 1/4 mile to Burbank Road, turn left (East), fallow this road about 5 miles to Ponderosa Drive, turn right (South) and (West) about 1/8 mile on the left (South) side

LEGAL DESCRIPTION: Lot A of SE 1/4, NW 1/4 & SW 1/4, NE 1/4, 35 – 92 – 51 Fairview Twp.

*QUARTER 1:	NW 1/4			OWNER NA	ME:	Grego	ry J.	& Vi	cki	L. Fu	llenk	amp	
*QUARTER 2:	NE 1/4		NO	/NER ADDRE	ESS:	3019 N	/ΙcCι	illy D	rive	NE			
*TOWNSHIP:	Fairview			OWNER C	ITY:	Atlant	а						
*RANGE:	51			OWNER STA	ATE:	Georg	ia						
*SECTION:	35			OWNER	ZIP:	30345							
ACRES:	14.5			QUAD NA	ME:								
OWNER CODE 1:	Р												
OWNER CODE 2:													
OWNER CODE 3:													
HISTORIC SIGN	IFICANCE												
*D(DE:			REGISTE	ER NA	ME:							
*DOE: *DOE DATE:			MULTIPL	E PR		Y NA	ME:	_					
REASON INELIGIB													
						С	ATE	GOF	Y:				
NOMINATIO	N STATUS:			S	SIGNI		ELE	VEL	1:	Ν	S	L	
					SIGNI		ELE	VEL	2:	Ν	S	L	
REFERENCE													
HISTORIC DISTRIC	T RATING:	C or	NC	C	CRITE	RIA 1:	Α	в	С	D			
	PERIOD:			C	CRITE	RIA 2:	Α	В	С	D			
				C	CRITE	RIA 3:	Α	в	С	D			
				C	CRITE	RIA 4:	Α	в	С	D			
SIGNIFICANCE NO	TES:												

STRUCTURE DETAILS

* = REQUIRED FIELD



SHPO ID:		_	
*PROPERTY NAME:			
OTHER NAME:			
	Storage	FOUNDATION	Poured concrete : <u>foundation</u>
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Asphalt shingles over cedar : shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	: Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM	: Balloon framing
		STYLE	: Gambrel roof barn
OCCUPIED:	Yes	TYPE	: Livestock barn
ACCESSIBLE:	Yes with permission	WALLS	2x6 stud with 1x6 : _#106 drop siding
STORIES:	2		rge Leo & Christina enkamp
*DATE OF CONSTRUCTION:	About 1910 CU	LTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. Milk cow stanchions and horse stalls have been removed. Roof has been shingled with asphalt shingles. 9'x7' overhead doors installed at the North end of East and West lean-to's. Some of the granaries and the box stall have one wall removed. Some of the posts have been removed. Some of the windows have been replaced with aluminum storm windows.


INTERIOR NOTES: <u>Has two rows of 4x6 posts with 6x6 beams. 2x8 floor joists. All three granaries</u> and the box stall are still in place.

OTHER NOTES: 2x6 stud walls with 1x6 #106 drop siding. Rafters are 2x6 with rough sawn sheathing. All of the 2x6's, 2x8's, 4x6's, 6x6's and ³/₄"roof sheathing is rough sawn cottonwood. Windows are 10"x 12" four light. Four dormers in the hayloft at the hip. Each dormer has one 10"x12" four light over one 10"x12" four light, double hung for ventilation. All of the windows on the first floor are 10"x12" four light. *PHYSICAL NOTES: Barn is in fair condition. Needs roofing soon. Some of the doors and windows need repair.


*RESTRICTED: Y or N	
	*RESTRICTED: Y or N




SKETCH MAP



NORTH ELEVATION











 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 October 26, 2012
 PHOTO NUMBER:
 1

 CAMERA DIRECTION:
 Looking NE, SW corner



 PHOTOGRAPHER:
 Jim Stone

 DATE OF PHOTO:
 October 26, 2012

PHOTO NUMBER: 2 CAMERA DIRECTION: Looking NW, SE corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 October 26, 2012
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking SW, NE corner



October 26, 2012

PHOTOGRAPHER: _____ DATE OF PHOTO:

PHOTO NUMBER: 4 CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: October 26, 2012 ROLL NUMBER: PHOTO NUMBER:

First floor, East lean-to, looking South, area where milk cow CAMERA DIRECTION: stanchions where

5



PHOTOGRAPHER:Jim StoneDATE OF PHOTO:October 26, 2012

ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 6 First floor, center of barn, looking South, posts, beam and box CAMERA DIRECTION: stall in SW corner

* = REQUIRED FIELD





PHOTOGRAPHER: **Jim Stone** DATE OF PHOTO: October 26, 2012

ROLL NUMBER: PHOTO NUMBER:

7 First floor, center of barn, looking North, CAMERA DIRECTION: granaries in NE corner



PHOTOGRAPHER: **Jim Stone** October 26, 2012 DATE OF PHOTO:

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: looking North

8 First floor, West lean-to,






Jim Stone PHOTOGRAPHER: DATE OF PHOTO: October 26, 2012


ROLL NUMBER: PHOTO NUMBER:

Special hayfork in hayloft, might be for CAMERA DIRECTION: bales

9







C Farm & Home Publishers, Ltd.

19

CLAY CO.,

7



HISTORY

This farm located in the SE ¹/₄ of the NW ¹/₄ and the SE ¹/₄ of the NE ¹/₄ in Section 35, Fairview Township, Clay County was homesteaded by Charles Cordier.

The 1894 Clay County Atlas lists C. V. Cordier as the owner.

The 1901 Clay County Atlas lists Harvey Gunderson as the owner.

The 1912 Clay County Atlas lists George and Joseph Fullerton as the owners. The name Fullerton could be a spelling error if the farm was bought in 1906 or 1908.

The 1924 Clay County Atlas lists George L. Fullenkamp as the owner.

The 1937, 1949 and 1956 Clay County Atlas lists Christina Fullenkamp as the owner. The 1937 Atlas lists George Fullenkamp as the operator (renter).

The Following Information is From

Gregory Fullenkamp, Atlanta, Georgia. He grew up on this farm.

George Leo and Christina Fullenkamp bought this farm in 1906 or 1908.

They built this barn in about 1910. The house was built in 1892 before they moved here.

This farm was called "Glendale Farms".

