

#### **SITE INFORMATION**

*SURVEY DATE: November 4, 2011	*ADDRESS:	46068 Timber Road				
*SURVEYOR: Jim Stone	*COUNTY:	Clay				
	*CITY:	Vermillion				
LOCATION DESCRIPTION: West of Vermillion on Hwy 50, turn South (left) on Hwy 19 and turn West						
(right) on Timber Road, West about 1-1/4 miles, address 46068 on the North side.						
LEGAL DECORPTION OWAY (ALCOHOL)	-1' 40 00 DE0					
LEGAL DESCRIPTION: SW ¼ of NE ¼ of Section 16, 92, R52						
*QUARTER 1: <u>NE 1/4</u>	OWNER NAME:	Duane and Connie Holoch				
*QUARTER 2:	OWNER ADDRESS:	46068 Timber Road				
*TOWNSHIP: <u>Vermillion</u>	OWNER CITY:	Vermillion				
*RANGE: <u>52 W</u>		South Dakota				
*SECTION: 16	OWNER ZIP:	57069				
ACRES: <u>38.85</u>	QUAD NAME:					
OWNER CODE 1: P						
OWNER CODE 2: F S L P						
OWNER CODE 3: F S L P						
<b>HISTORIC SIGNIFICANCE</b>						
*DOE:	REGISTER NA	ME-				
*DOE DATE:		MULTIPLE PROPERTY NAME:				
REASON INELIGIBLE:						
		CATEGORY:				
NOMINATION STATUS:	SIGNIF	FICANCE LEVEL 1: N S L				
DATE LISTED:	SIGNIF	FICANCE LEVEL 2: N S L				
REFERENCE NUMBER:						
HISTORIC DISTRICT RATING: C or NC	CRITE	RIA1: A B C D				
PERIOD:	CRITE	RIA 2: A B C D				
	CRITE	RIA 3: A B C D				
	CRITE	RIA 4: A B C D				
SIGNIFICANCE NOTES: Barn was remodeled in 1999, all but the north ten feet of haymow has been						
removed, 20' x 15' 6" overhead door installed on south side. Roof has been covered with steel roofing and Mr. Holoch is installing steel siding over the existing wood siding. Barn is in good condition.						
2x6 framing is all Douglas Fir which was the I						

<sup>\* =</sup> REQUIRED FIELD




STRUCTURE DETAILS					
SHPO ID:					
*PROPERTY NAME:	Chaney barn				
OTHER NAME:					
CURRENT FUNCTION:	Hay & machinery storage	FOUNDATION:	Poured concrete		
CURRENT SUBFUNCTION:	Hay & machinery storage	ROOF MATERIAL:			
	Livestock barn	ROOF SHAPE:			
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYSTEM:			
		STYLE:	Ground floor with huge hayloft		
OCCUPIED:	YES		Livestock barn		
	YES with		2x6 with 1x6 #106		
ACCESSIBLE:	permission	WALLS:	drop siding		
STORIES:	2S	SIGNIFICANT PERSON:	George Jasperson		
*DATE OF CONSTRUCTION:	1920 to 1930 CU	LTURAL AFFILIATION:	?		
ALTERED/MOVED NOTES: Original site. In 1999 all but the north ten feet of hayloft has been removed and 20' x 15'-6" overhead door installed on the South side for hay and machinery storage.					
INTERIOR NOTES: Origi	nal barn had two rows 6x	6 posts with (4) 2x6's nailed to	gether for a beam		
which ran North and South. Posts were 10' O.C. North to South and 12' O.C. East to West. Hayloft floor					
is 2x10 floor joists with ¾" floor boards. This can be seen in the 10 feet of floor left at the North end.					
Rafters are modified braced r OTHER NOTES: Four dorn		Γwo dormers on East and two θ	dormers on the West.		
Each dormer has (3) four light windows. A very large metal cupola on the roof peak. Barn had (3) 9x12					
four light windows on the East wall and (2) more next to the peak on the North. The South wall had (2)					
large windows next to peak. These windows were 4"x24" four light over 4"x12" four light and are					
double hung for ventilation. *PHYSICAL NOTES: Barr	n is in good condition. W	indows and small walk doors v	vill be covered on the		
outside with steel siding when Mr. Holoch is through siding the exterior.					




SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE HISTORIC SITES SURVEY STRUCTURE FORM



#### SKETCH MAP





\* = REQUIRED FIELD

3





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: November 4, 2011 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NW, SE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: November 4, 2011 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NE, SW corner





**PHOTOGRAPHER:** 

Jim Stone

**ROLL NUMBER:** 

DATE OF PHOTO: November 4, 2011

PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone

ROLL NUMBER:

DATE OF PHOTO: November 4, 2011

**PHOTO NUMBER:** 

Looking NE, Rafters and

CAMERA DIRECTION: existing 10' of hayloft





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: November 4, 2011 ROLL NUMBER:

PHOTO NUMBER: 5

Looking NW, Rafters and CAMERA DIRECTION: existing 10' of hayloft



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: November 4, 2011

ROLL NUMBER:

PHOTO NUMBER: 6

CAMERA DIRECTION: rafters, bracing and wall

Looking West,





PHOTOGRAPHER: DATE OF PHOTO:

**Connie Holoch** Winter of 2000- 2001

**ROLL NUMBER: PHOTO NUMBER:** 

Looking SE, NW corner of barn

**CAMERA DIRECTION:** 



DATE OF PHOTO: 1990


PHOTOGRAPHER: Connie Holoch

**ROLL NUMBER:** PHOTO NUMBER: 8

Looking NW, SE corner

CAMERA DIRECTION:







### **History**

This farm located in the NE ¼ of Section 16, Vermillion Township, Clay County was a "School Section" to be rented or sold with the proceeds set aside for rural school education.

The 1894 and 1901 Clay County Atlas lists Lee & Prentis as the owners.

The 1912 Clay County Atlas lists C. E. Prentis as the owner.

The 1924 Clay County Atlas lists George Jasperson as the owner.

The 1937 Clay County Atlas lists M. J. Chaney as the owner.

The 1948 and 1956 Clay County Atlas lists M. A. Chaney as the owner.

