

SITE INFORMATION

*SURVEY DATE: <u>July</u>	*ADDRESS:	SS: _ 30641 466 th Ave.										
*SURVEYOR: Jim \$	*COUNTY:											
		*CITY:	Verm	illior	1							
LOCATION DESCRIPTION: _S	South Dakota Highwa	, 50 East of Vermi	llion 2 r	niles	s to (Gree	nfiel	d Ro	ad,			
Turn left (North) 12-1/2 miles to	o 306 th Street, turn rig	ht (East) to 466 th A	Ave., tur	n riç	ght (Sout	th) at	oout	1/3			
mile, on the right (West) side												
LEGAL DESCRIPTION: NE 1/2	4 20 - 94 - 51 Garfiel	d Twp.										
*QUARTER 1: NE 1/4		OWNER NAME:				Craig L. & Leslie J. Nelson						
*QUARTER 2:	NER ADDRESS:											
*TOWNSHIP: Garfield		OWNER ADDRESS: OWNER CITY:										
*RANGE: 51		OWNER STATE:										
*SECTION: 20		OWNER ZIP:										
ACRES: 158.02		QUAD NAME:										
OWNER CODE 1: P												
OWNER CODE 2: F S L	Р											
OWNER CODE 3: F S L	Р											
HISTORIC SIGNIFICANCE												
HISTORIC SIGNIFICANCE	i											
*DOE:	REGISTER NAME:											
*DOE DATE:		MULTIPLE PR	OPERT	Y NA	ME:	_						
REASON INELIGIBLE:												
			_									
				GOF	•							
NOMINATION STATUS:		_ SIGNIFICANCE LEVEL 1: N S L SIGNIFICANCE LEVEL 2: N S L							_			
DATE LISTED:		SIGNI	FICANC	E LE	EVEL	. 2:	N	S	L			
REFERENCE NUMBER:		OD!TE	.D.A.4	_	_	_	_					
HISTORIC DISTRICT RATING:			RIA 1:				D					
PERIOD:			RIA 2:									
			RIA 3:									
		CKITE	RIA 4:	A	Ď	C	ט					
SIGNIFICANCE NOTES:												
SIGNIFICANCE NOTES:												


STRUCTURE DETAILS




SHPO ID:											
*PROPERTY NAME:			-								
OTHER NAME:											
CURRENT FUNCTION:	Storage		FOUNDATIO	ON-	Poured concrete						
GONNENT FONOTION.	Otorage		_ I OONDAIN	0.1.	Steel roofing						
					over cedar						
CURRENT SUBFUNCTION:	Storage		ROOF MATERI		shingles						
HISTORIC FUNCTION:	Livestock barn		_ ROOF SHA								
HISTORIC SUBFUNCTION:	Hay & grain stor	age	STRUCTURAL SYSTI								
200115155					Gambrel roof barn						
OCCUPIED:	Yes		IY	PE:	Livestock barn 2x6, sheathing &						
	Yes with				½"x6" cedar lap						
ACCESSIBLE:	permission		WAL	LS:	siding						
STORIES:	2	;	SIGNIFICANT PERSON:	G	ustaf Falk						
*DATE OF CONSTRUCTION:	1917 to 1918	CL	LTURAL AFFILIATION:		?						
ALTERED/MOVED NOTES: _	Original site. S	outh s	ide of roof and all side wall	ls ha	ve been covered						
with steel roofing. North side	e of roof still has	aspha	t shingles over cedar shing	gles.	Horse stalls and						
milk cow stanchions have be	en removed. Owi	ner is ç	joing to install steel on the	Nort	h side of the roof as						
the asphalt shingles are very	old.										
INTERIOR NOTES: Has two	rows 6x6 posts a	nd (3) :	2x8's beam to support have	oft fl	oor. Floor ioists are						
2x8's. Granary, harness room	•										
mangers as per Craig Nelson					g.a pano in aio						
OTHER NOTES: Windows w			alls are 2x6 with sheathing	1/2"	x6" cedar lap siding						
·											
and covered with steel roofing. Rafters and rafter bracing are 2x6. Has two metal cupola's. Has a stair case to the hayloft that is hinged and weighted to fold up when not in use.											
	god dira iroiginiod										
*PHYSICAL NOTES: Barn is	s in verv good cor	dition	All the windows have gla	iss a	nd all of the doors						
are repaired and covered with			<u> </u>								
41 ITA 2011			*D FATE: 6	v	N						
*UTM ZONE:				ΥO	r N						
*UTM EASTING:											
*UTM NORTHING:											



SKETCH MAP





* = REQUIRED FIELD

3





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July 20, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 20, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 20, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 20, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





Jim Stone PHOTOGRAPHER: DATE OF PHOTO: July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, posts and beam, horse stalls were along East

CAMERA DIRECTION: wall



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, harness room and

CAMERA DIRECTION: granary





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West through harness room to

CAMERA DIRECTION: fold up stairs





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North,

where milk cow

CAMERA DIRECTION: _stanchions were





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: July 20, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking West, lower wall and rafter

CAMERA DIRECTION: bracing



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: July 20, 2012 **ROLL NUMBER:**


PHOTO NUMBER:

10

CAMERA DIRECTION: upper rafter bracing

Hayloft, looking West,





CLAY CO., SD



HISTORY

This farm located in the NE ¼ of Section 20, Garfield Township, Clay County was homesteaded by Gustaf Falk.

The 1894, 1901 and 1912 Clay County Atlas lists Gustaf Falk as the owner.

The 1924 and 1937 Clay County Atlas lists Gustaf Falk Estate as the owner.

The 1948 and 1956 Clay County Atlas lists C. J. Faulk as the owner.