

SITE INFORMATION					
*SURVEY DATE: December 2,	2013 *ADDRESS: 926 E. 316 th Street				
*SURVEYOR: Jim Stone					
	*CITY: Vermillion				
LOCATION DESCRIPTION: From Vermillion, from intersection of South Dakota Highway 50 bi-pass and					
University Road, North 1 mile to 316th Street, turn right (East) about ¼ mile on the left (North) side					
LEGAL DESCRIPTION: Lot C of Lot 1 in SW ¼, 6 – 92 – 51 Vermillion Twp.					
*QUARTER 1:SW 1/4	OWNER NAME:Jeffery S. & Carolyn A. Jensen				
*QUARTER 2:	OWNER ADDRESS: 926 E. 316th Street				
*TOWNSHIP: Vermillion	OWNER CITY: Vermillion				
*RANGE: <u>51</u>	OWNER STATE: South Dakota				
*SECTION: 6	OWNER ZIP: 57069				
ACRES: 3.91	QUAD NAME:				
OWNER CODE 1: P					
OWNER CODE 2:					
OWNER CODE 3:					
HISTORIC SIGNIFICANCE					
HISTORIC SIGNIFICANCE					
*DOE:	REGISTER NAME:				
*DOE DATE:	MULTIPLE PROPERTY NAME:				
REASON INELIGIBLE:					
	CATEGORY:				
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L				
DATE LISTED:	SIGNIFICANCE LEVEL 2: N S L				
REFERENCE NUMBER:					
HISTORIC DISTRICT RATING: C or NO					
PERIOD:	CRITERIA 2: A B C D				
	CRITERIA 3: A B C D				
	CRITERIA 4: A B C D				
SIGNIFICANCE NOTES:					


STRUCTURE DETAILS



SHPO ID:	·	_		
*PROPERTY NAME:	<u> </u>			
OTHER NAME:	:			
CURRENT FUNCTION	: Storage	FOUNDATION:	Poured concrete	
			Steel roofing over	
CURRENT SUBFUNCTION:	Storage	_ ROOF MATERIAL:	 	
HISTORIC FUNCTION	: Livestock barn	_ ROOF SHAPE:	Gable roof	
HISTORIC SUBFUNCTION	: Hay storage	_ STRUCTURAL SYSTEM:		
		STYLE:	Gable roof barn	
OCCUPIED:		TYPE:		
400E00IDLE	Yes with	MALLO.	2x4 studs, and 1x6	
ACCESSIBLE:	: permission	WALLS:	#106 drop siding	
070015				
STORIES	·	SIGNIFICANT PERSON:	H. A. Atwood	
*DATE OF CONSTRUCTION	l: <u>1890 to 1910 </u>	JLTURAL AFFILIATION:	?	
ALTERED/MOVED NOTES: Original site. 1-1/4"x 26" galvanized, corrugated steel installed on roof over				
cedar shingles. All evidence of milk cow stanchions has been removed from the East lean-to.				
INTERIOR NOTES: Six double horse stalls still in place in West lean-to. Double 2x6 posts 8' O. C.				
support the center of the rafters on each side of the center 24'. The west side is open into the horse				
stalls. The East side is covered with 1x8 shiplap for a solid wall up to the rafters. 32' x 16' hayloft floor at the South end. The loft floor extends 8' over the two South horse stalls. The 24' x 32' in the center area				
at the North end is a hayloft from the ground up 28' to the peak of the roof.				
OTHER NOTES: Exterior walls are 2x4 stud walls with 1x6 #106 drop siding. The windows are 9" x 12"				
four light. The cupola has been removed. The 2x4 studs, 2x6 rafters, 2x6 floor joists, 2x6 posts, 4x4				
Posts and 4x4 beams are all rough sawn cottonwood.				
<u> </u>				
*PHYSICAL				
	s in good condition.	*RESTRICTED: Y o	or N	
*UTM EASTING:				
*UTM NORTHING:				




SKETCH MAP





SKETCH MAP



SOUTH ELEVATION

PHOTOGR





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

Looking NE, SW corner

CAMERA DIRECTION:



PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: December 2, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: December 2, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, West lean-to looking NE, double horse stalls on West side, note hayloft above two South

CAMERA DIRECTION: stalls.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, hayloft floor at

CAMERA DIRECTION: the South 16'.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

Center of barn, looking SW, double 2x6 posts 8' O. C. supporting center CAMERA DIRECTION: of rafters on West side.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

Center of barn, looking SE, double 2x6 posts with 1x8 shiplap up to

CAMERA DIRECTION: roof on the East side.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone **December 2, 2013**

ROLL NUMBER: PHOTO NUMBER:

First floor, East lean-to, looking NW, where the milk cow stanchions were, note 1x8 shiplap on West wall and 2x6

CAMERA DIRECTION: open joists 4' O. C.







History

This farm located in the SW ¼ of Section 6, Vermillion Township, Clay County was homesteaded by Ezbrian Harrington.

The 1894 and 1901 Clay County Atlas lists H. H. Atwood as the owner.

The 1912 Clay County Atlas lists E. Atwood as the owner.

The 1924 Clay County Atlas lists T. J. Helgenson as the owner.

The 1937 and 1948 Clay County Atlas lists Bertha A. Atwood as the owner.

The 1956 Clay County Atlas lists H. C. Johnson as the owner.

