


SITE INFORM	ATION											
*SURVEY DATE: August 16, 2		6, 2013	30376 458 th Ave.									
*SURVEYOR: Jim Stone			*COUNTY:	NTY: Clay								
			*CITY:	Wako	nda							
LOCATION DESCR												
South Dakota Highway 19, North about 13 miles to 304 th Street, turn left (West) about 4 miles to 458 th Ave., turn right (North) about ½ mile, on the right (East) side.												
	•	<u> </u>										
LEGAL DESCRIPTION: Lot 1 Denzin's Addition, SW 1/4, 6 – 94 – 52 Pleasant Valley Twp.												
*01140750.4	014/4			D'-1 W	, . 16 -	• •						
*QUARTER 1:	SW 1/4		OWNER NAME: Rick Wolfswinkel OWNER ADDRESS: 30376 458th Ave.									
*QUARTER 2: *TOWNSHIP:	Pleasant Valley	OWNER CITY:										
*RANGE:	52	WNER STATE:										
*SECTION:	6		OWNER ZIP:									
ACRES:	8.14		QUAD NAME:									
OWNER CODE 1:	P											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGN	IFICANCE											
*DOE:			REGISTER NAME: MULTIPLE PROPERTY NAME:									
*DOE DATE:			MULTIPLE PR	OPERI	YNA	NVIE:	_					
REASON INELIGIB	SLE:											
				С	ATE	GOR	Y:					
NOMINATIO		SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L									
	E NUMBER:											
	T RATING: C or	,	CRITE	ERIA 1:	Α	В	С	D				
	PERIOD:		CRITE	ERIA 2:	Α	В	С	D				
			CRITE	ERIA 3:	Α	В	С	D				
			CRITE	ERIA 4:	Α	В	С	D				
SIGNIFICANCE NOTES:												

STRUCTURE DETAILS



SHPO ID:		_							
*PROPERTY NAME:									
OTHER NAME:									
			Native stone and						
CURRENT FUNCTION:	Calving barn	FOUNDATION:	poured concrete Steel roofing over						
CURRENT SUBFUNCTION:	Cattle shelter	ROOF MATERIAL:	cedar shingles						
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable roof						
HISTORIC SUBFUNCTION:	Hay & grain storage	STRUCTURAL SYSTEM:	Balloon framing						
		STYLE:	Gable roof barn						
OCCUPIED:	Yes	TYPE:	Livestock barn						
			2x6 studs, 1x8 and						
ACCESSIBLE:	Yes with permission	WALLS:	1x6 #106 drop siding and steel roofing						
ACCESSIBLE.	permission	WALLS.	and steer rooming						
STORIES:	2	SIGNIFICANT PERSON:	H. J. West						
*DATE OF CONSTRUCTION:	?								
ALTERED/MOVED NOTES: Original site. Roof covered with steel roofing over cedar shingles. All evidence of milk cow stanchions has been removed. There is some evidence of double horse stalls on the									
		n the East side. Poured concre							
original native stone foundati	on, may not had any mo	rtar and needed to be re-enford	ed.						
INTERIOR NOTES: Two row	s of 4x6 posts with 4x6's	s for beams support 2x8 joists	for havloft floor.						
	-	ner. 2x6 rafters with two rows							
	O. C., also 2x6 bracing	from center of rafters down to							
OTHER NOTES: 2x6 stud w	alls with 1x6 #106 drop s	siding on the West and South v	valls. 1x8 # 106 drop						
siding on the North and East	walls. The North, West a	and South walls covered with h	orizontal steel roofing.						
East wall under East lean-to	still has 1x8 #106 drop s	ding exposed inside of lean-to	. Windows were 8"x						
x 10" four light. No cupola.									
*LITM FACTING.	n good condition.	*RESTRICTED: Y o	or N						









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 16, 2013

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 16, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: August 16, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SE, NW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: August 16, 2013 PHOTO NUMBER: 4

First floor, looki

First floor, looking NW, 4x6 posts, 4x6 beam and 2x8 floor joists, note milk room and granary in the NW corner

CAMERA DIRECTION:





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 16, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, some of the

double horse stalls on

CAMERA DIRECTION: the East wall.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 16, 2013

ROLL NUMBER: PHOTO NUMBER:

6

First floor, looking NE into East lean-to, note 1x8 original drop siding

CAMERA DIRECTION: on barn wall.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone August 16, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SE, 2x6 posts supporting rafters,

CAMERA DIRECTION: 8'O. C.



PHOTOGRAPHER: Jim Stone


DATE OF PHOTO: August 16, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking SW, 2x6 bracing from center of rafters down to floor and exterior wall, also a 2x6 brace from top of wall down to floor, both 8' O.

CAMERA DIRECTION: C.





CLAY CO., SD



History

This farm located in the SW ¼ of Section 6, Pleasant Valley Township, Clay County was homesteaded by Ole Johnson.

The 1894 Clay County Atlas lists Fannie M. McDonald as the owner.

The 1901 Clay County Atlas lists Estelle Hallam Bennett as the owner.

The 1912, 1924, 1937 and 1948 Clay County Atlas lists H. J. West as the owner.

The 1937 Clay County Atlas lists E. J. Bertelsen as the operator (renter).

The 1956 Clay County Atlas lists G. R. West as the owner.

