


SITE INFORM	<u>ATION</u>					
*SURVEY DA	TE: September	er 3, 2013 *ADDRESS	: _31417 Bluff road Road			
*SURVEY	OR: Jim Stone	e *COUNTY	ː Clay			
		*CITY	: Vermillion			
LOCATION DESCR	IPTION: From Ver	million, intersection of South	Dakota Highway 50 bi-pass and			
South Dakota High	way 19, North about	1-1/4 miles to Bluff Road, tur	n left (West) and follow Bluff Road			
about 2-3/4 miles, o	on the left (West) sid	le.				
LEGAL DESCRIPTION: NE 1/4, NE ¼, 33 – 93 – 52 Spirit Mound Twp.						
*QUARTER 1:	NE 1/4	OWNER NAME:	Richard & Sally Abild			
*QUARTER 2:		OWNER ADDRESS:	31418 Bluff Road			
*TOWNSHIP:	Spirit Mound	OWNER CITY:	Vermillion			
*RANGE:	52	OWNER STATE:	So. Dak.			
*SECTION:	33	OWNER ZIP:	57069			
ACRES:	39.68	QUAD NAME:				
OWNER CODE 1:	Р					
OWNER CODE 2:						
OWNER CODE 3:						
HISTORIC SIGN	IEICANCE					
IIIOTORIO GIGIA	II IOANOL					
*D(OE:	REGISTER N	REGISTER NAME:			
*DOE DA	TE:	MULTIPLE P	ROPERTY NAME:			
REASON INELIGIB	LE:					
			CATEGORY:			
NOMINATIO	N STATUS:	SIGN	SIGNIFICANCE LEVEL 1: N S L			
DATE LISTED:		SIGN	IFICANCE LEVEL 2: N S L			
REFERENCE	NUMBER:					
HISTORIC DISTRIC	TRATING: C or		ERIA 1: A B C D			
	PERIOD:		ERIA 2: A B C D			
			ERIA 3: A B C D			
		CRIT	ERIA 4: A B C D			
CIONIFIO ANOT NOTES						
SIGNIFICANCE NOTES:						


STRUCTURE DETAILS



SHPO ID:		_				
*PROPERTY NAME:						
OTHER NAME:						
CURRENT FUNCTION:	Storage	FOUNDATION	and the second s			
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL	Steel roofing over cedar shingles			
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE	: Gable roof			
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM	: Balloon framing			
		STYLE	: Gable roof barn			
OCCUPIED:	Yes	TYPE	: Dairy barn			
ACCESSIBLE:	Yes with permission	WALLS:	2x6 studs, 16" O. C., siding – sheathing removed, steel roofing.			
STORIES:	2	SIGNIFICANT PERSON:	Hans Lewison			
*DATE OF CONSTRUCTION:	Late 1800's CU	LTURAL AFFILIATION:	?			
ALTERED/MOVED NOTES: Original site. Roof covered with 1-1/4" x 26" galvanized, corrugated steel						
roofing over cedar shingles. Most evidence of milk cow stanchions has been removed. Siding and or						
sheathing has been removed and 1-1/4" x 26" galvanized, corrugated steel roofing applied horizontally.						
Interior walls on first floor lined with 1x10 shiplap. 10' x 10' milk room was added and removed from the						
SW corner. 6x6 posts have all been removed, the mortise in the bottom of 6x6 beam shows where all six posts were located.						
INTERIOR NOTES: Two rows of 6x6 posts with 6x6's for beams support 2x8 joists for hayloft floor.						
6x6 posts were mortised into the 6x6 beams. Milk cow stanchions were along the 32' East wall and 22' of						
the West wall. 2x6 rafters, 16" O. C. with $\frac{1}{2}$ steel rods from the top of the wall in the hayloft out and down to the floor, 5' – 4" O. C.						
OTHER NOTES: 2x6 stud walls, 16" O. C. and 1-1/4" x 26" galvanized corrugated steel roofing applied						
horizontally and directly to the studs on all four walls. Any siding and or sheathing has been removed.						
Wooden cupola. Windows were 8"x x 10" four light. Interior walls on the first floor lined with 1x10 shiplap						
and painted white. Floor joists, beams and bottom of hayloft floor is painted white.						
	n good condition.	*RESTRICTED: Y	or N			
*UTM NORTHING:						











PHOTOGRAPHER: **DATE OF PHOTO:**

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION:

Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: September 3, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NE, 6x6 posts, 6x6 posts removed, 1x10 shiplap

CAMERA DIRECTION: lining on all walls.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking SW, note raised foundation

CAMERA DIRECTION: for milk room.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone September 3, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking up and West, old trolley that uses a 4x4 for a hay

CAMERA DIRECTION: track.



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: September 3, 2013


ROLL NUMBER: PHOTO NUMBER:

8

Hayloft, looking NE, 2x6 studs 16" O. C., 2x6 rafters and ½" steel rods bracing top of wall, 5' -

CAMERA DIRECTION: 4" O. C.





SPIRIT MOUND TOWNSHIP

- 1 McDonald, Ben 31284
- 3 46292 4 Wood, Robert 46296

© Farm & Home Publishers, Ltd.

37

CLAY CO., 9



History

This farm located in the NE ¼ of Section 33, Spirit Mound Township, Clay County was homesteaded by Ole Lewison.

The 1894 Clay County Atlas lists Ole Lewison Estate as the owner. Knudt Olson was the renter.

The 1901, 1912 and 1924 Clay County Atlas lists Hans Lewison as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists R. P. Munger as the owner.

