

SITE INFORMATION

*SURVEY DATE: _ Aug. 2, 2012				*ADDRESS: 29773 Greenfield Road							
*SURVEYOR: Jim Stone			*COUNTY	': Clay	Clay						
				*CITY	: Bere	sfor	t				
LOCATION DESCR				•			field	Roa	d, tu	rn let	it
(North), 19 miles to	298 th Street, a	bout 1	1/3 mile on N	orth, on the left ((West) si	de.					
LEGAL DESCRIPT	ION: SE 1/. 3	95 _	- 51 Glenwo	od Twp							
LEGAL DEGORII II	OL 74, 3	- 33 -	- 51 Olciiwo	od i wp.							
*QUARTER 1:	SE 1/4			OWNER NAME:	: Gary & Diane Lundberg						
*QUARTER 2:				NER ADDRESS:	29773 Greenfield Road						
*TOWNSHIP:	Greenwood			OWNER CITY:	Beresford						
*RANGE:	51			OWNER STATE:	South Dakota						
*SECTION:	3			OWNER ZIP:	57004						
ACRES:	256,62			QUAD NAME:							
OWNER CODE 1:	Р										
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGN	IIFICANCE										
				DECISTED N	AME.						
*DOE: *DOE DATE:											
DE AGON INELIGIBLE				KOPEKI	1 11/	-CIVI C.	· —				
KLASON INCLIGIC)LL										
					C	CATE	GOF	RY:			
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L								
DATE LISTED:			SIGNIFICANCE LEVEL 2: N S L								
REFERENCI	E NUMBER:										
HISTORIC DISTRIC	CT RATING: (C or	NC	CRIT	ERIA 1:	Α	В	С	D		
	PERIOD:			CRIT	ERIA 2:	Α	В	С	D		
					ERIA 3:	Α	В	С	D		
				CRIT	ERIA 4:	Α	В	С	D		
SIGNIFICANCE NO	TES:										
SIGNIFICANCE NO											

STRUCTURE DETAILS




SHPO ID:					
*PROPERTY NAME:					
OTHER NAME:					
CURRENT FUNCTION: Vacant			FOUND!	TION:	Poured concrete
					Asphalt shingles
CURRENT CURFUNCTION	04		DOOF MATE	DIAL -	over cedar
CURRENT SUBFUNCTION:	Storage		ROOF MATE		
HISTORIC FUNCTION:	Livestock barn		ROOF S		Gambrel
HISTORIC SUBFUNCTION:	Hay and grain s	storage	STRUCTURAL SY		
				TYLE:	Gambrel roof barn
OCCUPIED:	Yes			TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission		144	VI 1 6.	2x6, 1x6 #106 drop siding
ACCESSIBLE.	permission		VV	ALLS.	siding
				SA	L. P. and F. O.
STORIES:	2	5	SIGNIFICANT PERSON:		
*DATE OF CONSTRUCTION:	1920's	CU	LTURAL AFFILIATION:		Swedish
ALTERED/MOVED NOTES:	Original site.	Roof ha	s been shingles with as	ohalt si	ningles. ½"x6" cedar
lap siding has been added or					
re-shingled.	ver the original in	xo arop	Siding: Oupola remove	a Wilcii	the built was
To omingiou.					
	_				
INTERIOR NOTES: Has two	rows 2x6 (space	d with s	hort 2x6's or sides of st	alls) po	sts and (3) 2x8's for
beams to support hayloft floo	or. Floor joists ar	re 2x8's.	Has a staircase up to t	he hayl	oft. The 11'x14' milk
room still in place. Horse sta	lls and milk cow	stanchio	ons are still in place.		
OTHER NOTES: Windows w	vere 9"x12" four l	light. W	alls are 2x6 with 1x6 dro	p sidin	g and 1x2"x6" cedar
lap siding. Rafters are 2x6 w	/ith no bracing. 4	4x6 post	s support the hip. Two	2x6's fo	or a plate at the hip.
		-			
*PHYSICAL NOTES: Barn is	s in good conditi	on. The	roof is leaking. Needs	some r	epairs on the
doors.	<u> </u>		<u> </u>		- p
*UTM ZONE:			*RESTRICTED	: Y o	r N
*UTM EASTING:					
*UTM NORTHING:					

^{* =} REQUIRED FIELD



SKETCH MAP







PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 2, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: Aug. 2, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: Aug. 2, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: Aug. 2, 2012 PHOTO NUMBER:

CAMERA DIRECTION: Feed room in SW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, Milk cow stanchions on

CAMERA DIRECTION: West side



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking South, double horse stall and milk room in the SE

CAMERA DIRECTION: corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 2, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, milk cow stanchions on

CAMERA DIRECTION: East side



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 2, 2012

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking North, 4x6 posts to support the

CAMERA DIRECTION: hip






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone Aug. 2, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Hayloft, looking North, North gable end wall





© Farm & Home Publishers Ltd 23 CLAY CO. SD.



HISTORY

This farm located in the SE ¼ of Section 3, Glenwood Township, Clay County was homesteaded by Carl Johan Stahl.

The 1894 Clay County Atlas lists S. A., L. P. and F. O. Larson as the owners.

The 1901 Clay County Atlas lists L.P. and F.O. Larson as the owners.

The 1912 Clay County Atlas lists S. A., L. P. and F. O. Larson as the owners.

The 1924 Clay County Atlas lists. S. A. Larson as the owner.

The 1937, 1948 and 1956 Clay County Atlas lists Edna Larson as the owner. The 1937 Atlas lists A. Lundberg as the operator (renter).