


<b>""SITE INFORMATION</b>							
*SURVEY DATE: July 27, 2	2013 *ADDRESS:	45278 305 <sup>th</sup> Street					
*SURVEYOR: Jim Ston		Clay					
	*CITY:	Volin					
LOCATION DESCRIPTION: From Vermillion, intersection of South Dakota Highway 50 bi-pass and							
South Dakota Highway 19, North about 12 miles to 305th Street, turn left (West) 9-1/8 miles on the right							
(North) side.							
LEGAL DESCRIPTION: E½, SE 1/4, 7 – 94 – 53 Bethel Twp							
*QUARTER 1: SE 1/4	OWNER NAME:	OWNER NAME: Ronald Burnell & Jeanne M. Nelson					
*QUARTER 2:	OWNER ADDRESS:						
*TOWNSHIP: Bethel	OWNER CITY:						
*RANGE: 53	•	OWNER STATE: South Dakota					
*SECTION: 7	OWNER ZIP:						
ACRES: 79.16	QUAD NAME:						
OWNER CODE 1: P							
OWNER CODE 2:							
OWNER CODE 3:							
HISTORIC SIGNIFICANCE							
HISTORIC SIGNIFICANCE							
	REGISTER NA	REGISTER NAME:					
*DOE DATE:	MULTIPLE PR	MULTIPLE PROPERTY NAME:					
REASON INELIGIBLE:							
		CATEGORY:					
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L					
DATE LISTED:		FICANCE LEVEL 2: N S L					
REFERENCE NUMBER:							
HISTORIC DISTRICT RATING: C or		RIA 1: A B C D					
PERIOD:		RIA 2: A B C D					
		RIA 3: A B C D					
	CRITE	RIA 4: A B C D					
SIGNIFICANCE NOTES:							
SIGNIFICANCE NOTES:							

#### STRUCTURE DETAILS



SHPO ID:		<u></u>			
*PROPERTY NAME:					
OTHER NAME:					
CURRENT FUNCTION:	Machinery storage	FOUNDA	TION:	Original foundation was native rock	
JOHNE TONOTION	machinery cicrage			Steel roofing over	
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	cedar shingles	
HISTORIC FUNCTION:	HISTORIC FUNCTION: Livestock barn		ROOF SHAPE:		
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYS	STEM:	Balloon framing	
		S	TYLE:	Gable roof barn	
OCCUPIED:	Yes	•	TYPE:	Livestock barn	
ACCESSIBLE:	Yes with permission	WALLS:		2x6 studs, 1x10 diagonal sheathing, ½"x6" cedar lap siding& steel roofing	
STORIES:	2	SIGNIFICANT PERSON:	F	Fred Jacobson	
*DATE OF CONSTRUCTION:	Early 1900 C	ULTURAL AFFILIATION:		?	
ALTERED/MOVED NOTES: Original site. Any evidence of horse stalls or milk cow stanchions has been					
removed. Hayloft floor removed. Some of the 2x8 the floor joists raised to about 16' and are 8' O. C.					
2x6 bracing from the hip down to the raised floor joists. Double 1x8's from center of upper rafters down to					
raised floor joists, 8' O. C. 17' x 14' sliding door added on South wall. 24' x 34' open front pole barn					
added on the West side, with walls 13' high. Roof covered with steel roofing over cedar shingles and walls are covered with steel roofing.					
INTERIOR NOTES: No evidence of posts or beams to support hayloft floor. The hayloft floor joists were					
2x8's.					
OTHER NOTES: 2x6 stud walls, 1x10 diagonal sheathing and ½"x 6" cedar lap siding on all four walls.					
Steel roofing applied on all four walls. Rafters are 2x6's. Windows are 8" x10"four light on first floor and					
two 8"x10" four light over 8"x10" four light, double hung, in the East gable of hayloft. All of the 2x6 studs,					
2x6 rafters and 2x8 floor joists been repaired in places with p	s are rough sawn cotto				
*PHYSICAL NOTES: Barn is	in good condition.				
*UTM ZONE:  *UTM EASTING:  *UTM NORTHING:			Υo	r N	









PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER:

PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 26, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: \_\_

Jim Stone July 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, 2x6 studs, diagonal sheathing on West of original barn.

**CAMERA DIRECTION:** 



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking up and NE, raised 2x8 floor joists, 2x6 and double 1x8's bracing to create a

CAMERA DIRECTION: truss.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking up and SE, very well engineered truss using

CAMERA DIRECTION: existing materials.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking East, view of lowered hayloft door on East gable end, Hay track actually slopes about 2 feet to the West

CAMERA DIRECTION: gable end.





PHOTOGRAPHER: DATE OF PHOTO:


Jim Stone July 26, 2013

**ROLL NUMBER: PHOTO NUMBER:** 

West addition, looking NW, typical pole barn

CAMERA DIRECTION: construction.







### **HISTORY**

This farm located in the SE ¼ of Section 7, Bethel Township, Clay County was homesteaded by Fredrick Kincel.

The 1894 Clay County Atlas lists Celia Ward as the owner.

The 1901 Clay County Atlas lists M. J. Chaney as the owner.

The 1912, 1924 and 1937 Clay County Atlas lists Fred Jacobson as the owner.

The 1948 and 1956 Clay County Atlas lists Katie Jacobson as the owner.