

SITE INFORMATION

*SURVEY DATE: <u>Aug. 20, 2012</u> *SURVEYOR: Jim Stone

*ADDRESS:	45589 Cottonwood Street
*COUNTY:	Clay
*CITY:	Meckling

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 West about 7-1/2 miles, just past Meckling to Cottonwood Street, turn left (South) and then right (West) about ½ mile on the left (South) side.

LEGAL DESCRIPTION: SE 1/4, 27 – 93 – 53 Meckling Twp.

*QUARTER 1:	SE 1/4		0	WNER NAME:	Warre	n L.	& He	len	J. Wa	alrav	en	
*QUARTER 2:			OWN	ER ADDRESS:	45589	Cott	onw	ood	Stre	et		
*TOWNSHIP:	Meckling		_	OWNER CITY:	Meckli	ing						
*RANGE:	53		0\	WNER STATE:	South	Dak	ota					
*SECTION:	27		_	OWNER ZIP:	57069							
ACRES:	162.29		_	QUAD NAME:								
OWNER CODE 1:	Р											
OWNER CODE 2:												
OWNER CODE 3:												
HISTORIC SIGN	IFICANCE											
*D0	OE:			REGISTER NA	ME:							
REASON INELIGIB	LE:											
					С	ATE	GOF	łY:				
NOMINATIO	N STATUS:			SIGNI	FICANC	ELE	EVEL	. 1:	Ν	S	L	
DAT	TE LISTED:			SIGNI	FICANC	ELE	EVEL	. 2:	Ν	S	L	
REFERENCE												
HISTORIC DISTRIC	T RATING:	C or	NC	CRITE	ERIA 1:	Α	в	С	D			
	PERIOD:			CRITE	ERIA 2:	Α	В	С	D			
				CRITE	ERIA 3:	Α	В	С	D			
				CRITE	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NO	TES:											
STRUCTURE DE	TAILS											



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Two horses	FOUNDATION:	Poured concrete
	Hay and machinery		Steel roofing over
CURRENT SUBFUNCTION:	storage	ROOF MATERIAL:	cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
			Western feeder
		STYLE:	barn
OCCUPIED:	Yes	TYPE:	Livestock barn
	Yes with		2x4 and 2x6, 1x6
ACCESSIBLE:	permission	WALLS:	#106 drop siding
STORIES:	1	SIGNIFICANT PERSON: H	erman Walraven
*DATE OF CONSTRUCTION:	1940's	CULTURAL AFFILIATION:	Dutch

ALTERED/MOVED NOTES: Original site. Original barn was built with 4x6 posts 6' O.C. on the East and West walls. West lean-to seems to have been built at the same time. East lean-to was built soon after that time. West 20'x28' addition was built later. All stalls and milk cow stanchions have been removed. Steel roofing was installed over cedar shingles. Two over head doors installed in the South wall.

INTERIOR NOTES: <u>Has two rows 4x6 posts 6' O.C. on the East and West walls. Walls are open except</u> the bottom 8' of the East wall. Horse stalls were in the West lean-to and the milk cow stanchions were in the East lean-to. Center 20'x40' was hay storage from the ground level to the peak. Hayloft over the East lean-to.

OTHER NOTES: <u>Windows were 4"x24" four light, some have been replaced with 9'x12" vinyl four light</u> windows. Walls are 2x4 studs with a 6x6 post 10' O.C. in the East and West lean-to's. The North and

South walls in the center area are 2x6 studs. 20'x28' addition is all 2x6 studs. Siding was 1x6 #106 drop siding, however most of it has been replaced with 1x6 car siding. Center area has 4x6 for sills.


*PHYSICAL NOTES: Barn is in good condition.

*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				


* = REQUIRED FIELD



SKETCH MAP











 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 20, 2012
 PHOTO NUMBER:
 1

 CAMERA DIRECTION:
 Looking NE, SW corner



PHOTOGRAPHER: _____ DATE OF PHOTO:

Aug. 20, 2012

 PHOTO NUMBER:
 2

 CAMERA DIRECTION:
 Looking NW, SE corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 20, 2012
 PHOTO NUMBER:
 3

 CAMERA DIRECTION:
 Looking SW, NE corner



 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 Aug. 20, 2012
 PHOTO NUMBER:
 4

 CAMERA DIRECTION:
 Looking SE, NW corner





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: Aug. 20, 2012 ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 5 First floor, looking North, 4x6 posts 6'O.C. and bracing, West wall



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	Aug. 20, 2012	PHOTO NUMBER:	6

First floor, looking North, 4x6 post, 6' O.C. and CAMERA DIRECTION: bracing, East wall





PHOTOGRAPHER: DATE OF PHOTO: Aug. 20, 2012

ROLL NUMBER: PHOTO NUMBER:

East lean-to, looking North, solid wall on West and hayloft above, note fold down door

7

CAMERA DIRECTION: from hayloft




Jim Stone PHOTOGRAPHER: DATE OF PHOTO: Aug. 20, 2012

ROLL NUMBER: PHOTO NUMBER:

8 Looking NW through 14' lean-to and into 20'28' CAMERA DIRECTION: addition.

* = REQUIRED FIELD







HISTORY

This farm located in the SE ¼ of Section 27, Meckling Township, Clay County was homesteaded by Jerome Tucker.

The 1894 and 1901 Clay County Atlas lists Casper Miller as the owner.

The 1912 Clay County Atlas lists August Miller as the owner.

The 1924 Clay County Atlas lists Ellen Miller as the owner.

The 1937 Clay County Atlas lists C. Walraven and A. Paulson as the owners and H. Walraven as the operator (renter).

The 1948 and 1956 Clay County Atlas lists Herman Walraven as the owner.